

An bit error in the cable could mean more than 2 errors after 10b/8b, One bit error it is not enough!!!!

