
Case 3

Data Master -> Node

Node -> Data Master



- link down is detected in HW
- Alternate port is changed into Designated (in other words, port is not blocking any more, forwarding activated

