

Левая доковина (начало)					
	Цепи переменного тока В1			X	
		1	X:1	SG1:2	#
		2	X:2	SG1:4	#
		3	X:3	SG1:6	#
		4	X:4	SG1:8	#
		5	X:5	SG1:10	#
		6	X:6	SG1:12	#
		7			
		8			
	Цепи переменного тока В2			X	
		9	X:9	SG2:2	#
		10	X:10	SG2:4	#
		11	X:11	SG2:6	#
		12	X:12	SG2:8	#
		13	X:13	SG2:10	#
		14	X:14	SG2:12	#
		15			
		16			
	Цепи переменного тока 3Ia ЛЭП			X	
		17	X:17	SG3:2	#
		18	X:18	SG3:4	#
	Цепи переменного напряжения СШ			X	
		19	X:19	SG4:2	+
		20	X:20	SG4:4	+
		21	X:21	SG4:6	+
		22	X:22	SG4:8	+
		23	X:23	SG5:2	+
		24	X:24	SG5:4	+
		25	X:25	SG5:6	+
		26	X:26	SG5:8	+
	Цепи переменного напряжения ОВ			X	
		27	X:27	SG6:2	+
		28	X:28	SG6:4	+
		29	X:29	SG6:6	+
		30	X:30	SG6:8	+
		31	X:31	SG7:2	+
		32	X:32	SG7:4	+
		33	X:33	SG7:6	+
		34	X:34	SG7:8	+
	Цепи отбора напряжения ЛЭП			X	
		35	X:35	SG8:2	+
		36	X:36	SG8:4	+
		37	X:37	SG8:6	+

Левая доковина (продолжение на листе 2)

Условные обозначения

