

|                         |                                                                                     |    |      |        |   |
|-------------------------|-------------------------------------------------------------------------------------|----|------|--------|---|
| Левая доковина (начало) |                                                                                     |    |      |        |   |
|                         | Цепи переменного тока В1                                                            |    |      | X      |   |
|                         |    | 1  | X:1  | SG1:2  | # |
|                         |    | 2  | X:2  | SG1:4  | # |
|                         |    | 3  | X:3  | SG1:6  | # |
|                         |    | 4  | X:4  | SG1:8  | # |
|                         |    | 5  | X:5  | SG1:10 | # |
|                         |    | 6  | X:6  | SG1:12 | # |
|                         |    | 7  |      |        |   |
|                         |    | 8  |      |        |   |
|                         | Цепи переменного тока В2                                                            |    |      | X      |   |
|                         |    | 9  | X:9  | SG2:2  | # |
|                         |    | 10 | X:10 | SG2:4  | # |
|                         |    | 11 | X:11 | SG2:6  | # |
|                         |    | 12 | X:12 | SG2:8  | # |
|                         |    | 13 | X:13 | SG2:10 | # |
|                         |    | 14 | X:14 | SG2:12 | # |
|                         |    | 15 |      |        |   |
|                         |    | 16 |      |        |   |
|                         | Цепи переменного тока 3Ia<br>ЛЭП                                                    |    |      | X      |   |
|                         |   | 17 | X:17 | SG3:2  | # |
|                         |   | 18 | X:18 | SG3:4  | # |
|                         | Цепи переменного напряжения<br>СШ                                                   |    |      | X      |   |
|                         |  | 19 | X:19 | SG4:2  | + |
|                         |  | 20 | X:20 | SG4:4  | + |
|                         |  | 21 | X:21 | SG4:6  | + |
|                         |  | 22 | X:22 | SG4:8  | + |
|                         |  | 23 | X:23 | SG5:2  | + |
|                         |  | 24 | X:24 | SG5:4  | + |
|                         |  | 25 | X:25 | SG5:6  | + |
|                         |  | 26 | X:26 | SG5:8  | + |
|                         | Цепи переменного напряжения<br>ОВ                                                   |    |      | X      |   |
|                         |  | 27 | X:27 | SG6:2  | + |
|                         |  | 28 | X:28 | SG6:4  | + |
|                         |  | 29 | X:29 | SG6:6  | + |
|                         |  | 30 | X:30 | SG6:8  | + |
|                         |  | 31 | X:31 | SG7:2  | + |
|                         |  | 32 | X:32 | SG7:4  | + |
|                         |  | 33 | X:33 | SG7:6  | + |
|                         |  | 34 | X:34 | SG7:8  | + |
|                         | Цепи отбора напряжения ЛЭП                                                          |    |      | X      |   |
|                         |  | 35 | X:35 | SG8:2  | + |
|                         |  | 36 | X:36 | SG8:4  | + |
|                         |  | 37 | X:37 | SG8:6  | + |

Левая доковина (продолжение на листе 2)

Условные обозначения

