

Левая баковина (продолжение на листе 1)

		45		
		46		
		47	X:47	A1-M5.XB-3
		48	X:48	UZ1-4
	Цепи оперативного тока ГЗ			X
		49	X:49	KS1-X1-1
		50	X:50	A1-M5.XB-11
		51	X:51	A1-M5.XB-5
		52	X:52	KS1-X1-12
		53		
		54		
		55		
		56		
		57	X:57	A1-M5.XB-12
		58	X:58	R1-2
	Цепи оперативного тока ТЗ			X
		59	X:59	KS2-X1-1
		60	X:60	A1-M6.XB-8
		61		
		62		
		63	X:63	A1-M5.XB-15
		64	X:64	KS2-X1-12
		65	X:65	A1-M5.XB-19
		66	X:66	KS3-X1-12
		67	X:67	A1-M5.XB-21
		68	X:68	A1-M5.XB-23
		69	X:69	A1-M5.XB-25
		70	X:70	A1-M5.XB-27
		71	X:71	A1-M5.XB-29
		72	X:72	A1-M5.XB-31
		73	X:73	A1-M6.XB-1
		74		
		75		
		76		
		77		
		78		
		79		
		80		
		81		
		82		
		83	X:83	R2-2
		84	X:84	A1-M6.XB-8
	Выходные цепи			X
		85	X:85	A1-M2.XB-2
		86	X:86	A1-M2.XB-4
		87	X:87	A1-M2.XB-6
		88	X:88	A1-M2.XB-8
		89	X:89	A1-M2.XB-10
		90	X:90	A1-M2.XB-12
		91	X:91	A1-M2.XB-14
		92	X:92	A1-M2.XB-16
		93	X:93	A1-M2.XB-18
		94	X:94	A1-M2.XB-20
		95	X:95	A1-M2.XB-22
		96	X:96	A1-M2.XB-24
		97	X:97	A1-M2.XB-26
		98	X:98	A1-M2.XB-28
		99	X:99	A1-M2.XB-30
		100	X:100	A1-M2.XB-32
		101	X:101	A1-M3.XB-2
		102	X:102	A1-M3.XB-4
		103	X:103	A1-M3.XB-6
		104	X:104	A1-M3.XB-8
		105	X:105	A1-M3.XB-10
		106	X:106	A1-M3.XB-12

Левая баковина (продолжение на листе 3)