

Левая баковина (продолжение на листе 1)

	Цепи переменного напряжения ТН ошиновки КОР			X
		41	X:41	SG6-2
		42	X:42	SG6-4
		43	X:43	SG6-6
		44	X:44	SG6-8
		45	X:45	SG6-10
		46	X:46	SG6-12
	Цепи оперативного тока			X
		47	X:47	SQ1-33
		48	X:48	UZ1-1
		49		
		50		
		51		
		52	X:52	A1-M4.XB-1
		53		
		54	X:54	A1-M4.XB-3
		55		
		56		
		57		
		58		
		59		
		60		
		61		
		62		
		63		
		64		
		65		
		66		
		67	X:67	A1-M4.XB-4
		68	X:68	UZ1-4
	Цепи ЗДЗ НН			X
		69	X:69	A1-M4.XB-7
		70		
		71	X:71	A1-M4.XB-5
		72	X:72	A1-M4.XB-8
		73		
	Цепи ТМПо			X
		74	X:74	A1-M4.XB-11
		75		
		76	X:76	A1-M4.XB-9
		77	X:77	A1-M4.XB-12
		78		
	Цепи ТМПр			X
		79	X:79	A1-M4.XB-15
		80		
		81	X:81	A1-M4.XB-13
		82	X:82	A1-M4.XB-16
		83		
	Выходные цепи			X
		84	X:84	A1-M2.XB-2
		85	X:85	A1-M2.XB-4
		86	X:86	A1-M2.XB-6
		87	X:87	A1-M2.XB-8
		88	X:88	A1-M2.XB-10
		89	X:89	A1-M2.XB-12
		90	X:90	A1-M2.XB-14
		91	X:91	A1-M2.XB-16
		92	X:92	A1-M2.XB-18
		93	X:93	A1-M2.XB-20
		94	X:94	A1-M2.XB-22
		95	X:95	A1-M2.XB-24
		96	X:96	A1-M2.XB-26
		97	X:97	A1-M2.XB-28
		98	X:98	A1-M2.XB-30
		99	X:99	A1-M2.XB-32

Левая баковина (продолжение на листе 3)