

Левая баковина (продолжение на листе 1)

	Цепи переменного тока В6			X	
		41	X:41	SG6:2	#
		42	X:42	SG6:4	#
		43	X:43	SG6:6	#
		44	X:44	SG6:8	#
		45	X:45	SG6:10	#
		46	X:46	SG6:12	#
		 47			
		 48			
	Цепи переменного тока В7			X	
		49	X:49	SG7:2	#
		50	X:50	SG7:4	#
		51	X:51	SG7:6	#
		52	X:52	SG7:8	#
		53	X:53	SG7:10	#
		54	X:54	SG7:12	#
		 55			
		 56			
	Цепи переменного тока В8			X	
		57	X:57	SG8:2	#
		58	X:58	SG8:4	#
		59	X:59	SG8:6	#
		60	X:60	SG8:8	#
		61	X:61	SG8:10	#
		62	X:62	SG8:12	#
		 63			
		 64			
	Цепи переменного тока В9			X	
		65	X:65	SG9:2	#
		66	X:66	SG9:4	#
		67	X:67	SG9:6	#
		68	X:68	SG9:8	#
		69	X:69	SG9:10	#
		70	X:70	SG9:12	#
		 71			
		 72			
	Цепи переменного тока СВ стороны 1 секции			X	
		73	X:73	SG10:2	#
		74	X:74	SG10:4	#
		75	X:75	SG10:6	#
		76	X:76	SG10:8	#
		77	X:77	SG10:10	#
		78	X:78	SG10:12	#
		 79			
		 80			

Левая баковина (продолжение)

Левая баковина (окончание)

	Цепи переменного тока СВ стороны 2 секции			X	
		81	X:81	SG11:2	#
		82	X:82	SG11:4	#
		83	X:83	SG11:6	#
		84	X:84	SG11:8	#
		85	X:85	SG11:10	#
		86	X:86	SG11:12	#
		○ 87			
		○ 88			
	Цепи переменного напряжения 1 секции			X	
		89	X:89	SG12:2	+
		90	X:90	SG12:4	+
		91	X:91	SG12:6	+
		92			
	Цепи переменного напряжения 2 секции			X	
		93	X:90	SG12:2	+
		94	X:94	SG12:4	+
		95	X:95	SG12:6	+
		96			
	Цепи оперативного тока			X	
		○ 97	X:97	UZ1:1	+
		○ 98	X:98	SG1:14	—
		○ 99			
		○ 100			
		○ 101			
		○ 102			
		○ 103			
		○ 104			
X	Цепи сигнализации				
A1-M1.XP:2	X:105	105 ○			
		106 ○			
HL1:2	X:107	107 ○			
		108 ○			
X	Освещение				
SQ1:11	X:109	109 ○			
SQ3:11	X:110	110 ○			
SQ1:21	X:111	111 ○			
SQ3:21	X:112	112 ○			

WE2

WE4

КЧ

КЧ

С

С