

Левая боковина 2 секции (продолжение на листе 2)				
	Цепи переменного тока В13		X	
		97	X-97	SG13-2
		98	X-98	SG13-4
		99	X-99	SG13-6
		100	X-100	SG13-8
		101	X-101	SG13-10
		102	X-102	SG13-12
		103		
		104		
	Цепи переменного тока В14		X	
		105	X-105	SG14-2
		106	X-106	SG14-4
		107	X-107	SG14-6
		108	X-108	SG14-8
		109	X-109	SG14-10
		110	X-110	SG14-12
		111		
		112		
	Цепи переменного тока В15		X	
		113	X-113	SG15-2
		114	X-114	SG15-4
		115	X-115	SG15-6
		116	X-116	SG15-8
		117	X-117	SG15-10
		118	X-118	SG15-12
		119		
		120		
	Цепи переменного тока В16/СВ1		X	
		121	X-121	SG16-2
		122	X-122	SG16-4
		123	X-123	SG16-6
		124	X-124	SG16-8
		125	X-125	SG16-10
		126	X-126	SG16-12
		127		
		128		
	Цепи переменного тока СВ2		X	
		129	X-129	SG17-2
		130	X-130	SG17-4
		131	X-131	SG17-6
		132	X-132	SG17-8
		133	X-133	SG17-10
		134	X-134	SG17-12
		135		
		136		
	Цепи переменного тока ОВ		X	
		137	X-137	SG18-2
		138	X-138	SG18-4
		139	X-139	SG18-6
		140	X-140	SG18-8
		141	X-141	SG18-10
		142	X-142	SG18-12
		143		
		144		
	Цепи переменного тока ШСВ/СВ 1С		X	
		145	X-145	SG19-2
		146	X-146	SG19-4
		147	X-147	SG19-6
		148	X-148	SG19-8
		149	X-149	SG19-10
		150	X-150	SG19-12
		151		
		152		