

Левая боковина (начало)						
	Цепи переменного тока ЛЭП			X		
		1	X:1	SG1:2	#	
		2	X:2	SG1:4	#	
		3	X:3	SG1:6	#	
		4	X:4	SG1:8	#	
		5	X:5	SG1:10	#	
		6	X:6	SG1:12	#	
		7				
		8				
	Цепи переменного напряжения СШ			X		
		9	X:9	SG2:2	+	
		10	X:10	SG2:4	+	
		11	X:11	SG2:6	+	
		12	X:12	SG2:8	+	
		13	X:13	SG3:2	+	
		14	X:14	SG3:4	+	
		15	X:15	SG3:6	+	
		16	X:16	SG3:8	+	
	Цепи переменного напряжения ОСШ			X		
		17	X:13	SG4:2	+	
		18			+	
		19	X:15	SG4:4	+	
	Цепи оперативного тока			X		
		20	X:20	UZ1:1	+	
		21	X:21	SG1:14	—	
		22				
		23	X:23	UZ1:4	+	
	Цепи сигнализации			X		
		24	X:24	A1-M1.XP:2	—	
		25				
		26	X:26	HL1:2	—	
		27				
	Цепи освещения			X		
		28	X:28	SQ1:11	кч	
		29			WE2	
		30	X:30	SQ1:21		с
		31				

Левая боковина (продолжение на листе 2)

Левая боковина (продолжение на листе 2)

