

The diagram illustrates the power supply system for the 1000V switchgear, showing three stages of voltage transformation (SG12, SG13, SG14) and the resulting AC circuits (A2, B1, B2, B3).

Stage SG12: Three-phase input (X:67, X:68, X:69) is transformed into three-phase output (X:70, X:71, X:72). The output is connected to the A2 circuit (M5.XA:1, M5.XA:2, M5.XA:3, M5.XA:4, M5.XA:5, M5.XA:6) and the B1 circuit (M5.XA:7, M5.XA:8, M5.XA:9, M5.XA:10, M5.XA:11, M5.XA:12).

Stage SG13: Three-phase input (X:75, X:76, X:77) is transformed into three-phase output (X:78, X:79, X:80). The output is connected to the A2 circuit (M5.XA:7, M5.XA:8, M5.XA:9, M5.XA:10, M5.XA:11, M5.XA:12) and the B2 circuit (M5.XA:13, M5.XA:14, M5.XA:15, M5.XA:16, M5.XA:17, M5.XA:18).

Stage SG14: Three-phase input (X:83, X:84, X:85) is transformed into three-phase output (X:86, X:87, X:88). The output is connected to the A2 circuit (M5.XA:13, M5.XA:14, M5.XA:15, M5.XA:16, M5.XA:17, M5.XA:18) and the B3 circuit (M5.XA:19, M5.XA:20, M5.XA:21, M5.XA:22, M5.XA:23, M5.XA:24).

The diagram also shows the connection of the three-phase input (X:67, X:68, X:69) to the A2 circuit (M5.XA:1, M5.XA:2, M5.XA:3, M5.XA:4, M5.XA:5, M5.XA:6) and the B1 circuit (M5.XA:7, M5.XA:8, M5.XA:9, M5.XA:10, M5.XA:11, M5.XA:12).

[illegible]

A2		
SFP port	SFP Модуль 100BASE-FX	M10.X1-TX M10.X1-RX
SFP port	SFP Модуль 100BASE-FX	M10.X2-TX M10.X2-RX
SFP port	SFP Модуль 100BASE-FX	M10.X3-TX M10.X3-RX
SFP port	SFP Модуль 100BASE-FX	M10.X4-TX M10.X4-RX

= / ~ 220 B	+ / L
	- / N