

Левая боковина 2 секции				
	Цепи переменного тока В1			Х
		1	X:1	SG1:2
		2	X:2	SG1:4
		3	X:3	SG1:6
		4	X:4	SG1:8
		5	X:5	SG1:10
		6	X:6	SG1:12
		7		
		8		
	Цепи переменного тока В2			Х
		9	X:9	SG2:2
		10	X:10	SG2:4
		11	X:11	SG2:6
		12	X:12	SG2:8
		13	X:13	SG2:10
		14	X:14	SG2:12
		15		
		16		
	Цепи переменного тока В3			Х
		17	X:17	SG3:2
		18	X:18	SG3:4
		19	X:19	SG3:6
		20	X:20	SG3:8
		21	X:21	SG3:10
		22	X:22	SG3:12
		23		
		24		
	Цепи переменного тока В4			Х
		25	X:25	SG4:2
		26	X:26	SG4:4
		27	X:27	SG4:6
		28	X:28	SG4:8
		29	X:29	SG4:10
		30	X:30	SG4:12
		31		
		32		
	Цепи переменного тока В5			Х
		33	X:33	SG5:2
		34	X:34	SG5:4
		35	X:35	SG5:6
		36	X:36	SG5:8
		37	X:37	SG5:10
		38	X:38	SG5:12
		39		
		40		

Левая боковина 2 секции (продолжение на листе 2)

Правая боковина 2 секции				
Х	Цепи оперативного тока			
UZ1:1	X:89	89		
SQ1:33	X:90	90		
SG1:14	X:91	91		
		92		
		93		
		94		
		95		
		96		
		97		
		98		
		99		
		100		
		101		
		102		
		103		
		104		
		105		
		106		
		107		
		108		
		109		
		110		
		111		
		112		
		113		
		114		
		115		
		116		
UZ1:4	X:117	117		
A1-M4.XB:2	X:118	118		
A1-M2.XB:2	X:119	119		
A1-M2.XB:4	X:120	120		
A1-M2.XB:6	X:121	121		
A1-M2.XB:8	X:122	122		
A1-M2.XB:10	X:123	123		
A1-M2.XB:12	X:124	124		
A1-M2.XB:14	X:125	125		
A1-M2.XB:16	X:126	126		
A1-M2.XB:18	X:127	127		
A1-M2.XB:20	X:128	128		
A1-M2.XB:22	X:129	129		
A1-M2.XB:24	X:130	130		
A1-M2.XB:26	X:131	131		
A1-M2.XB:28	X:132	132		
A1-M2.XB:30	X:133	133		
A1-M2.XB:32	X:134	134		
A1-M4.XB:2	X:135	135		
A1-M4.XB:4	X:136	136		
A1-M4.XB:6	X:137	137		
A1-M4.XB:8	X:138	138		
		139		
		140		
		141		

Правая боковина 2 секции (продолжение на листе 2)

Условные обозначения

