

Левая боковина 2 секции (продолжение)

	Цепи переменного тока В6			X	
		41	X:41	SG6:2	
		42	X:42	SG6:4	
		43	X:43	SG6:6	
		44	X:44	SG6:8	
		45	X:45	SG6:10	
		46	X:46	SG6:12	
		⌀ 47			
		⊙ 48			
	Цепи переменного тока В7			X	
		49	X:49	SG7:2	
		50	X:50	SG7:4	
		51	X:51	SG7:6	
		52	X:52	SG7:8	
		53	X:53	SG7:10	
		54	X:54	SG7:12	
		⌀ 55			
		⊙ 56			
	Цепи переменного тока В8			X	
		57	X:57	SG8:2	
		58	X:58	SG8:4	
		59	X:59	SG8:6	
		60	X:60	SG8:8	
		61	X:61	SG8:10	
		62	X:62	SG8:12	
		⌀ 63			
		⊙ 64			
	Цепи переменного тока В9			X	
		65	X:65	SG9:2	
		66	X:66	SG9:4	
		67	X:67	SG9:6	
		68	X:68	SG9:8	
		69	X:69	SG9:10	
		70	X:70	SG9:12	
		⌀ 71			
		⊙ 72			
	Цепи переменного тока В10 (СВ)			X	
		73	X:73	SG10:2	
		74	X:74	SG10:4	
		75	X:75	SG10:6	
		76	X:76	SG10:8	
		77	X:77	SG10:10	
		78	X:78	SG10:12	
		⌀ 79			
		⊙ 80			
	Цепи переменного напряжения 1 секции			X	
		81	X:81	SG11:2	
		82	X:82	SG11:4	
		83	X:83	SG11:6	
		84	X:84	SG11:8	
	Цепи переменного напряжения 2 секции			X	
		85	X:85	SG12:2	
		86	X:86	SG12:4	
		87	X:87	SG12:6	
		88	X:88	SG12:8	

Правая боковина 2 секции (продолжение на листе 2)

Х	Выходные цепи			
		135		
		136		
		137		
		138		
		139		
		140		
		141		
		142		
SA1:4	X:143	143		
SA1:6	X:144	144		
SA2:4	X:145	145		
SA2:6	X:146	146		
SA3:4	X:147	147		
SA3:6	X:148	148		
SA4:4	X:149	149		
SA4:6	X:150	150		
SA5:4	X:151	151		
SA5:6	X:152	152		
SA6:4	X:153	153		
SA6:6	X:154	154		
SA7:4	X:155	155		
SA7:6	X:156	156		
SA8:4	X:157	157		
SA8:6	X:158	158		
SA9:4	X:159	159		
SA9:6	X:160	160		
SA10:4	X:161	161		
SA10:6	X:162	162		
		163		
		164		
		165		
		166		
		167		
		168		
Х	Выходные цепи			
A1-M1.XP:2	X:169	169 		
		170 		
HL1:2	X:171	171 		
		172 		
Х	Освещение			
SQ1:11	X:173	173 		
SQ3:11	X:174	174 		
SQ1:21	X:175	175 		
SQ3:21	X:176	176 		

WE2

WE4

кч

кч

с

с