

Левая баковина 2 секции (начало)

	Цепи переменного тока В1		Х	
		1 X-1	SG12	#
		2 X-2	SG14	#
		3 X-3	SG16	#
		4 X-4	SG18	#
		5 X-5	SG110	#
		6 X-6	SG112	#
		7		
		8		
	Цепи переменного тока В2		Х	
		9 X-7	SG2-2	#
		10 X-8	SG2-4	#
		11 X-9	SG2-6	#
		12 X-10	SG2-8	#
		13 X-11	SG2-10	#
		14 X-12	SG2-12	#
		15		
		16		
	Цепи переменного тока В3		Х	
		17 X-17	SG3-2	#
		18 X-18	SG3-4	#
		19 X-19	SG3-6	#
		20 X-20	SG3-8	#
		21 X-21	SG3-10	#
		22 X-22	SG3-12	#
		23		
		24		
	Цепи переменного тока В4		Х	
		25 X-25	SG4-2	#
		26 X-26	SG4-4	#
		27 X-27	SG4-6	#
		28 X-28	SG4-8	#
		29 X-29	SG4-10	#
		30 X-30	SG4-12	#
		31		
		32		
	Цепи переменного тока В5		Х	
		33 X-33	SG5-2	#
		34 X-34	SG5-4	#
		35 X-35	SG5-6	#
		36 X-36	SG5-8	#
		37 X-37	SG5-10	#
		38 X-38	SG5-12	#
		39		
		40		

Левая баковина 2 секции (продолжение на листе 2)

Правая баковина 2 секции (начало)

Х	Цепи оперативного тока		
UZ11	X-161	161	
SG121	X-162	162	
		163	
		164	
		165	
		166	
		167	
		168	
		169	
		170	
		171	
		172	
		173	
		174	
		175	
		176	
		177	
		178	
		179	
		180	
A1-M7.XB-1	X-181	181	
		182	
		183	
		184	
		185	
		186	
		187	
		188	
		189	
A1-M7.XB-2	X-190	190	
		191	
		192	
		193	
		194	
		195	
		196	
		197	
		198	
A1-M7.XB-3	X-199	199	
A1-M7.XB-4	X-200	200	
A1-M7.XB-5	X-201	201	
A1-M7.XB-6	X-202	202	
A1-M7.XB-7	X-203	203	
A1-M7.XB-9	X-204	204	
A1-M7.XB-10	X-205	205	
A1-M7.XB-11	X-206	206	
A1-M7.XB-12	X-207	207	
A1-M7.XB-13	X-208	208	
A1-M7.XB-14	X-209	209	
A1-M7.XB-15	X-210	210	

Правая баковина 2 секции (продолжение на листе 2)

Условные обозначения

