

Левая доковина 2 секции (продолжение на листе 3)

	Цепи переменного напряжения 2 секции			X	
		153	X:153	SG20.2	+
		154	X:154	SG20.4	+
		155	X:155	SG20.6	+
		156	X:156	SG20.8	+
	Цепи переменного напряжения 2 секции			X	
		157	X:157	SG21.2	+
		158	X:158	SG21.4	+
		159	X:159	SG21.6	+
		160	X:160	SG21.8	+

Правая доковина 2 секции (продолжение на листе 3)

SA11.4	X:348	348		
SA11.6	X:349	349		
SA11.8	X:350	350		
SA11.10	X:351	351		
SA12.4	X:352	352		
SA12.6	X:353	353		
SA12.8	X:354	354		
SA12.10	X:355	355		
SA13.4	X:356	356		
SA13.6	X:357	357		
SA13.8	X:358	358		
SA13.10	X:359	359		
SA14.4	X:360	360		
SA14.6	X:361	361		
SA14.8	X:362	362		
SA14.10	X:363	363		
SA15.4	X:364	364		
SA15.6	X:365	365		
SA15.8	X:366	366		
SA15.10	X:367	367		
SA16.4	X:368	368		
SA16.6	X:369	369		
SA16.8	X:370	370		
SA16.10	X:371	371		
SA17.4	X:372	372		
SA17.6	X:373	373		
SA17.8	X:374	374		
SA17.10	X:375	375		
SA18.4	X:376	376		
SA18.6	X:377	377		
SA18.8	X:378	378		
SA18.10	X:379	379		
		380		
		381		
		382		