

2 секция. Левая баковина (продолжение на листе 3)					
	Цепи переменного тока ШСВ стороны 2 секции			X	
	┌	153	X:153	SG20:2	#
	└	154	X:154	SG20:4	#
	┌	155	X:155	SG20:6	#
	└	156	X:156	SG20:8	#
	┌	157	X:157	SG20:10	#
	└	158	X:158	SG20:12	#
		○ 159			
		○ 160			
	Цепи переменного напряжения 1 секции			X	
		161	X:161	SG21:2	+
		162	X:162	SG21:4	+
		163	X:163	SG21:6	+
		164	X:164	SG21:8	+
	Цепи переменного напряжения 2 секции			X	
		165	X:165	SG22:2	+
		166	X:166	SG22:4	+
		167	X:167	SG22:6	+
		168	X:168	SG22:8	+

	SA10:10	X:427	427		
	SA11:4	X:428	428		
	SA11:6	X:429	429		
	SA11:8	X:430	430		
	SA11:10	X:431	431		
	SA12:4	X:432	432		
	SA12:6	X:433	433		
	SA12:8	X:434	434		
	SA12:10	X:435	435		
	SA13:4	X:436	436		
	SA13:6	X:437	437		
	SA13:8	X:438	438		
	SA13:10	X:439	439		
	SA14:4	X:440	440		
	SA14:6	X:441	441		
	SA14:8	X:442	442		
	SA14:10	X:443	443		
	SA15:4	X:444	444		
	SA15:6	X:445	445		
	SA15:8	X:446	446		
	SA15:10	X:447	447		
	SA16:4	X:448	448		
	SA16:6	X:449	449		
	SA16:8	X:450	450		
	SA16:10	X:451	451		
	SA17:4	X:452	452		
	SA17:6	X:453	453		
	SA17:8	X:454	454		
	SA17:10	X:455	455		
	SA18:4	X:456	456		
	SA18:6	X:457	457		
	SA18:8	X:458	458		
	SA18:10	X:459	459		
	SA19:4	X:460	460		
	SA19:6	X:461	461		
	SA19:8	X:462	462		
	SA19:10	X:463	463		
			464		
			465		
			466		
			467		
			468		
			469		
			470		
			471		
			472		