

Левая доковина 2 секции (начало)

	Цепи переменного тока В1		X		
		1	X:1	SG1:2	#
		2	X:2	SG1:4	#
		3	X:3	SG1:6	#
		4	X:4	SG1:8	#
		5	X:5	SG1:10	#
		6	X:6	SG1:12	#
		7			
		8			
	Цепи переменного тока В2		X		
		9	X:7	SG2:2	#
		10	X:8	SG2:4	#
		11	X:9	SG2:6	#
		12	X:10	SG2:8	#
		13	X:11	SG2:10	#
		14	X:12	SG2:12	#
		15			
		16			
	Цепи переменного тока В3		X		
		17	X:17	SG3:2	#
		18	X:18	SG3:4	#
		19	X:19	SG3:6	#
		20	X:20	SG3:8	#
		21	X:21	SG3:10	#
		22	X:22	SG3:12	#
		23			
		24			
	Цепи переменного тока В4		X		
		25	X:25	SG4:2	#
		26	X:26	SG4:4	#
		27	X:27	SG4:6	#
		28	X:28	SG4:8	#
		29	X:29	SG4:10	#
		30	X:30	SG4:12	#
		31			
		32			
	Цепи переменного тока В5		X		
		33	X:33	SG5:2	#
		34	X:34	SG5:4	#
		35	X:35	SG5:6	#
		36	X:36	SG5:8	#
		37	X:37	SG5:10	#
		38	X:38	SG5:12	#
		39			
		40			

Левая доковина 2 секции (продолжение на листе 2)

Правая доковина 2 секции (начало)

Х	Цепи оперативного тока			
UZ1:1	X:161	161		
		162		
SG1:21	X:162	163		
		164		
		165		
		166		
		167		
		168		
		169		
		170		
		171		
		172		
		173		
		174		
		175		
		176		
		177		
		178		
		179		
		180		
A1-M7.XB:1	X:181	181		
		182		
		183		
		184		
		185		
		186		
		187		
		188		
		189		
		190		
A1-M7.XB:2	X:190	191		
		192		
		193		
		194		
		195		
		196		
		197		
		198		
A1-M7.XB:3	X:199	199		
A1-M7.XB:4	X:200	200		
A1-M7.XB:5	X:201	201		
A1-M7.XB:6	X:202	202		
A1-M7.XB:7	X:203	203		
A1-M7.XB:9	X:204	204		
A1-M7.XB:10	X:205	205		
A1-M7.XB:11	X:206	206		
A1-M7.XB:12	X:207	207		
A1-M7.XB:13	X:208	208		
A1-M7.XB:14	X:209	209		
A1-M7.XB:15	X:210	210		

Правая доковина 2 секции (продолжение на листе 2)

Условные обозначения

