

Левая доковина 2 секции (продолжение на листе 3)

	Цепи переменного напряжения 1 секции			X	
		153	X:153	SG20:2	+
		154	X:154	SG20:4	+
		155	X:155	SG20:6	+
		156	X:156	SG20:8	+
	Цепи переменного напряжения 2 секции			X	
		157	X:157	SG21:2	+
		158	X:158	SG21:4	+
		159	X:159	SG21:6	+
		160	X:160	SG21:8	+



Правая доковина 2 секции (продолжение на листе 3)

	SA11:4	X:348	348		
	SA11:6	X:349	349		
	SA11:8	X:350	350		
	SA11:10	X:351	351		
	SA12:4	X:352	352		
	SA12:6	X:353	353		
	SA12:8	X:354	354		
	SA12:10	X:355	355		
	SA13:4	X:356	356		
	SA13:6	X:357	357		
	SA13:8	X:358	358		
	SA13:10	X:359	359		
	SA14:4	X:360	360		
	SA14:6	X:361	361		
	SA14:8	X:362	362		
	SA14:10	X:363	363		
	SA15:4	X:364	364		
	SA15:6	X:365	365		
	SA15:8	X:366	366		
	SA15:10	X:367	367		
	SA16:4	X:368	368		
	SA16:6	X:369	369		
	SA16:8	X:370	370		
	SA16:10	X:371	371		
	SA17:4	X:372	372		
	SA17:6	X:373	373		
	SA17:8	X:374	374		
	SA17:10	X:375	375		
	SA18:4	X:376	376		
	SA18:6	X:377	377		
	SA18:8	X:378	378		
	SA18:10	X:379	379		
			380		
			381		
			382		

