

Левая боковина (начало)				
	Цепи переменного тока В1			Х
		1	Х:1	SG1:2
		2	Х:2	SG1:4
		3	Х:3	SG1:6
		4	Х:4	SG1:8
		5	Х:5	SG1:10
		6	Х:6	SG1:12
			7	
			8	
	Цепи переменного тока В2			Х
		9	Х:7	SG2:2
		10	Х:8	SG2:4
		11	Х:9	SG2:6
		12	Х:10	SG2:8
		13	Х:11	SG2:10
		14	Х:12	SG2:12
			15	
			16	
	Цепи переменного тока В3			Х
		17	Х:17	SG3:2
		18	Х:18	SG3:4
		19	Х:19	SG3:6
		20	Х:20	SG3:8
		21	Х:21	SG3:10
		22	Х:22	SG3:12
			23	
			24	
	Цепи переменного тока В4			Х
		25	Х:25	SG4:2
		26	Х:26	SG4:4
		27	Х:27	SG4:6
		28	Х:28	SG4:8
		29	Х:29	SG4:10
		30	Х:30	SG4:12
			31	
			32	
	Цепи переменного тока В5			Х
		33	Х:33	SG5:2
		34	Х:34	SG5:4
		35	Х:35	SG5:6
		36	Х:36	SG5:8
		37	Х:37	SG5:10
		38	Х:38	SG5:12
			39	
			40	

Левая боковина (продолжение на листе 2)

Правая боковина (начало)				
Х	Выходные цепи			
A1-M2.XB-2	Х:153	153		
A1-M2.XB-4	Х:154	154		
A1-M2.XB-6	Х:155	155		
A1-M2.XB-8	Х:156	156		
A1-M2.XB-10	Х:157	157		
A1-M2.XB-12	Х:158	158		
A1-M2.XB-14	Х:159	159		
A1-M2.XB-16	Х:160	160		
A1-M2.XB-18	Х:161	161		
A1-M2.XB-20	Х:162	162		
A1-M2.XB-22	Х:163	163		
A1-M2.XB-24	Х:164	164		
A1-M2.XB-26	Х:165	165		
A1-M2.XB-28	Х:166	166		
A1-M2.XB-30	Х:167	167		
A1-M2.XB-32	Х:168	168		
A1-M3.XB-2	Х:169	169		
A1-M3.XB-4	Х:170	170		
A1-M3.XB-6	Х:171	171		
A1-M3.XB-8	Х:172	172		
A1-M3.XB-10	Х:173	173		
A1-M3.XB-12	Х:174	174		
A1-M3.XB-14	Х:175	175		
A1-M3.XB-16	Х:176	176		
A1-M3.XB-18	Х:177	177		
A1-M3.XB-20	Х:178	178		
A1-M3.XB-22	Х:179	179		
A1-M3.XB-24	Х:180	180		
A1-M3.XB-26	Х:181	181		
A1-M3.XB-28	Х:182	182		
A1-M3.XB-30	Х:183	183		
A1-M3.XB-32	Х:184	184		
A1-M4.XB-2	Х:185	185		
A1-M4.XB-4	Х:186	186		
A1-M4.XB-6	Х:187	187		
A1-M4.XB-8	Х:188	188		
A1-M4.XB-10	Х:189	189		
A1-M4.XB-12	Х:190	190		
A1-M4.XB-14	Х:191	191		
A1-M4.XB-16	Х:192	192		
	Х:193	193		
	Х:194	194		
	Х:195	195		
	Х:196	196		
	Х:197	197		
	Х:198	198		
	Х:199	199		
	Х:200	200		

Правая боковина (продолжение на листе 2)

