

Левая боковина (начало)				
	Цепи переменного тока В1			Х
		1	X:1	SG1:2
		2	X:2	SG1:4
		3	X:3	SG1:6
		4	X:4	SG1:8
		5	X:5	SG1:10
		6	X:6	SG1:12
			7	
			8	
	Цепи переменного тока В2			Х
		9	X:7	SG2:2
		10	X:8	SG2:4
		11	X:9	SG2:6
		12	X:10	SG2:8
		13	X:11	SG2:10
		14	X:12	SG2:12
			15	
			16	
	Цепи переменного тока В3			Х
		17	X:17	SG3:2
		18	X:18	SG3:4
		19	X:19	SG3:6
		20	X:20	SG3:8
		21	X:21	SG3:10
		22	X:22	SG3:12
			23	
			24	
	Цепи переменного тока В4			Х
		25	X:25	SG4:2
		26	X:26	SG4:4
		27	X:27	SG4:6
		28	X:28	SG4:8
		29	X:29	SG4:10
		30	X:30	SG4:12
			31	
			32	
	Цепи переменного тока В5			Х
		33	X:33	SG5:2
		34	X:34	SG5:4
		35	X:35	SG5:6
		36	X:36	SG5:8
		37	X:37	SG5:10
		38	X:38	SG5:12
			39	
			40	

Левая боковина (продолжение на листе 2)

Правая боковина (начало)				
Х	Выходные цепи			
A1-M2.XB-2	X:153	153		
A1-M2.XB-4	X:154	154		
A1-M2.XB-6	X:155	155		
A1-M2.XB-8	X:156	156		
A1-M2.XB-10	X:157	157		
A1-M2.XB-12	X:158	158		
A1-M2.XB-14	X:159	159		
A1-M2.XB-16	X:160	160		
A1-M2.XB-18	X:161	161		
A1-M2.XB-20	X:162	162		
A1-M2.XB-22	X:163	163		
A1-M2.XB-24	X:164	164		
A1-M2.XB-26	X:165	165		
A1-M2.XB-28	X:166	166		
A1-M2.XB-30	X:167	167		
A1-M2.XB-32	X:168	168		
A1-M3.XB-2	X:169	169		
A1-M3.XB-4	X:170	170		
A1-M3.XB-6	X:171	171		
A1-M3.XB-8	X:172	172		
A1-M3.XB-10	X:173	173		
A1-M3.XB-12	X:174	174		
A1-M3.XB-14	X:175	175		
A1-M3.XB-16	X:176	176		
A1-M3.XB-18	X:177	177		
A1-M3.XB-20	X:178	178		
A1-M3.XB-22	X:179	179		
A1-M3.XB-24	X:180	180		
A1-M3.XB-26	X:181	181		
A1-M3.XB-28	X:182	182		
A1-M3.XB-30	X:183	183		
A1-M3.XB-32	X:184	184		
A1-M4.XB-2	X:185	185		
A1-M4.XB-4	X:186	186		
A1-M4.XB-6	X:187	187		
A1-M4.XB-8	X:188	188		
A1-M4.XB-10	X:189	189		
A1-M4.XB-12	X:190	190		
A1-M4.XB-14	X:191	191		
A1-M4.XB-16	X:192	192		
	X:193	193		
	X:194	194		
	X:195	195		
	X:196	196		
	X:197	197		
	X:198	198		
	X:199	199		
	X:200	200		

Правая боковина (продолжение на листе 2)

