

Левая боковина 2 секции (продолжение на листе 3)

	Цепи переменного напряжения 1 секции			X	
		153	X:153	SG20-2	+
		154	X:154	SG20-4	+
		155	X:155	SG20-6	+
		156	X:156	SG20-8	+
	Цепи переменного напряжения 2 секции			X	
		157	X:157	SG21-2	+
		158	X:158	SG21-4	+
		159	X:159	SG21-6	+
		160	X:160	SG21-8	+

Правая боковина 2 секции (продолжение на листе 3)

	SA11-4	X:348	348		
	SA11-6	X:349	349		
	SA11-8	X:350	350		
	SA11-10	X:351	351		
	SA12-4	X:352	352		
	SA12-6	X:353	353		
	SA12-8	X:354	354		
	SA12-10	X:355	355		
	SA13-4	X:356	356		
	SA13-6	X:357	357		
	SA13-8	X:358	358		
	SA13-10	X:359	359		
	SA14-4	X:360	360		
	SA14-6	X:361	361		
	SA14-8	X:362	362		
	SA14-10	X:363	363		
	SA15-4	X:364	364		
	SA15-6	X:365	365		
	SA15-8	X:366	366		
	SA15-10	X:367	367		
	SA16-4	X:368	368		
	SA16-6	X:369	369		
	SA16-8	X:370	370		
	SA16-10	X:371	371		
	SA17-4	X:372	372		
	SA17-6	X:373	373		
	SA17-8	X:374	374		
	SA17-10	X:375	375		
	SA18-4	X:376	376		
	SA18-6	X:377	377		
	SA18-8	X:378	378		
	SA18-10	X:379	379		
			380		
			381		
			382		