

Левая доковина 2 секции (начало)

	Цепи переменного тока В1		X		
		1	X:1	SG1:2	#
		2	X:2	SG1:4	#
		3	X:3	SG1:6	#
		4	X:4	SG1:8	#
		5	X:5	SG1:10	#
		6	X:6	SG1:12	#
		7			
		8			
	Цепи переменного тока В2		X		
		9	X:7	SG2:2	#
		10	X:8	SG2:4	#
		11	X:9	SG2:6	#
		12	X:10	SG2:8	#
		13	X:11	SG2:10	#
		14	X:12	SG2:12	#
		15			
		16			
	Цепи переменного тока В3		X		
		17	X:17	SG3:2	#
		18	X:18	SG3:4	#
		19	X:19	SG3:6	#
		20	X:20	SG3:8	#
		21	X:21	SG3:10	#
		22	X:22	SG3:12	#
		23			
		24			
	Цепи переменного тока В4		X		
		25	X:25	SG4:2	#
		26	X:26	SG4:4	#
		27	X:27	SG4:6	#
		28	X:28	SG4:8	#
		29	X:29	SG4:10	#
		30	X:30	SG4:12	#
		31			
		32			
	Цепи переменного тока В5		X		
		33	X:33	SG5:2	#
		34	X:34	SG5:4	#
		35	X:35	SG5:6	#
		36	X:36	SG5:8	#
		37	X:37	SG5:10	#
		38	X:38	SG5:12	#
		39			
		40			

Левая доковина 2 секции (продолжение на листе 2)

Правая доковина 2 секции (начало)

	X	Цены оперативного тока			
+	UZ1:1	X:161	161		
—	SG1:21	X:162	162		
			163		
			164		
			165		
			166		
			167		
			168		
			169		
			170		
			171		
			172		
			173		
			174		
			175		
			176		
			177		
			178		
			179		
			180		
—	A1-M7.XB:1	X:181	181		
			182		
			183		
			184		
			185		
			186		
			187		
			188		
			189		
—	A1-M7.XB:2	X:190	190		
			191		
			192		
			193		
			194		
			195		
			196		
			197		
			198		
—	A1-M7.XB:3	X:199	199		
—	A1-M7.XB:4	X:200	200		
—	A1-M7.XB:5	X:201	201		
—	A1-M7.XB:6	X:202	202		
—	A1-M7.XB:7	X:203	203		
—	A1-M7.XB:9	X:204	204		
—	A1-M7.XB:10	X:205	205		
—	A1-M7.XB:11	X:206	206		
—	A1-M7.XB:12	X:207	207		
—	A1-M7.XB:13	X:208	208		
—	A1-M7.XB:14	X:209	209		
—	A1-M7.XB:15	X:210	210		

Правая доковина 2 секции (продолжение на листе 2)

Условные обозначения

