

Левая боковина 2 секции (продолжение на листе 3)				
	Цепи переменного напряжения 1 секции			X
		153	X:153	SG20:2
		154	X:154	SG20:4
		155	X:155	SG20:6
		156	X:156	SG20:8
	Цепи переменного напряжения 2 секции			X
		157	X:157	SG21:2
		158	X:158	SG21:4
		159	X:159	SG21:6
		160	X:160	SG21:8

Правая боковина 2 секции (продолжение на листе 3)				
SA11:4	X:348	348		
SA11:6	X:349	349		
SA11:8	X:350	350		
SA11:10	X:351	351		
SA12:4	X:352	352		
SA12:6	X:353	353		
SA12:8	X:354	354		
SA12:10	X:355	355		
SA13:4	X:356	356		
SA13:6	X:357	357		
SA13:8	X:358	358		
SA13:10	X:359	359		
SA14:4	X:360	360		
SA14:6	X:361	361		
SA14:8	X:362	362		
SA14:10	X:363	363		
SA15:4	X:364	364		
SA15:6	X:365	365		
SA15:8	X:366	366		
SA15:10	X:367	367		
SA16:4	X:368	368		
SA16:6	X:369	369		
SA16:8	X:370	370		
SA16:10	X:371	371		
SA17:4	X:372	372		
SA17:6	X:373	373		
SA17:8	X:374	374		
SA17:10	X:375	375		
SA18:4	X:376	376		
SA18:6	X:377	377		
SA18:8	X:378	378		
SA18:10	X:379	379		
		380		
		381		
		382		