

2 секция. Левая боковина (продолжение на листе 3)				
	Цепи переменного тока ШСВ стороны 2 секции			X
		153	X:153	SG20:2
		154	X:154	SG20:4
		155	X:155	SG20:6
		156	X:156	SG20:8
		157	X:157	SG20:10
		158	X:158	SG20:12
		 159		
		 160		
	Цепи переменного напряжения 1 секции			X
		161	X:161	SG21:2
		162	X:162	SG21:4
		163	X:163	SG21:6
		164	X:164	SG21:8
	Цепи переменного напряжения 2 секции			X
		165	X:165	SG22:2
		166	X:166	SG22:4
		167	X:167	SG22:6
		168	X:168	SG22:8

2 секция. Правая боковина (продолжение на листе 3)				
	SA10:10	X:427	427	
	SA11:4	X:428	428	
	SA11:6	X:429	429	
	SA11:8	X:430	430	
	SA11:10	X:431	431	
	SA12:4	X:432	432	
	SA12:6	X:433	433	
	SA12:8	X:434	434	
	SA12:10	X:435	435	
	SA13:4	X:436	436	
	SA13:6	X:437	437	
	SA13:8	X:438	438	
	SA13:10	X:439	439	
	SA14:4	X:440	440	
	SA14:6	X:441	441	
	SA14:8	X:442	442	
	SA14:10	X:443	443	
	SA15:4	X:444	444	
	SA15:6	X:445	445	
	SA15:8	X:446	446	
	SA15:10	X:447	447	
	SA16:4	X:448	448	
	SA16:6	X:449	449	
	SA16:8	X:450	450	
	SA16:10	X:451	451	
	SA17:4	X:452	452	
	SA17:6	X:453	453	
	SA17:8	X:454	454	
	SA17:10	X:455	455	
	SA18:4	X:456	456	
	SA18:6	X:457	457	
	SA18:8	X:458	458	
	SA18:10	X:459	459	
	SA19:4	X:460	460	
	SA19:6	X:461	461	
	SA19:8	X:462	462	
	SA19:10	X:463	463	
		464		
		465		
		466		
		467		
		468		
		469		
		470		
		471		
		472		