

Левая доковина (начало)

	Цепи переменного тока В1		X2		
		1	X2:1	SG5:2	#
		2	X2:2	SG5:4	#
		3	X2:3	SG5:6	#
		4	X2:4	SG5:8	#
		5	X2:5	SG5:10	#
		6	X2:6	SG5:12	#
		7			
		8			
	Цепи переменного тока В2		X2		
		9	X2:9	SG6:2	#
		10	X2:10	SG6:4	#
		11	X2:11	SG6:6	#
		12	X2:12	SG6:8	#
		13	X2:13	SG6:10	#
		14	X2:14	SG6:12	#
		15			
		16			
	Цепи переменного тока Т(АТ)		X2		
		17	X2:17	SG7:2	#
		18	X2:18	SG7:4	#
		19	X2:19	SG7:6	#
		20	X2:20	SG7:8	#
		21	X2:21	SG7:10	#
		22	X2:22	SG7:12	#
		23			
		24			
	Цепи переменного напряжения		X2		
		25	X2:25	SG8:2	+
		26	X2:26	SG8:4	+
		27	X2:27	SG8:6	+
		28	X2:28	SG8:8	+
	Цепи оперативного тока		X2		
		29	X2:29	UZ2:1	+
		30	X2:30	SG5:14	—
		31			
		32			
		33			
		34	X2:34	A2-M6.XB-1	—
		35			
		36			
		37			
		38	X2:38	A2-M6.XB-3	—
		39	X2:39	A2-M6.XB-5	—
		40			

Левая доковина (продолжение на листе 2)

Правая доковина (начало)

	X1	Цепи переменного тока В1			
#	SG1:2	X1:1	1		
#	SG1:4	X1:2	2		
#	SG1:6	X1:3	3		
#	SG1:8	X1:4	4		
#	SG1:10	X1:5	5		
#	SG1:12	X1:6	6		
			7		
			8		
	X1	Цепи переменного тока В2			
#	SG2:2	X1:9	9		
#	SG2:4	X1:10	10		
#	SG2:6	X1:11	11		
#	SG2:8	X1:12	12		
#	SG2:10	X1:13	13		
#	SG2:12	X1:14	14		
			15		
			16		
	X1	Цепи переменного тока Т(АТ)			
#	SG3:2	X1:17	17		
#	SG3:4	X1:18	18		
#	SG3:6	X1:19	19		
#	SG3:8	X1:20	20		
#	SG3:10	X1:21	21		
#	SG3:12	X1:22	22		
			23		
			24		
	X1	Цепи переменного напряжения			
+	SG4:2	X1:25	25		
+	SG4:4	X1:26	26		
+	SG4:6	X1:27	27		
+	SG4:8	X1:28	28		
	X1	Цепи оперативного тока			
+	UZ1:1	X1:29	29		
—	SG1:14	X1:30	30		
			31		
			32		
			33		
—	A1-M6.XB-1	X1:34	34		
			35		
			36		
			37		
—	A1-M6.XB-3	X1:38	38		
—	A1-M6.XB-5	X1:39	39		
			40		

Правая доковина (продолжение на листе 2)

Условные обозначения

