

	Цепи переменного тока ЛЭП		X	
		1 X:1	SG1:2	#
		2 X:2	SG1:4	#
		3 X:3	SG1:6	#
		4 X:4	SG1:8	#
		5 X:5	SG1:10	#
		6 X:6	SG1:12	#
		7		
		8		
	Цепи переменного тока 3/0 ЛЭП		X	
		9 X:9	SG2:2	#
		10 X:10	SG2:4	#
	Цепи переменного напряжения		X	
		11 X:11	SG3:2	+
		12 X:12	SG3:4	+
		13 X:13	SG3:6	+
		14 X:14	SG3:8	+
		15 X:15	SG4:2	+
		16 X:16	SG4:4	+
		17 X:17	SG4:6	+
		18 X:18	SG4:8	+
	Цепи отбора напряжения ЛЭП		X	
		19 X:19	SG5:2	+
		20 X:20	SG5:4	+
		21 X:21	SG5:6	+
	Цепи оперативного тока		X	
		22 X:22	UZ1:1	+
		23 X:23	SG1:14	
		24		
		25		
		26		
		27		
		28		
		29 X:29	A1-M4.XB:1	
		30 X:30	A1-M4.XB:3	
		31 X:31	A1-M4.XB:5	
		32 X:32	A1-M4.XB:7	
		33 X:33	A1-M4.XB:9	
		34 X:34	A1-M4.XB:11	
		35 X:35	A1-M4.XB:13	
		36 X:36	A1-M4.XB:15	
		37 X:37	A1-M4.XB:17	
		38 X:38	A1-M4.XB:19	
		39 X:39	A1-M4.XB:21	
		40 X:40	A1-M4.XB:23	
		41 X:41	A1-M4.XB:25	

Условные обозначения

