

Левая боковина (продолжение на листе 2)

		111		
		112		
		113		
		114		
		115		
		116		
-EC3		117	X:117	A1-M6.XB.30
		118	X:118	R4-2
	Цепи ЗДЗ НН1		X	
+EC4		119	X:119	A1-M7.XB.1
		120		
		121	X:121	A1-M6.XB.31
-EC4		122	X:122	A1-M7.XB.2
		123		
	Цепи Обода НН1		X	
+EC5		124	X:124	A1-M7.XB.7
		125		
		126	X:126	A1-M7.XB.3
		127	X:127	A1-M7.XB.5
-EC5		128	X:128	A1-M7.XB.4
		129		
	Цепи ЗДЗ СН (НН2)		X	
+EC6		130	X:130	A1-M7.XB.11
		131		
		132	X:132	A1-M7.XB.9
-EC6		133	X:133	A1-M7.XB.10
		134		
	Цепи Обода СН (НН2)		X	
+EC7		135	X:135	A1-M7.XB.17
		136		
		137	X:137	A1-M7.XB.13
		138	X:138	A1-M7.XB.15
-EC7		139	X:139	A1-M7.XB.14
		140		
	Цепи ЗДЗ НН3		X	
+EC8		141	X:141	A1-M7.XB.21
		142		
		143	X:143	A1-M7.XB.19
-EC8		144	X:144	A1-M7.XB.20
		145		
	Цепи Обода НН3		X	
+EC9		146	X:146	A1-M7.XB.27
		147		
		148	X:148	A1-M7.XB.23
		149	X:149	A1-M7.XB.25
-EC9		150	X:150	A1-M7.XB.24
		151		
	Цепи ЗДЗ НН4		X	
+EC10		152	X:152	A1-M7.XB.31
		153		
		154	X:154	A1-M7.XB.29
-EC10		155	X:155	A1-M7.XB.30
		156		
	Цепи Обода НН4		X	
+EC11		157	X:157	A1-M8.XB.5
		158		
		159	X:159	A1-M8.XB.1
		160	X:160	A1-M8.XB.3
-EC11		161	X:161	A1-M8.XB.2
		162		

Правая боковина (продолжение на листе 2)

X		Цепи РАС A1		
A1-M1XP.5	X:277	277	♀	
A1-M1XP.15	X:278	278	♂	
		279		
A1-M1XP.4	X:280	280		
A1-M1XP.14	X:281	281		
X		Цепи переменного тока A2		
SG11.2	X:282	282		
SG11.4	X:283	283	↗	
SG11.6	X:284	284	↘	
SG11.8	X:285	285	↗	
SG11.10	X:286	286		
SG11.12	X:287	287	↘	
		288	♀	
		289	♂	
SG12.2	X:290	290	↘	
SG12.4	X:291	291	↗	
SG12.6	X:292	292		
SG12.8	X:293	293	↘	
SG12.10	X:294	294	↗	
SG12.12	X:295	295	↘	
		296	♀	
		297	♂	
SG13.2	X:298	298	↗	
SG13.4	X:299	299	↘	
SG13.6	X:300	300	↗	
SG13.8	X:301	301	↘	
SG13.10	X:302	302	↗	
SG13.12	X:303	303	↘	
		304	♀	
		305	♂	
X		Цепи оперативного постоянного тока A2		
SG13.14	X:306	306	♀	+EC12
UZ2.8	X:307	307	♂	
A2.1-X4.2	X:308	308	♀	-EC12
UZ2.11	X:309	309	♂	
X		Выходные цепи A2		
A2-M2.XB.2	X:310	310	X:310	X:60
A2-M2.XB.4	X:311	311		
		312		
		313		
SA17.4	X:314	314	X:314	X:63
SA18.4	X:315	315		
		316		
		317		
		318		
		319		
X		Цепи сигнализации A2		
A2-M1XP.2	X:320	320	♀	+EH1
		321	♂	
		322	♀	(+)EH1
		323	♂	
		324		
		325		
A2-M1XP.3	X:326	326	X:326	X:269
		327		
		328		
		329		
		330		
		331		
		332	♀	-EH1
		333	♂	X:276

Правая боковина (продолжение на листе 4)