
-> Sourcern Lernbill. -> 50 gs load. 3 4ell bills -> how to coal the hornbill boxes. bills -> ultirately mitigate the high temps. to dronges one winning but how dronges -> reasure preig BM Later -> frey are 848 Andjing how birds are corping. -> frey want to reasone BM and femp but trey can't - converty:

- asing medisied kitchen smalle scales * Convertly: approx weights: 42 -> 62. Sig error 18 too high > 10013 eating chicks during twilight activity -> tregra 50.6°C is the limity. -> Nests (Boxes) Hardwood hole & perch plywood side and roof
1,5m above ground -> Cameras record too late. Unreliable in recording -) Interior of box needs to be wood Drongos climb up, fetch cam Hornbills Lift lid, lift temale collect data, replace PROBLEM with pillowcase, measure battery, pet back (1) chicks, replace all



The drive between nests

6m high ladder, measure

chicks, swap camera traps

Driving main issue

Red-Winged Startings Secretary Birds

Nest

> Freestanding camera trop

> Stability key

The stability key >> Stability Key -> Not too visible -> No vigible wires -> Nest on top of trees Red-Winged Starlings -> Clever -> Interested in breeding pattern in city -> Need v. small not visible cameras watching nests -> No charge for up to z months - Livestreamed? -) Scale to auto-record weight (Birds ID'd) \$150-160g Max -> Upper Campus