


PROGRAM: 1969r1



LEGEND

—	WIRING BY VENDOR
- - -	WIRING BY CUSTOMER

NOTE

- INTERNAL MOTOR THERMAL OVERLOAD IS RECOMMENDED.

