



Wydział Mechaniczny Energetyki i Lotnictwa
Politechnika Warszawska

Wprowadzenie do PTC Creo

mgr inż. Grzegorz Kamiński

1 października 2025

Etapy procesu wytwarzania

- * stworzenie obrabianego modelu,
- * definicja środowiska gdzie odbywa się proces wytwarzania (typ obrabiarki, uchwyty, narzędzia, baz),
- * stworzenie ścieżek NC (wybór konkretnego narzędzia do geometrii),
- * przeniesienie ścieżek na urządzenie.

Manufacturing

New

Type

- ☐ Layout
- ☐ Sketch
- ☐ Part
- ☐ Assembly
- ☒ Manufacturing
- ☐ Drawing
- ☐ Format
- ☐ Notebook

Sub-type

- ☒ NC assembly
- ☐ Expert machinist
- ☐ CMM
- ☐ Sheetmetal
- ☐ Cast cavity
- ☐ Mold cavity
- ☐ Harness
- ☐ Process plan
- ☐ Additive Manufacturing



Name: mfg0002

Common name:

☒ Use default template



OK Cancel

Workpiece




Create: Rectangular Workpiece
Choose Csys


Workpiece




Fixture




Clearance



Coordinate system for mill



Work Center Configuration



Milling Work Center

Name: MILL01

Type: Mill

CNC Control: -

Post Processor: UNCX01 ID 1

Number of Axes: 3 Axis ☐ Enable probing

Output Tools Parameters Assembly Travel Cycles Properties

Commands

FROM: Do Not Output

LOADTL: Modal

COOLNT/OFF: Output

SPINDL/OFF: Output

Cutter Compensation

Output Point: Tool Center

Safe Radius: 0.05

Adjust Corner: Straight

Spline Output:

Probe Compensation

Output Point: Stylus Center

Pause OK Cancel

Operations

 MILL01  ACS0:F9(CSYS)

Clearance Parameters Options Fixture Setup Process Properties

 MILL01  NC_ASM_DEF_CSYS:F4(CSYS) ID=8

Clearance Home Point Parameters Options Fixture Setup Process Properties

Model


Type: None

Reference:

Tolerance: 0.10


☒ Always use Operation Retract

Cutting Tools









Cutting Tools



Edit the set of cutting tools available on the machine tool for the active operation.





Cutting Tools




Volume Milling




Cutting Tools



Local Milling



Surface Milling





Dziękuję
za uwagę

grzegorz.kaminski@pw.edu.pl