Spheres

Lens Riding High	Steepen Base Curve by .50 D	
	Reduce Diameter by .3 mm	
Lens Riding Low	Movement with Blink	Steepen Base Curve by .50 D
		Increase Diameter by .3mm
	No Movement	Flatten Base Curve by .50 D
		Decrease Diameter by .3 mm
Excessive Movement	Steepen Base Curve by .50 D	
	Increase Diameter by .3 mm	
Restricted Movement	Flatten Base Curve by .50 D	
	Decrease Diameter by .3 mm	
Bubbles	Centrally	Flatten Base Curve by .50 D
		Decrease Diameter by .3 mm
	Peripherally	Decrease Edge Lift by 1.00 mm
		Increase Diameter by .3mm
Surface Non Wetting	New Lens	Clean Lens
		Change Material
	Older Lens	Clean Lens
		Order New Lens
Too Much Edge Lift	Reduce Edge Lift by 1.00mm	
	Increase Diameter by .3 mm	
Not Enough Edge Lift	Increase Edge Lift by 1.00 mm	
	Decrease Diameter by .3 mm	