RECEIPT FOR REPORTS
(FORM RR PAGE 1 OF 2)
The buyer acknowledges receipt of the reports listed below.
Report line 1.1: received and reviewed.
Report line 1.2: received and reviewed.
Report line 1.3: received and reviewed.
Report line 1.4: received and reviewed.

RECEIPT FOR REPORTS
(FORM RR PAGE 2 OF 2)
The buyer acknowledges receipt of the reports listed below.
Report line 2.1: received and reviewed.
Report line 2.2: received and reviewed.
Report line 2.3: received and reviewed.
Report line 2.4: received and reviewed.

(555) 010-0300
office@harborpoint.example
PROPERTY INSPECTION REPORT
1.1 Finding about the roof, part 1
Moderate
The flashing at corner 1 is loose.
Recommendation
Have a roofer reseal it.
1.2 Finding about the gutters, part 1
Moderate
Gutter run 1 sags.
Recommendation
Rehang the gutter.

Docusign Envelope ID: 3C9A51E2-6B7D-4F80-9A1B-2C3D4E5F6A7B

(555) 010-0300
office@harborpoint.example
2.1 Finding about the roof, part 2
Moderate
The flashing at corner 2 is loose.
Recommendation
Have a roofer reseal it.
2.2 Finding about the gutters, part 2
Moderate
Gutter run 2 sags.
Recommendation
Rehang the gutter.

Docusign Envelope ID: 3C9A51E2-6B7D-4F80-9A1B-2C3D4E5F6A7B

(555) 010-0300
office@harborpoint.example
3.1 Finding about the roof, part 3
Moderate
The flashing at corner 3 is loose.
Recommendation
Have a roofer reseal it.
3.2 Finding about the gutters, part 3
Moderate
Gutter run 3 sags.
Recommendation
Rehang the gutter.

Docusign Envelope ID: 3C9A51E2-6B7D-4F80-9A1B-2C3D4E5F6A7B

(555) 010-0300
office@harborpoint.example
4.1 Finding about the roof, part 4
Moderate
The flashing at corner 4 is loose.
Recommendation
Have a roofer reseal it.
4.2 Finding about the gutters, part 4
Moderate
Gutter run 4 sags.
Recommendation
Rehang the gutter.

Docusign Envelope ID: 3C9A51E2-6B7D-4F80-9A1B-2C3D4E5F6A7B

INVOICE
40010001
INVOICE DATE
May 2, 2025
Osprey Plumbing & Drain
License #000321 | Port Alder, CA 90000
Invoice line 1.1: pipe work item 1
Invoice line 1.2: pipe work item 2
Invoice line 1.3: pipe work item 3

Docusign Envelope ID: 3C9A51E2-6B7D-4F80-9A1B-2C3D4E5F6A7B

Invoice line 2.1: pipe work item 1
Invoice line 2.2: pipe work item 2
Invoice line 2.3: pipe work item 3

Docusign Envelope ID: 3C9A51E2-6B7D-4F80-9A1B-2C3D4E5F6A7B

Invoice line 3.1: pipe work item 1
Invoice line 3.2: pipe work item 2
Invoice line 3.3: pipe work item 3

Docusign Envelope ID: 3C9A51E2-6B7D-4F80-9A1B-2C3D4E5F6A7B

ESTIMATE
40010002
ESTIMATE DATE
May 2, 2025
Osprey Plumbing & Drain
License #000321 | Port Alder, CA 90000
Estimate line 1.1: pipe work item 1
Estimate line 1.2: pipe work item 2
Estimate line 1.3: pipe work item 3

Docusign Envelope ID: 3C9A51E2-6B7D-4F80-9A1B-2C3D4E5F6A7B

Estimate line 2.1: pipe work item 1
Estimate line 2.2: pipe work item 2
Estimate line 2.3: pipe work item 3

Docusign Envelope ID: 3C9A51E2-6B7D-4F80-9A1B-2C3D4E5F6A7B

ESTIMATE
40010003
ESTIMATE DATE
May 2, 2025
Osprey Plumbing & Drain
License #000321 | Port Alder, CA 90000
Estimate line 1.1: pipe work item 1
Estimate line 1.2: pipe work item 2
Estimate line 1.3: pipe work item 3

Docusign Envelope ID: 3C9A51E2-6B7D-4F80-9A1B-2C3D4E5F6A7B

Estimate line 2.1: pipe work item 1
Estimate line 2.2: pipe work item 2
Estimate line 2.3: pipe work item 3

Docusign Envelope ID: 3C9A51E2-6B7D-4F80-9A1B-2C3D4E5F6A7B

Inspector / Licence No. 000456
Sandpiper Pest Control, Inc.
WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT
Findings are listed by section below.
Item 1A: evidence of drywood termites at the eave.

Section 2: subarea findings
Item 2A: evidence of drywood termites at the eave.

Section 3: subarea findings
Item 3A: evidence of drywood termites at the eave.

Section 4: subarea findings
Item 4A: evidence of drywood termites at the eave.

Standardized Notice of Work Completed; Items Pending
Report #: 70001
Items 1A and 2A were completed on April 20, 2025.

Sandpiper Pest Control, Inc.
(555) 010-0400 - Phone

Inspector / Licence No. 000456
Sandpiper Pest Control, Inc.
WOOD DESTROYING PESTS AND ORGANISMS REINSPECTION REPORT
Reinspection note 1: no further activity.

Reinspection note 2: no further activity.

Marisol Vega Finish Carpentry
88 Kelp Ave.
Port Alder, CA. 90000
Lic # 000111
(555) 010-0444
June 3, 2025
Re: 12 Gull Ln
Repaired the eave boards noted in the pest report.
Total: $900

Pay online
ITEM QTY AMOUNT
Thermostat, programmable 1 $180.00
Invoice # GA-17-2
Total: $180.00

Gull Air Heating
Questions? Call (555) 010-0555 billing@gullair.example
License #000222