$$Q(x) = \frac{1 - erf(x/\sqrt{2})}{2}$$

HATA FONKSIYONU DEĞERLERİ

$$Q(x) = \frac{1 - \operatorname{erf}(x/12)}{2}$$

$$Q(12x) = \frac{1 - \operatorname{erf}(x)}{2} = \frac{\operatorname{erfc}(x)}{2}$$




Table 1. Fonksiyonu Değerleri

	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09
0.0	.5000	.4960	.4920	.4880	.4840	.4801	.4761	.4721	.4681	.4641
0.1	.4602	.4562	.4522	.4483	.4443	.4404	.4364	.4325	.4286	.4247
0.2	.4207	.4168	.4129	.4090	.4052	.4013	.3974	.3936	.3897	.3859
0.3	.3821	.3783	.3745	.3707	.3669	.3632	.3594	.3557	.3520	.3483
0.4	.3446	.3409	.3372	.3336	.3300	.3264	.3228	.3192	.3156	.3121
0.5	.3085	.3050	.3015	.2981	.2946	.2912	.2877	.2843	.2810	.2776
0.6	.2743	.2709	.2776	.2643	.2611	.2578	2546	.2514	.2483	.2451
0.7	.2420	.2389	.2358	.2327	.2296	.2266	.2236	.2206	.2177	.2148
0.8	.2119	.2090	.2061	.2033	.2005	.1977	.1949	.1922	.1894	.1867
0.9	.1841	.1814	.1788	.1762	.1736	.1711	.1685	.1660	.1635	.1611
1.0	.1587	.1562	.1539	.1515	.1492	.1469	.1446	.1423	.1401	.1379
1.1	.1357	.1335	.1314	.1292	.1271	.1251	.1230	.1210	.1190	.1170
1.2	.1151	.1131	.1112	.1093	.1075	.1056	.1038	.1020	.1003	.0985
1.3	.0968	.0951	.0934	.0918	.0901	.0885	.0869	.0853	.0838	.0823
1.4	.0808	.0793	.0778	.0764	.0749	.0735	.0721	.0708	.0664	.0681
1.5	.0668	.0655	.0643	.0630	.0618	.0606	.0594	.0582	.0571	.0559
1.6	.0548	.0537	.0526	.0516	.0505	.0495	.0485	.0475	.0465	.0455
1.7	.0446	.0436	.0427	.0418	.0409	.0401	.0392	.0384	.0375	.0367
1.8	.0359	.0351	.0344	.0336	.0329	.0322	.0314	.0307	.0301	.0294
1.9	.0287	.0281	.0274	.0268	.0262	.0256	.0250	.0244	.0239	.0233
2.0	.0228	.0222	.0217	.0212	.0207	.0202	.0197	.0192	.0188	.018
2.1	.0179	.0174	.0170	.0166	.0162	.0158	.0154	.0150	.0146	.014
2.2	.0139	.0136	.0132	.0129	.0125	.0122	.0119	.0116	.0113	.011
2.3	.0107	.0104	.0102	.00990	.00964	.00939	.00914	.00889	.00866	.0084
2.4	.00820	.00798	.00776	.00755	.00734	.00714	.00695	.00676	.00857	.0063
2.5	.00621	.00604	.00587	.00570	.00554	.00539	.00523	.00508	.00494	.0048
2.6	.00466	.00453	.00440	.00427	.00415	.00402	.00391	.00379	.00368	.0035
2.7	.00347	.00336	.00326	.00317	.00307	.00298	.00289	.00280	,00272	.0026
2.8	.00256	.00248	.00240	.00233	.00226	.00219	.00212	.00205	.00199	.0019
2.9	.00187	.00181	.00175	.00169	.00164	.00159	.00154	.00149	.00144	.0013

×	10 logx	(X(x)	×	10 log x	Q(x)	×	10 logx	Q(x)
3.00	4.77	1.35E-03	4.00	6.02	3.17E-05	5.00	6.99	2.87E-07
3.05	4.84	1.14E-03	4.05	6.07	2.056-05	5.05	7.03	2.21E-07
3.10	4.91	9.68E-04	4.10	6.13	2.07E-05	5.10	7.08	1.70E-07
3.15	4.98	8.16E-04	4.15	6.18	1.67E-05	5.15	7.12	1.30E-07
3.20	5.05	6.87E-04	4.20	6.23	1.33E-05	5.20	7.16	9.96E-08
3.25	5.12	5.77E-04	4.25	6.28	1.07E-05	5.25	7.20	7.61E-08
3.30	5.19	4.83E-04	4.30	6.33	8.54E-06	5.30	7.24	5.79E-08
3.35	5.25	4.04E-04	4.35	6.38	6.81E-06	5.35	7.28	4.40E-08
3.40	5.31	3.37E-04	4.40	6.43	5.41E-06	5.40	7.32	3.33E-08
3.45	5.38	2.80E-04	4.45	6.48	4.29E-06	5.45	7.36	2.52E-08
3.50	5.44	2.33E-04	4.50	6.53	3.40E-06	5.50	7.40	1.90E-08
3.55	5.50	1.93E-04	4.55	6.58	2.68E-06	5.55	7.44	1.43E-08
3.60	5.56	1.59E-04	4.60	6.63	2.11E-06	5.60	7.48	1.07E-08
3.65	5.62	1.31E-04	4.65	6.67	1.66E-06	5,65	7.52	8.03E-09
3.70	5.68	1.08E-04	4.70	6.72 -	1.30E-06	5.70	7.56	6.00E-09
3.75	5.74	8.84E-05	4.75	6.77	1.02E-06	5.75	7.60	4.47E-09
3.80	5.80	7.23E-05	4,80	6.81	7.93E-07	5.80	7.63	3.32E-09
3.85	5.85	5.91E-05	4.85	6.86	6.17E-07	5.85	7.67	2.46E-09
3.90	5.91	4.81E-05	4.90	6.90	4.79E-07	5.90	7.71	1.82E-09
3.95	5.97	3.91E-05	4.95	6.95	3.71E-07	5.95	7.75	1.34E-09