

### International Federation of Automatic Control

### BENCHMARK PROBLEMS FOR CONTROL SYSTEM DESIGN

REPORT OF THE IFAC THEORY COMMITTEE

Edited by Edward J. Davison, Chairman

### Benchmark Problems for Control System Design

### **Abstract**

This report contains a collection of potential "benchmark problems" for the Control Community and has been completed by the IFAC Theory Committee over the period July 1987 - July 1990. The motivation for carrying out such a study is that it was believed by the IFAC Theory Committee that it would be useful to have a collection of standard problems for comparing the benefits of "new or existing control system design tools", i.e. at present, every new design method is applied to some ad hoc example, and it is difficult to determine a meaningful comparison between existing techniques.

The procedure for collecting such benchmark problems was as follows. A formal request to the Control Community asking for potential benchmark problems appeared in:

- (a) The IFAC Newsletter No. 5, October 1988.
- (b) The IEEE Control System Society Magazine, February 1989;

and in addition:

(c) A request for submission of potential problems from the IFAC Theory Committee members (representing 32 countries) was made.

i.e. potential problems were sought from as wide an audience as possible. The submitted problems were then reviewed, and a subset of the problems selected, with a view of obtaining the widest possible selection of representative "real world" problems. (Page limitations dictated that only a subset of submitted problems could be accepted.)

With the exception of one problem (90-13), all of the enclosed benchmark problems are modelled from the "real world"; the majority of the problems are multivariable, and many of the problems have associated with them structured uncertainties, as well as constraints of various types associated with either inputs or outputs of the system. All of the problems have associated with them a contact address, where additional information on the problem may be obtained on request.

Edward J. Davison

May 1990

### List of Benchmark Problems

		Page
90-01	Binary Distillation Column	2
90-02	Drum Boiler Problem	4
90-03	Shell Control Problem	6
90-04	Cold Rolling Mill	10
90-05	Control of Missile Autopilot	15
90-06	Lower Order Controller for a High Order Plant	17
90-07	Hydraulic Positioning System	30
90-08	Control Surface Servo Problem for an Underwater Vehicle	32
90-09	Cascade of Inverted Pendula	37
90-10	Regulation of a Ship's Heading	41
90-11	Automatic Track Control of City Bus	43
90-12	Robotic System Problem	45
90-13	Robust Control of a 'Simple Process'	52

### List of Contributors to Report

Benchmark Problem No. 90-01: E.J. Davison

90-02: E.J. Davison

90-03: J.C. Kantor

90-04: H.W. Smith

90-05: U. Hartmann, G. Grebing

90-06: B.D.O. Anderson, U-L. Ly, Yi Liu

90-07: M. Senning

90-08: H.W. Smith

90-09: E.J. Davison

90-10: K.J. Astrom

90-11: J. Ackermann, W. Darenberg

90-12: I. Troch, K. Desoyer

90-13: Ph. de Larminat

### Characterization of Benchmark Problems by Area

	$\underline{\text{Page}}$
Process Control	1
90-01 Binary Distillation Column	2
90-02 Drum Boiler System	4
90-03 Shell Control Problem	6
90-04 Cold Rolling Mill	10
Aero-Control	14
90-05 Control of Missile Autopilot	15
90-06 Lower Order Controller for a High Order Plant	17
Servo-Control	29
90-07 Hydraulic Positioning System	30
90-08 Control Surface Servo Problem for an Underwater Vehicle	32
Mechanical Systems	36
90-09 Cascade of Inverted Pendula	37
90-10 Regulation of a 'Ship's Heading'	41
90-11 Automatic Track Control of a City Bus	43
90-12- Robotic System Problem	45
General Systems	51
90-13 Robust Control of a 'Simple Process'	52

# Overview Description of Benchmark Problems

			7	$\overline{}$	_		1	_		1		_						_			_		_
	Characteristics of problem		constraints imposed	non-minimum phase plant	constraints imposed,	plant parameter variations specified	constraints imposed	constraints imposed,	plant parameter variations specified	non-minimum phase plant,	constraints imposed	constraints imposed,	plant parameter variations specified	constraints imposed,	decentralized control structure imposed,	plant parameter variations specified	non-minimum phase plant	constriants imposed	constraints imposed,	plant parameter variations specified	3 degree of freedom	+ DC motor dynamics	constraints imposed
No. of	uncertain	parameters	1		က		•	2		ı	,	∞		1			1		2		1		4
No. of	explicit	disturbances	1	1	2	_	က	ı		•		1		2			1	ı	,		•		1
No. of	measurable	outputs	unspecified	2	2	,	5	Ţ		2		П		2			1 to 10	ŗ	4		င		H
No. of	outputs		3	2	2		5	1		2		1		1			1 to 10	1	1		ŝ		1
No. of	inputs		ဗ	3	3		8	ī		8		H		2			1 to 10	1	1		3		1
Plant	order		11	6	time	delay	10	દ		52		က		8			2 to 20	દ	5		12		u
Plant	type		L,C	$\Gamma$ ,C	$\Gamma, C$		L,D	L,C		D,C		L,C		L,C			$\Gamma,C$	$_{ m L,C}$	L,C		NL,C		NL,C
	Problem #		90-01 Dis. Column	90-02 Boiler	90-03 Shell		90-04 Rolling Mill	90-05 Missile		90-06 High Order	Plant	90-07 Hydraulic	System	90-08 Underwater	Vehicle		90-09 Pendula	90-10 Ship Heading	90-11 Bus		90-12 Robotics		90-13 Robust

C = continuous time model D = discrete time model L = linear plant, NL = nonlinear plant,

### Acknowledgement

On behalf of the IFAC Community, I wish to give thanks to the following members of the IFAC Theory Committee:

J. Ackermann	Vice-Chairman
A. Benveniste	Vice-Chairman
Han-Fu Chen	Vice-Chairman
M. Grimble	Vice-Chairman
G. Goodwin	Vice-Chairman
Y. Tsypkin	Vice-Chairman

who carried out the difficult process of reviewing all submitted potential benchmark problems for the report, and to Linda Espeut for her outstanding work in organizing and typing of the report.

Edward J. Davison, Chairman IFAC Theory Committee 1987-1990

### Note of Disclaimer

IFAC bears no responsibility re the accuracy or validity of the enclosed Benchmark problems.

### Process Control

Problem #90-01 (Binary Distillation Column)

Problem #90-02 (Drum Boiler Problem)

Problem #90-03 (Shell Control Problem)

Problem #90-04 (A Cold Rolling Mill)

## Problem #90-01 BINARY DISTILLATION COLUMN

(A) General Description

has the feature that pressure variation is included in the model's description; the system is multivariable, with 3 inputs and 3 outputs, and includes one disturbance input. This problem describes a fairly realistic model of a binary distillation column, and

(B) Reference

The formulation of this problem is given in:

Davison, E.J., "Control of a distillation column with pressure variation", Trans. Is-nitute of Chemical Engineers, vol. 45, 1967, pp. T229-250.

(C) Problem Description
The equation of a binary distillation column with n plates for a general binary system of components is given in the above reference. The following linearized model is obtained from the above reference, for a column containing 8 plates:

$$\dot{x} = Ax + Bu + E\omega$$

$$y = Cx$$

$$y_m = x$$

$$t = \begin{pmatrix} u_1 \\ u_2 \\ u_3 \end{pmatrix}, y = \begin{pmatrix} y_1 \\ y_2 \\ y_3 \end{pmatrix}, \omega = \omega_1, \text{ where:}$$

 $x_{10} = \text{composition of more volatile component in reboiler}$ pressure x11 =

 $x_1 = \text{composition of more volatile component in condenser}$ 

 $x_2 = \text{composition of more volatile component in plate # 1}$ 

composition of more volatile component in bottom product = composition of more volatile component in plate #8 y, = E3

 $y_2 = \text{composition of more volatile component in top product}$   $y_3 = \text{pressure}$ 




Figure 1: Binary distillation column with pressure variation

Columns 1 through 6

1.5000e-02 2.0200e-02 2.0200e-02 0	1.0000e-02 0 0 0 0 0 0 0 0	
1.1000e-02 -3.1200e-02 -3.1200e-02 2.0200e-02 0	5.0000e-04 2.0000e-04 0 0 2.0000e-04 5.0000e-04 1.8500e-02 1.0	100
6.3000e-03 -1.5800e-02 9.5000e-03 0	4.2000e-02 -4.8300e-02 5.5500e-02 -2.5500e-02	000
4.6000e-03 -1.4100e-03 9.5000e-03 0	2.50000e-03 5.0000e-03 5.0000e-03 5.0000e-03 5.0000e-03 5.0000e-03 5.0000e-03 5.0000e-03 5.0000e-03 5.0000e-03 5.0000e-03	000
4.3000e-03 -1.3800e-02 9.5000e-03 0 0 0 0 0 0	through 11  2 2.8000e-02 2 4.8200e-02 2 2.0200e-02 0	000
-1.4000e-03 9.5000e-03 0 0 0 0 0 0 0 0 0 0 2.5500e-02	Columns 7 th  0 0 2.2000e-02 2.0200e-02 2.0200e-02 2.0200e-02 0 5.0000e-06 1.0000e-06 1.0000e-05 4.6000e-05 4.6000e-05	0 6

- u<sub>1</sub> = reboiler steam temperature
- u<sub>2</sub> = condenser coolant temperature
- u<sub>3</sub> = controlled reflux
- ω<sub>1</sub> = change of input feed concentration
- ym = outputs of the system which can be measured

It is desired to design a controller to regulate the 3 outputs  $y_1$ ,  $y_2$ ,  $y_3$  against the unmeasurable disturbance  $\omega_1$  (and other unmeasurable disturbances), with as fast a settling time as possible, subject to the constraint:

$$\begin{vmatrix} u_1 & | \le 2.5 \\ u_2 & | \le 2.5 \\ u_3 & | \le 0.30 \end{vmatrix}, t \ge 0$$

for  $|\omega_1| \le 1$ ,  $t \ge 0$ . In this problem, the choice of what measurable outputs to use in the controller, is considered to be part of the problem statement; in general, a controller which uses the fewest number of output measurements is desirable.

## (D) Name of Person Submitting Problem

Dept. of Electrical Engineering University of Toronto

Toronto, Ontario, Canada M5S 1A4 Tel: (416) 978-6342

0

0

0

0

0

0

0

0

0

0

υ

Process

## Problem #90-02 DRUM BOILER PROBLEM

## (A) General Description

This problem describes a fairly realistic model of a drum boiler and has the feature of being multivariable, unstable, and non-minimum phase.

(B) Reference
The source of this problem is given in:
Chien, K.L., Ergin, E.I., Ling, C., Lee, A., "Dynamic analysis of a boiler", Trans.
ASME, vol. 80, 1958, pp. 1809-1819.

## (C) Problem Description

The following plant

$$\dot{x}=Ax+Bu+E\omega$$
  $y=Cx$   $y=Cx$  is a linearized model of a drum boiler where  $u=egin{pmatrix} u_1\\u_3\\u_3 \end{pmatrix}, \ y=egin{pmatrix} y_1\\y_2\\u_3 \end{pmatrix}, \ \omega=\omega_1, \ x\in R^9,$ 

density of output steam flow

where:

temperature of output steam flow

temperature of superheater

H £3

quality of steam I T water flow in riser 11 X.5

pressure II £6

temperature of riser H  $x_7$ 

temperature of water in boiler water level in boiler 11 Ħ 6 18

-1.0000e-02

|| [최

5.2000e+01

pressure II 5 water level in boiler 11

input fuel flow 1

4.0300e-05 -3.7700e-03 3.6000e-04 -1.0500e-01 -4.1400e-01 7.8600e-05 0 0 -3.3500e-06 -2.9100e+00 -1.0400e-04 -1.1100e-04 1.0000e-03 0 --2.5500e-01 -1.2600e+04 -3.5600e+01 -1.2700e+00 00 00 2.3400e-03 0 0 3.0300e+00 -5.9600e-02 0 0 0000000 3.950e-2 0 2.840e-3 0 -1.2800e+01 -1.0000e-10 -0 00 -3.0500e+00 7.8700e-02 -5.2000e-05 1.7300e+01 1.8000e+01 0 0 0 -5.1300e-06 -1.5000e+00 1.7800e+00 4.3100e+01 5.6900e+01 6.0200e-03 -2.4500e-02 2.9400e-05 -3.1500e-03 -2.2000e+00 -1.7700e-03 1.9400e-04 -7.1700e-02 00 Columns 1 through 6 Columns 7 through 9 00 3.6800e+02 2.7400e+01 -6.4700e-02 3.8500e+03 2.2400e+04 1.2700e+01 9.0000e+01 000 8.2800e+00 00 6.3300e-05 1.4900e-03 -3.9300e+00 1.5600e+00 2.3300e+00 -2.0300e-01 00 00 (1 er ø ပ




Figure 1: Drum Boiler System

 $u_2 = input$  water flow

u<sub>3</sub> = temperature of input water flow

ω<sub>1</sub> = output steam flow disturbance

It is desired to design a controller to regulate the outputs of the system against constant disturbance  $\omega_1$ , and to track constant setpoints  $y^{rd} \in R^2$  with as fast a settling time as possible. Note: the input  $u_3$  is generally not used in the 'conventional control' of such a boiler.

## (D) Name of Person Submitting Problem

E.J. Davison

University of Toronto Toronto, Ontario, Canada M5S 1A4 Dept. of Electrical Engineering

Tel: (416) 978-6342

5

## Problem #90-03 SHELL CONTROL PROBLEM

## (A) General Description

This problem describes a representative example of a practical control problem arising in process control.

(B) Reference
The formulation of this problem is given in:
Pratt, D.M., Morari, M., Shell Process Control Workshop, Buttersworth: Stoneham,

## (C) Problem Description

Figure 1 shows a heavy oil fractionator with three product draws and three side circulating loops. The heat requirement of the column enters with the feed, which is by economics and operating requirements. There is no product specification for the of the column. The three circulating loops remove heat to achieve the desired product Therefore, they have varying heat duty requirements. The bottom loop has an enthalpy duty can be used as a manipulated variable to control the column. The heat duties of a gaseous stream. Product specifications for the top and side draws are determined bottom draw, but there is an operating constraint on the temperature in the lower part separation. The heat exchangers in these loops reboil columns in other parts of the plant. controller which regulates heat removal in the loop by adjusting steam make. Its heat the other two loops act as disturbances to the column.

The relevant information regarding the Shell Control Problem is stated in these five

- 1. Control Objectives
- 2. Control Constraints
- 3. Process Model
- 4. Uncertainties in the Gains of the Model
- 5. Prototype Test Cases




Figure 1: Diagram of a heavy oil fractionator (Shell control problem)

We have tried to encapsulate the relevant control issues in this one problem while staying as realistic as possible. The problem is stated such that an infinite number of scenarios can occur in controlling the unit. We would encourage the development of solution methodologies that are flexible enough to deal with varying (and possibly conflicting) problem requirements, and can be readily automated such that control designs can be carried out by plant personnel with only a modest knowledge of control concepts.

A complete solution to the problem should describe, in detail, the analysis and synthesis procedures that indicate that the proposed controller satisfies the control objectives for all the plants in the uncertainty set. However, because of possible discrepancies between investigators on analysis techniques, we have formulated a number of prototype test cases which form a common frame of reference for evaluating different designs.

### Control Objectives

- 1. Maintain the top and side draw product end points at specification (0.0  $\pm$  0.005 at steady state).
- Maximize steam make in the steam generators (i.e., maximize heat removal) in the bottom circulating reflux. (Important note: heat duties are expressed in terms of heat input to the column. Decreasing heat duty implies increasing the amount of heat removed.)
- 3. Reject the unmeasured disturbances entering the column from the upper and intermediate refluxes due to change in heat duty requirements from other columns. (Upper and intermediate reflux duties range between -0.5 and 0.5.) Reject disturbances even when one or both end point analyzers fail.
- Keep the closed-loop speed of response between 0.8 and 1.25 of the open-loop process bandwidth.

### Control Constraints

- 1. All draws must be within hard maximum and minimum bounds of 0.5 and -0.5.
- 2. The bottom reflux heat duty is constrained within the hard bounds of 0.5 and -0.5.
- All manipulated variables have maximum move size limitations of magnitude 0.05 per minute.
- 4. Fastest sampling time is 1 minute.

- 5. The bottom reflux draw temperature has a minimum value of -0.5.
- The top endpoint must be maintained within the maximum and minimum values of 0.5 and -0.5.

## Process Model (First Order Deadtime)

 $\frac{Ke^{-\theta s}}{\tau s+1}$ 

	_					
		u,	$u_2$	u3	3	ŝ
		TOP	SIDE	BOTTOMS	INTER	UPPER
_		DRAW	DRAW	REFLUX	REFLUX	REFLUX
_				DUTY	DUTY	DUTY
	TOP	K = 4.05	K = 1.77	K = 5.88	K = 1.20	K = 1.44
Ŋ.	END	$\tau = 50$	$\tau = 60$	$\tau = 50$	$\tau = 45$	$\tau = 40$
_	POINT	$\theta = 27$	$\theta = 28$	$\theta = 27$	$\theta = 27$	$\theta = 27$
_	SIDE	K = 5.39	K = 5.72	K = 6.90	K = 1.52	K = 1.83
372	END	7 = 50	$\tau = 60$	7 = 40	$\tau = 25$	$\tau = 20$
_	POINT	$\theta = 18$	$\theta = 14$	$\theta = 15$	$\theta = 15$	$\theta = 15$
	TOP	K = 3.66	K = 1.65	K = 5.53	K = 1.16	K = 1.27
2,1	TEMP	7 = 9	$\tau = 30$	7 = 40	$\tau = 11$	$\tau = 6$
		$\theta = 2$	$\theta = 20$	$\theta = 2$	$0 = \theta$	$\theta = 0$
	UPPER	K = 5.92	K = 2.54	K = 8.10	K = 1.73	K = 1.79
23	REFLUX	$\tau = 12$	$\tau = 27$	$\tau = 20$	7 = 5	r = 19
_	TEMP	$\theta = 11$	$\theta = 12$	$\theta = 2$	$0 = \theta$	$\theta = 0$
	SIDE	K = 4.13	K = 2.38	K = 6.23	K = 1.31	K = 1.26
22	DRAW	ء = د 8 = د	r = 19	$\tau = 10$	$\tau = 2$	$\tau = 22$
	TEMP	$\theta = 5$	$L = \theta$	$\theta = 2$	$\theta = 0$	$\theta = 0$
	INTER	K = 4.06	K = 4.18	K = 6.53	K = 1.19	K = 1.17
24	REFLUX	$\tau = 13$	$\tau = 33$	۲ = 9	$\tau = 19$	$\tau = 24$
	TEMP	$\theta = 8$	$\theta = 4$	$\theta = 1$	$\theta = 0$	$\theta = 0$
	BOTTOMS	K = 4.38	K = 4.42	K = 7.20	K = 1.14	K = 1.26
\$2	REFLUX	r = 33	$\tau = 44$	$\tau = 19$	$\tau = 27$	$\tau = 32$
-	TEMP	$\theta = 20$	$\theta = 22$	$\theta = 0$	$\theta = 0$	$\theta = 0$

## Uncertainties in the Gains of the Model

	l		۰ ا	T	· · · · · ·	I	<u> </u>
UPPER REFLUX DUTY	1.44 + 0.16ε5	1.83 + 0.13£ <sub>5</sub>	1.27 + 0.08¢s	1.79 + 0.04es	$1.26 \pm 0.02\varepsilon_{8}$	1.17 + 0.01ε5	1.26 + 0.18£s
INTER REFLUX DUTY	1.20 + 0.12£4	1.52 + 0.13£4	1.16 + 0.0864	$1.73 + 0.02\varepsilon_4$	1.31 + 0.03£4	1.19 + 0.08£4	1.14 + 0.18£4
BOTTOMS REFLUX DUTY	5.88 + 0.59£3	6.90 + 0.89£₃	5.53 + 0.67£3	$8.10 \pm 0.32\varepsilon_3$	$6.23 + 0.30\epsilon_3$	6.53 + 0.72c3	7.20 + 1.33€3
SIDE DRAW	$1.77 + 0.39\varepsilon_2$	5.72 + 0.57e2	$1.65 \pm 0.35\varepsilon_2$	$2.54 + 0.24\epsilon_2$	$2.38 \pm 0.93\epsilon_2$	4.18 + 0.35e2	4.42 + 0.73ε2
TOP	$4.05 + 2.11\epsilon_1$	$5.39 + 3.29\varepsilon_1$	3.66 + 2.29e <sub>1</sub>	$5.92 + 2.34\epsilon_1$	$4.13 + 1.71\varepsilon_1$	4.06 + 2.39£ı	4.38 + 3.11¢ <sub>1</sub>
	TOP END POINT	SIDE END POINT	TOP TEMP	UPPER REFLUX TEMP	SIDE DRAW TEMP	INTER REFLUX TEMP	BOTTOMS REFLUX TEMP

 $-1 \le \varepsilon_i \le 1; \quad i = 1, 2, 3, 4, 5$ 

### Prototype Test Cases

Demonstrate, through simulation, that the proposed controller satisfies the control objectives without violating the control constraints for the following plants within the uncertainty set (assume all inputs and outputs are initially at zero; magnitudes for the upper and intermediate reflux duty step changes are indicated below):

1.  $\varepsilon_1 = \varepsilon_2 = \varepsilon_3 = \varepsilon_4 = \varepsilon_5 = 0$ . Upper reflux duty = 0.5, intermediate reflux duty = 0.5.

2.  $\varepsilon_1 = \varepsilon_2 = \varepsilon_3 = -1$ ;  $\varepsilon_4 = \varepsilon_5 = 1$ . Upper reflux duty = -0.5, intermediate reflux duty = -0.5.

3.  $\varepsilon_1 = \varepsilon_3 = \varepsilon_4 = \varepsilon_5 = 1$ ,  $\varepsilon_2 = -1$ . Upper reflux duty = -0.5, intermediate reflux duty = -0.5.

4.  $\varepsilon_1=\varepsilon_2=\varepsilon_3=\varepsilon_4=\varepsilon_5=1$ . Upper reflux duty = 0.5, intermediate reflux duty = -0.5.

5.  $\epsilon_1=-1$ ,  $\epsilon_2=1$ ,  $\epsilon_3=\epsilon_4=\epsilon_5=0$ . Upper reflux duty = -0.5, intermediate reflux duty = -0.5.

(D) Name of Person Submitting Problem

J.C. Kantor
Dept. of Chemical Engineering
University of Notre Dame
Notre Dame, Indiana 46556
U.S.A.
Tel: (239) 558-5581

Process

## Problem #90-04 A COLD ROLLING MILL

## (A) General Description

This problem deals with a two-stand cold rolling mill. The process dynamics are dominated by the interstand time delay. A discrete 10<sup>th</sup> order model is given. The model includes disturbances, is multivariable and strongly interacting. The controller structure and controller parameters are to be found to meet realistic design specifications.

### (B) Reference

A full description of the model is given in Smith, H.W., "Dynamic Control of a Two-Stand Cold Mill", Automatica, 5, 2, pp. 109-115, 1969, where a continuous approximation to the time delay is used. The numerical model given here has not been published previously.

## (C) Problem Description


### ntroduction


We consider in this problem a two-stand cold rolling mill, which processes cold metal strip, previously rolled hot, to reduce it to final thickness and to produce the final surface finish. The process is an interesting one for the control engineer, as it is multivariable (3 inputs, three outputs), strongly interacting, subject to constant disturbances (1 potentially measurable, 2 unmeasurable), and strongly constrained in both state and input

variables. The process is shown diagramatically in Figure 1.

The strip enters the mill with thickness h, at velocity v. In the first stand, the rolls, which are positioned by a screwdown drive (position s<sub>1</sub>), exert a force F<sub>1</sub> on the strip, which deforms it plastically so that the strip exits with the thickness h<sub>0,1</sub> at velocity v. The strip is rolled with a steady-state tensile stress t in the interstand section. This tension can be altered by a transient change in the peripheral speed of stand 2 from its steady-state value, (v<sub>d</sub>), which is a third control input. The existence of rolling tension strongly couples the two stands. The input thickness h, varies as a result of imperfections in the hot-rolling process which feeds it; a particular problem is caused by welds joining two hot-rolled strips to allow continuous cold processing, which cause step disturbances. This disturbance is potentially measurable. A major determinant of rolling force is the coefficient of friction between rolls and strip; this is never precisely known, varies with

lubrication and roll surface condition, and is different between the two stands. The two coefficients  $(\mu_1$  and  $\mu_2)$  are treated as constant disturbances which cannot be measured.





### Modelling the Process

### Il forces

The rolling force, torque, and neutral plane thickness are calculated by integrating the forces and relative roll-strip velocities across the roll gap. The neutral plane, at which roll and strip have the same velocity, plays an important role in the calculation and knowledge of the thickness at this point is needed for dynamic modelling. The output variables, in our case F and h, as we are assuming infinitely stiff roll drives and are not interested in torque, are given by

$$F = f(h_i, h_o, t_i, t_o, \mu)$$
  
$$h_n = h(h_i, h_o, t_i, t_o, \mu)$$

We will use a model linearized about the operating point, and will assume the mill input tension and the mill output tension are independently regulated and constant. Each variable is normalized to a deviation from its steady-state value; these variables will be indicated by hats, e.g.  $\hat{F}$ ,  $\hat{h}$  and so on.

Screw position and mill stretch

The output thickness from a stand is controlled by its screw position 3, but the stand housings deflect under the very large forces used, so that roll force also influences output thickness:

$$h_o = \frac{F}{M} + s$$

Note that screw motion has been defined as positive upward. M is the modulus of elasticity of the housing (unit force/unit deflection).

Continuity of mass flow

Continuity demands that for each roll gap

$$v_i h_i = v_n h_n = v_o h_o$$

which, when linearized, provides additional relations which must be satisfied.

Dynamic relationships

Finally, we have two dynamic relationships which must be satisfied. The strip leaving the first stand enters the second stand T seconds later, where T is the travel time between stands. It follows that

$$h_{i,2}(t)=h_{o,1}(t-T)$$

In addition, if the two stands have differing velocities, the interstand strip will have a strain rate  $(v_{i,2}-v_{o,1})/L$ , and thus tensile stress will be given by

$$\dot{t} = \frac{E}{L}(v_{i,2} - v_{o,2})$$

We combine all these relationships, after linearizing about the operating point, to get a dynamic model. The model is a greatly simplified one, as we have assumed ideal drives (no dynamics), have taken them as infinitely stiff, and have assumed external tensions to be perfectly regulated. It is adequate, however, for preliminary investigations of mill control.

### The Working Model

Model simplification and discretization

In using the above basic equations to formulate a working model, it is found that the tension time constant is quite short (15 ms) compared to the interstand time delay. Although the drives have been idealized, it is also impossible, with the forces available, to accelerate the large roll masses in such a short time. The tension time constant has therefore been ignored. The dominant dynamics are thus a 1-second time delay. The mill will be computer-controlled, and the model is accordingly discretized with a sampling interval of 0.1 seconds (determined by the characteristics of the X-ray thickness gauges used) and the drive velocity input commands are assumed constant over this interval.

Model matrices

The system is of the form

$$x_{n+1} = Ax_n + Bu_n + Ee_n$$
  
 $y_n = Cx_n + Du_n + Fe_n$ 

where x is the  $10 \times 1$  state vector, u is the  $3 \times 1$  control vector, and e is the  $3 \times 1$  disturbance vector.

The state vector

$$x'(n) = (\hat{h}_{o,1}(n), \dots, \hat{h}_{o,1}(n-9))$$

The control vector is made up of the three normalized velocity commands

$$\mathbf{u}'(n) = (s_1(n), s_2(n), v_d(n))$$

The output vector

$$y'(n) = (\hat{h}_{o,1}(n), \hat{h}_{o}, \hat{t}(n), \hat{F}_{1}(n), \hat{F}_{2})$$

The disturbance vector

$$e'(n) = (\hat{h}_i(n), \hat{\mu}_1(n), \hat{\mu}_2(n))$$

All the variables except u are normalized. The variables s<sub>1</sub> and s<sub>2</sub> have units of 0.001 in: b<sub>4</sub> is normalized. The saturation limits are actually on the velocities rather than the controls themselves, that is,

$$\dot{u}'_{max} = (.018in/sec,.07/sec)$$

The numerical values for the matrices are given in Table 1.

### Control Objectives

Outputs to be regulated

There are five possible outputs to be regulated; since only three are possible with three controls, we must make a choice. Two are obvious. The output thickness must be regulated, since this is the specified product. The tensile stress in the strip must also be constrained for

		0																				1	MAIKLA F	0 0	-0.0250		0.3470	-0.0120			
	0	0	0	0	0																	•	HAL		0.0025	-0.3220	0.44	0.0020			
	0	0	0	0	0																										
	0	0	0	0	0					0.8940	-16.9300	0.0700	0.3980			c	-0.5420	68,7000	-0.2850	-0.2460			000	0001.0			, ,	0	0	0	0
through 7	0	0	0	0	0			Columns 8 through 10	0		0	0	0			c							0		0	0	0	0	0	0	0
Columns 1 through 7	1.0000	0	0	0 (	0			Columns 8	0	0	0	0	0	NATOTAN		o		Ñ				MATRIX E	0.7130	0	0	0	0	0	0	0	0
		¢	~ ·	•	<b>,</b> c	, 0	0	0	1.0000	0	0																				
		ď	<b>&gt;</b>	0 0	• •		0	1.0000	0	0	0																				
		c	•	<b>,</b>		0	1.0000	0	0	0	0																				
		c	•	0	0	1.0000	0	0	0	0	0																				
		<	<b>,</b>		1.0000	0	0	0	0	0	0		0.1120	00			0	0	0	0	0				-0.4600	0	0	0	٥	0	0
	4	/ ugnozum T ruzongn /	· c	1.0000	0	0	0	0	0	0	0	Columns 8 through 10	0	00			0	٥	0	0	1.0000				-1.3500	0	0	0	0	0	0
			1.0000	0	0	0	0	0	0	0	o '	lumns 8	0	00	c	0	٥	0	0	1.0000	0		MATRIX B		2.7600	0	0	0	0	0	0

safety reasons (the strip may not be allowed to go slack or break) and an easy way to constrain it is to regulate it. The best third choice is not so obvious. We could choose either the interstand thickness or some linear combination of the two forces.

### Performance desired

We shall adapt as our test input a step disturbance  $\hat{h}_i = 0.1$  occurring at t = 0. For this input, we wish to;

- 1. minimize the total length of the strip for which  $|\hat{h}_o| > 0.04$
- 2. ensure that  $|\hat{t}| < 1$  throughout the transient, and minimize its maximum value if possible subject to the output thickness specification
- 3. not saturate any drive at any point in the transient
- 4. minimize, but not necessarily regulate, the steady-state value of  $\hat{F}_2$ .

## (D) Name of Person Submitting Problem

Professor H.W. Smith Department of Electrical Engineering University of Toronto Toronto, Ontario, Canada M5S 1A4 Tel: (416) 978-5341 FAX: (416) 978-7423

### Aero-Control

Problem #90-05 (Control of Missile Autopilot) Problem #90-06 (Lower Order Controller Design for a High Order Plant)

Aero

## Problem #90-05 CONTROL OF MISSILE AUTOPILOT

(A) General Description

It is desired to control the vertical acceleration of a rigid guided missile over different operating conditions. The missile is open loop stable, but has insufficient damping and is non-mininum phase.

(B) Reference

For the source of this problem contact U. Hartmann.

(C) Problem Description

The behaviour of a rigid body guided missile may be described as follows:

 $\dot{x} = Ax + bu$ 

e = y-yref

where  $x \in \mathbb{R}^3$ ,  $u \in \mathbb{R}^1$ ,  $y \in \mathbb{R}^1$ ,  $e \in \mathbb{R}^1$  are given as follows:

u = elevator command (radians)

 $y = \text{vertical acceleration } (\text{m/sec}^2) (a_t \text{ in Figure 1})$ 

 $x_1 = \text{pitch rate (radians/sec) } (\Delta q \text{ in Figure 1)}$ 

 $x_3 = \text{elevator deflection angle (radians)} (\Delta \eta \text{ in Figure 1})$  $x_2 = \text{angle of attack (radians) } (\Delta \alpha \text{ in Figure 1)}$ 

 $e = \text{error between output and desired set point } y_{ref}$ 

It is desired to find a controller to control the vertical acceleration y subject to the following constraints:

(a) For a set point change in  $y_{ref}$ , the % overshoot in  $y \le 10\%$  and the steady-state error  $\le 5\%$ . The bandwidth of the closed loop system  $\le 10$  Hz. (b) The elevator deflection angle  $x_3$  should be limited to  $||x_3|| \le 20^\circ$ . The elevator deflection angle rate  $\dot{x}_3$  should be limited to  $||\dot{x}_3|| \le 600^\circ/\text{sec}$ .

(c) The above control specifications are to be satisfied for 10 given flight operating conditions (which depend on much number, altitude and mass of the vehicle).

In this vehicle, the pitch rate  $x_1$  can be measured and used for purposes of control.




Figure 1: Notation used to describe vehicle.

The data for this problem is given as follows:

$$A = \begin{pmatrix} a_{11} & a_{12} & b_1 \\ 1 & a_{22} & b_2 \\ 0 & 0 & -190 \end{pmatrix}, \quad b = \begin{pmatrix} 0 \\ 0 \\ 190 \end{pmatrix}$$

where  $a_{11}$ ,  $a_{12}$ ,  $a_{23}$ ,  $b_1$ ,  $b_2$ ,  $c_{11}$ ,  $c_{12}$ ,  $d_1$  are given as follows for 10 different operating conditions (see Table 1).

Table 1

altitude			ш 0					12000 m		İ
mach	0	8.	Ţ	9	2.5	2	0	65	0	0.4
number										:
411	-0.327	0.391	-0.688	-0.738	-0.886	-1.364	-0.333	-0.337	-0.369	-0.402
als	-63.94	-130.29	-619.27	-651.57	-1068.85	-92.82	-163.24	-224.03	-253.71	.277 2
422	-1.0	-1.42	-2.27	-2.75	-3.38	-4.68	-0.666	-0.663	-0.80	-0.884
ę,	-155.96	-186.5	-552.9	-604.18	-1004.39	-128.46	-153.32	-228.72	-249.87	-419.35
ę,	-0.237	-0.337	-0.429	-0.532	-0.582	-0.087	-0.124	-0.112	-0.135	-0.166
CJ1	0.326	0.35	0.65	99.0	0.79	1.36	0.298	0.319	0.33	0.36
C12	-208.5	-272.38	-651.11	-913.64	-1926.45	-184.26	-247.75	-375.75	-500.59	-796.18
d <sub>1</sub>	90.93	22.06	283.44	250.5	402.96	76.43	63.77	117.4	103.76	178.59

(D) Name of Persons Submitting Problem

Dr. Ing. U. Ilartmann Bodenseewerk Gerätetechnik GmbH Postfach 101155 7770 Uberlingen Germany Tel: 07551-89/6105

Dipl. Ing. G. Grebing Bodenseewerk Gerätetechnik GmbH Postfach 101155 7770 Uberlingen Germany Tel: 07551-89/6168

### Aero

## Problem #90-08 LOWER ORDER CONTROLLER DESIGN FOR A HIGH ORDER PLANT

## (A) Motivation for the Problem

industry is provided. The open-loop plant model possesses key features that render the application plant (typical of most industrial problems). In this case, a design example from the aircraft of conventional design techniques difficult, if not impossible, in achieving the specified design The motivation for the problem is to provide a uniform testbed for the evaluation of different approaches and algorithms in design of low-order linear feedback controllers for a high-order requirements. They are:

- (i) High dynamic order (55th-order);
- (ii) Multivariable system with two inputs and two outputs;
- (iii) Open-loop instability (i.e., Flutter mode);
- (iv) Numerous highly oscillatory modes (i.e., lightly damped structural modes);
- (v) Nonminimum-phase characteristics.

design philosophy and related details on final design performance can be found in reference [1] and [2]. Additional results on controller reduction applied to this problem can be found in reference [3]. that was used in a research study of active control technology [1] where a linear-quadraticgaussian (LQG)-based design has been developed for flutter control and gust load alleviation. The resulting  $55^{th}$ -order controller has been subsequently reduced to a  $10^{th}$ -order controller for practical implementation using a standard modal residualization technique. Description of the (B) Brief Description of Problem Origin This plant is an aeroelastic model for a modified Boeing B-767 airplane, at a flutter condition,

(C) Problem Description
The problem is to synthesize a linear feedback control law of low order (preferably less than

- (i) Stabilizes the flutter mode with damping of at least 0.015;
- (ii) Provides minimal damping of 0.4 to the remaining low-frequency modes;
- (iii) Reduces the mean-square responses of aircrast dynamic load variables to turbulence;

(iv) Possesses desirable robustness in terms of phase and gain margins at each control loop.

The following are a set of design requirements for the benchmark problem:

- (i) Minimum damping of 0.015 for the flutter mode identified by its frequency near  $\omega \approx 20$ rad/sec (e.g., flutter mode damping achieved by the LQG controller in references [1] and [2] is 0.074);
- Minimum damping of 0.40 for the remaining low-frequency modes (e.g., aircraft shortperiod mode, compensator modes, etc.);  $\equiv$
- (iii) Adequate attenuation of aircrast dynamic load responses to a 10st/sec rms turbulence wi (e.g., comparable with those achieved by the LQG controller in references [1] and [2]);
- (iv) Moderate control activities based on mean-square responses of control deflections and their rates to a 10ft/sec turbulence  $w_1(t)$  (i.e., comparable with results in references [1] and [2]);
- (v) Adequate phase and gain margins:
- Gain margin of ± 6 dB
- Phase margin of ±45°

in the elevator and aileron control lops. Stability margins are evaluated one-loop-at-a-time using classical single-loop analysis).

[2] meets the above design objectives). The LQG controller design in references [1] and [2] was obtained from the following quadratic cost function with process and sensor noise characteristics order controller (for example, using a previously designed LQG controller of references [1] and The linear feedback control system could be designed directly, or from the reduction of a highfor the plant model described in Appendix I.

· Design cost function: The cost function is of the form:

$$J = \int_0^\infty \left[ Q_1 y_1^2(t) + Q_2 y_2^2(t) + Q_3 y_3^2(t) + R_1 u_1^2(t) + R_2 u_2^2(t) \right] dt$$

The following output variables  $y_i$  (i=1,2,3) have been penalized in the cost function with weighting factors  $Q_i$  (i = 1, 2, 3):

Weighting Factor Q;	$3.76 \times 10^{-14}$	$1.20 \times 10^{-13}$	$2.45 \times 10^{-12}$
Output Variables y,	(1) Inboard bending moment (BMOMI)	(2) Inboard torsion (TORI)	(3) Outboard torsion (TORO)

along with the input variables  $u_i$  and their weighting factors  $R_i$  (i=1,2):

Input Variable u, Weighting Factor R, (1) Elevator control (ELEVC) 3.647 × 10<sup>2</sup> (2) Aileron control (AILC) 1.459 × 10<sup>1</sup>

Process and sensor noise characteristics: A Kalman filter was designed using the measurement of aircraft pitch rate QCG and wing-tip acceleration WTIPDD. The process noises  $w_i$  (i = 1, 2, 3) have input distribution matrix  $B_n$  and spectral densities  $W_i$  (i = 1, 2, 3):

Process Noise w; Spectral Density W; (1) Vertical gust (WG) 2.8224 × 10<sup>4</sup> (in/sec)<sup>2</sup>/rad/sec) (2) Elevator input noise (ELEVN) 2.742 × 10<sup>-5</sup>(rad/sec) (3) Aileron input noise (AILN) 6.854 × 10<sup>-4</sup>(rad/sec)

The sensor noises  $v_i$  (i = 1, 2) for the above two measurements have the following spectral densities:

Fig.1 Closed-loop system structure with a full order controller

Appendix I shows the resulting gain matrices F and L of the regulator and Kalman filter design respectively, using the above design parameters. Figure 1 shows a block diagram of the closed-loop system constructed with a full-order LQG controller where the matrices A, B, C,  $B_n$ ,  $C_p$ , F and L are given in Appendix I.

For convenience, design evaluation of the above full-order LQG controller, a  $10^{th}$ -order (reduced) controller [1,2] and a  $5^{th}$ -order controller [3] are given in Table 1.

Table 1 I non Evaluation for Dull (10G Design) and Reduced Order Conte

Closed-Loop Evaluation for Pull (LQG Design) and Reduced Order Controllers	in) and Re	duced Order (	Controllers
Controller Order	55 <sup>th</sup> [2]	104 [2]	544[3,LCFW]
Flutter Mode Damping	0.074	0.070	0.0501
Inboard Wing Station:			
Bending Moment (×10 <sup>5</sup> in-lbs)	2.348	2.349	2.624
Shear (Ibs)	854.	861.	950.
Torsion (×10⁴ in-lbs)	4.437	4.597	4.969
Outboard Wing Station:			
Bending Moment (×105 in Ibs)	0.259	0.262	0.239
Shear (Ibs)	259.	260.	286.
Torsion (×104 in-lbs)	1.196	1.206	1.274
Control Surface Activities:			
Elevator Control Deflection (rad)	0.00054	0.00056	0.000339
Elevator Control Surface Rate (rad/sec)	0.00407	0.00436	0.00401
Aileron Control Deflection (rad)	0.00158	0.00163	0.00176
Aileron Control Surface Rate (rad/sec)	0.0275	0.0276	0.0332
Stability Margins:*			
Elevator Control Loop: Gain Margin (dB)	15.9	36.4	18.2
Phase Margin (deg)	180	180	102
Aileron Control Loop: Gain Margin (dB)	74	25	(-15,14.4)
Phase Margin (deg) 58.6	58.6	(-138.9,146)	(-140,82.3)

<sup>†</sup> Root-Mean-Square (rms) to a 10ft/sec vertical Dryden turbulence [by injecting white-noise at the input w<sub>1</sub>(t) with a power spectral density of

(10ft/sec)2(rad/sec)].

\* Frequency range considered is  $0.01 \le w \le 100 \text{ rad/sec.}$ 

## (D) Previous Results Obtained

Discussion of the aircraft aeroelastic model and design in the LQG Controller can be found in the following references:

- Ly, U.-L. and D. Gangsaas, "Application of Modified Linear Quadratic Guassian Design to Active Control of a Transport Airplane", AIAA, Guidance and Control Conference, Boulder, Colorado, August 1979.
- Ly, U.-L., D. Gangsaas and D.C. Norman, "Practical Gust Load Aleviation and Flutter Suppression Control Laws Based on an LQG Methodology", AIAA, Aerospace Sciences Meeting, 1981.

A discussion of some controller reduction methods used on the full order LQG designed controller to generate lower order controllers appears in the following:

3. Liu, Y., B.D.O. Anderson, U.-L. Ly, "Coprime Factorization Controller Reduction with Bezout Identity Induced Prequency Weighting", Automatica, to appear.

## (E) Name of Persons Submitting the Problem

Prof. B.D.O. Anderson
Dept. of Systems Engineering
Research School of Physical Sciences
Australian National University
C.P.O. Box, 4, ACT 2601, Australia
Tel: 062-492461 (International + 61-62-492461)
Fax: 062-491884 (International + 61-62-491884)
Telex: +107-19236

Dept. of Aeronautics and Astronautics
The University of Washington
Seattle, WA 98155, USA
Tel: (2005) 543-6670
Tels: (2005) 543-9285
Telex: 4740096
Data files for the model state matrices can be obtained directly from Dr. Ly through

electronic mail via Arpanet.

Mr. Yi Liu
CSIRO, Division of Mineral and Process Engineering
Lucas Heights Research Laboratories
Private Mail Bag 7
Menai, NSW 2234, Australia
Tel: 02-5433459 (International + 61-2-5433459)
Fax: 02-6434434 (International + 61-2-5434434)
Telex: A73341

### Appendix I Plant Model State Matrices

Aeroelastic model of a modified B767-aircraft at a flutter condition is a linear state model of

$$\dot{x}(t) = Ax(t) + Bu(t) + B_n w(t)$$

where

- z(t) is a state vector (of dimension 55) containing the aircraft rigid and aeroelastic modes, actuator modes, Dryden turbulence filter and other noise shaping filters;
- u(t) is a control vector (of dimension 2) containing the elevator control ELEVC and the alleron control AILC;
- w(t) is a process noise input vector (of dimension 3) containing the vertical turbulence input  $w_1(t)$ , the elevator noise input  $w_2(t)$  and the alleron noise input  $w_3(t)$ .

The sensor output  $y(t) = [QCG WTIPDD]^T$  consists of the aircraft pitch rate QCG and the wing-tip acceleration WTIPDD variables and is given by

$$y(t) = Cx(t) + v(t)$$

The performance output variables

 $y_N(t) = [SHRI,BMOMI,TORI,SHRO,BMOMO,TORO,ELD,EL,AILOD,AILO]^T$ 

ven by

 $y_N(t) = C_p x(t)$ 

represent those outputs to be used in the covariance analysis of the aircraft subjected to a vertical turbulence of 10ft/sec rms. They represent the dynamic loads of the aircraft at the inboard and outboard wing stations, the elevator and aileron control deflections and rates respectively, i.e.,

Bending moment at the inboard wing station (in-lbs) Bending moment at the outboard wing station (lbs) Shear force at the outboard wing station (lbs) Torsion at the outboard wing station (in-lbs) Shear force at the inboard wing station (lbs) Torsion at the inboard wing station (in-lbs) Elevator control surface deflection (rad) Aileron control surface deflection (rad) Elevator control surface rate (rad/sec) Aileron control surface rate (rad/sec) вмомо: BMOMI: AILOD: FORI: SHRO: roro: AILO: ELD:

A closed-loop system with a full-order LQG controller is shown in Figure 1. State matrices A, B,  $B_n$ , C and  $C_p$  along with the full-state feedback gain matrix F and the Kalman gain matrix L corresponding to the LQG controller in [1,2] are shown below.

Dr. U.-L. Ly

	HT.									
	X1	X2	х3	X4	x5	X6	X7	х8	х9	X10
-	0.1015	-19.77	0.0000E+00	0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00	0.0000E+00	0.0000E+00	0.00002+00
X1	19.77	0.1015	0.000000+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X2	0.0000E+00	0.0000E+00	-2.3202E-02		0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.00000+00
х3	0.0000E+00	0.0000E+00		-2.3202E-02	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X4		0.0000E+00	0.0000E+00		-0.3165	-14.33	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X5	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	14.33	-0.3165	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X6	0.00008+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00		-0.3892	-22.29	0.0000E+00	0.0000E+00
X7	0.0000E+00		0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	22.29	-0.3892	0.0000E+00	0.0000E+00
X8	0.00000+00	0.000000	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	-0.9883	-36.16
X9	0.00000+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	36.16	-0.9883
X10	0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X11	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X1.2	00+30000.0	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X13	0.0000E+00	0.000000+00	0.0000E+00	0.0000E+00	0.00000+00	0.0000E+00	0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00
X14	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X15	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.00008+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X1.6	0.0000E+00	0.0000E+00		0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00	0.0000E+00
X17	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00	0.0000E+00	0.00002+00
X18	0.0000E+00	0.0000E+00	0.0000E+00		0.0000E+00	0.0000000000000000000000000000000000000	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X1.9	0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X20	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00		0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X21	0.00002+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00		0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00
X22	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X23	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00	0.00002+00
X24	0.0000E+00	0.0000E+00	0.0000£+00	0.0000E+00	0.0000E+00	0.000000+00	0.0000E+00	0.0000E+00	0.0000E+00	0.000000+00
X25	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.00000000	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X26	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00		0.0000E+00	0.0000E+00	0.0000E+00
X27	0.0000E+00	0.000000+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
x28	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
X29	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.00002+00	0.0000£+00
X30	0.00002+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000£+00	0.0000E+00	0.000000000	0.0000E+00	0.0000E+00	0.0000E+00
x31	0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00	0.0000E+00	0.000000+00		0.0000E+00	0.0000E+00	0.0000E+00
X32	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00		0.0000E+00		0.0000E+00	0.0000E+00	0.0000E+00
X33	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00		0.0000E+00		0.0000E+00		0.0000E+00
x34	0.00000+300	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00			0.0000E+00		0.00002+00
X35	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00		0.0000E+00				0.0000E+00
x36	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.00002100	0.00000100

X37 X38 X39 X40 X41 X42 X43 X44 X45 ELEVD ELEVD ELEVDD AILD AILD AILD WIND1 WIND1 WIND2 ENOISE ANOISE	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00	0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.000E+00 0.000E+00 0.000E+00 0.000E+00 0.000E+00 0.000E+00 0.000E+00 0.000E+00 0.000E+00 0.000E+00 0.000E+00 0.000E+00 0.000E+00 0.000E+00 0.000E+00 0.000E+00 0.000E+00	0.0000E+00 0.000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00
	X11	X12	X13	X14	X15	X16	X17	X18	X19	X20
X1 X2 X3 X4 X5 X6 X7 X8 X9 X10 X11 X12 X13 X14 X15 X16	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 -1.342 2.547 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 -2.547 -1.342 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 2.312 21.51 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 -21.51 -2.312 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00
X17 X18 X19 X20	0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00	63.79 0.0000E+00	-2.796 0.0000E+00 0.0000E+00	0.0000E+00 -3.332 56.37	0.0000E+00 -56.37 -3.332

```
X21
X22
X23
                            0.0000E+00
0.0000E+00
               0.0000E+00
                                           0.0000E+00
                                                        0.0000E+00
                                                                     0.0000E+00
                                                                                   0.0000E+00
                                                                                                 0.0000E+00
                                                                                                               0.0000E+00
                                                                                                                            0.0000E+00
                                                                                                                                          0.00008+0
                 0000E+00
                                            0000E+00
                                                                                                               0.0000E+00
0.0000E+00
                                                        0.0000E+00
                                                                      0.0000E+00
                                                                                   0.0000E+00
                                                                                                 0.0000E+00
                                                                                                                              .0000E+00
                                                                                                                                          0.0000E+0
                 .0000E+00
                              000000+00
                                           Ô
                                            0000E+00
                                                        0.0000E+00
                                                                      0.0000E+00
                                                                                     .0000E+00
                                                                                                   .0000E+00
                                                                                                                             0
                                                                                                                              .0000E+00
                                                                                                                                          0.00006+0
x24
                 00006+00
                               0000E+00
                                            0000E+00
                                                        0.0000E+00
                                                                      0.0000E+00
                                                                                   0.0000E+00
                                                                                                 Ω
                                                                                                   00000E+00
                                                                                                               0.00000+00
                                                                                                                               00002+00
                 0000E+00
                            n
                              000000+00
                                           n
                                            00005+00
                                                          .0000E+00
                                                                        0000E+00
                                                                                     0000E+00
                                                                                                   0000E+00
                                                                                                                 .0000E+00
                                                                                                                               0000E+00
                                                                                                                                          0.0000E + 0
X26
                 0000E+00
                               0000E+00
                                            0000E+00
                                                          .0000E+00
                                                                      0.0000E+00
                                                                                   0.0000E+00
                                                                                                   0000E+00
                                                                                                               0.0000E+00
                                                                                                                               0000E+00
                                                                                                                                           .0000E+C
X27
X28
                 0000E+00
                              0000E+00
                                           n
                                            00005+00
                                                          0000E+00
                                                                      0.0000E+00
                                                                                     0000E+00
                                                                                                   0000E+00
                                                                                                                 0000E+00
                                                                                                                               0000E+00
                                                                                                                                          0.0000E+C
               ۵
                 0000E+00
                              0000E+00
                                            0000E+00
                                                          .0000E+00
                                                                      0.0000E+00
                                                                                     .0000E+00
                                                                                                   0000E+00
                                                                                                               0.00000 \pm 00
                                                                                                                              00005400
                                                                                                                                           .0000E+0
X29
X30
                 .0000E+00
                            0.0000E+00
                                                                                     .0000E+00
                                                                                                   .0000E+00
                                           0.00002+00
                                                          00005+00
                                                                      0.0000E+00
                                                                                                                 0000E+00
                                                                                                                               0000E+00
                                                                                                                                           .0000E+0
               0.0000E+00
                            ñ
                              00005+00
                                            0000E+00
                                                          00002+00
                                                                      0.00002:00
                                                                                                               0.0000E+00
                                                                                                                              000000+00
                                                                                                                                           0000E+0
X31
                 0000E+00
                              0000E+00
                                            0000E+00
                                                                                                              0.0000E+00
0.0000E+00
                                                          0000E+00
                                                                     Ó
                                                                       0000E+00
                                                                                   ñ
                                                                                     0000E+00
                                                                                                   00006+00
                                                                                                                               00002+00
                                                                                                                                           .0000E+0
X32
               0.0000E+00
                            ñ
                              0000E+00
                                            0000E+00
                                                          0000E+00
                                                                      0.0000E+00
                                                                                     .0000E+00
                                                                                                   0000E+00
                                                                                                                              0000E+00
                                                                                                                                           000000+0
X33
                .0000E+00
                              0000E+00
                                            0000E+00
                                                          0000E+00
                                                                     0.00000 \pm 0.0
                                                                                   0.00006+00
                                                                                                   0000000
                                                                                                               0.0000E+00
                                                                                                                               000002+00
                                                                                                                                           0000E+0
X34
               0.0000E+00
                            0
                              0000E+00
                                          0.0000E+00
                                                          0000E+00
                                                                       0000E+00
                                                                                                   .0000E+00
                                                                                     0000E+00
                                                                                                               0.0000E+00
                                                                                                                            0.0000E+00
                                                                                                                                           0000E+0
X3S
               0.0000E+00
                               0000E+00
                                            0000E+00
                                                          00002+00
                                                                     0.0000E+00
                                                                                     .0000E+00
                                                                                                 0.00005+00
                                                                                                               0.0000E+00
                                                                                                                              0000E+00
               0.0000E+00
                              0000E+00
                                          0.00000±+00
                                                          0000E+00
                                                                       0000E+00
                                                                                     0000E+00
                                                                                                                .0000E+00
                                                                                                  .000000+00
                                                                                                                              .0000E+00
                                                                                                                                           0000E+0
X37
               0 00002+00
                              0000E+00
                                            .0000E+00
                                                          0000E+00
                                                                                                                              0000E+00
                                                                     0.0000E+00
                                                                                     .0000E+00
                                                                                                 0.0000E+00
                                                                                                               D.0000E+00
                                                                                                                            ñ
                                                                                                                                           000002+0
X38
X39
               0.0000E+00
                              0000E+00
                                          0.00000 \pm 00
                                                          00005+00
                                                                       .0000E+00
                                                                                     .0000E+00
                                                                                                  .0000E+00
                                                                                                                 0000E+00
                                                                                                                              .0000E+00
                                                                                                                                           0000E+0
                                          0.0000E+00
0.0000E+00
               0.00000+00
                            0.0000E+00
                                                          0000E+00
                                                                                                                .0000E+00
                                                                                                                            0.0000E+00
                                                                                                                                           0000E+0
X40
                0000E+00
                              0000E+00
                                                                                                  .0000E+00
                                                                                                                .0000E+00
                                                          00008+00
                                                                     0.0000E+00
                                                                                     000002+00
                                                                                                 ñ
                                                                                                                              000000+00
                                                                                                                                          0.0000E+0
X41
                                          0.0000E+00
0.0000E+00
               0.0000E + 00
                            0.000000
                                                          000000000
                                                                       0000E+00
                                                                                     0000E+00
                                                                                                                              .0000E+00
                                                                                                                                         0.0000F+0
X42
               0.0000E+00
                              0000E+00
                                                          00002+00
                                                                     0.00008+00
                                                                                     0000E+00
                                                                                                 0.0000E+00
                                                                                                                0000E+00
                                                                                                                              .0000E+00
                                                                                                                                           0000E+0
               0.0000E+00
                            0.0000E + 00
                                          0.0000E \pm 0.0
                                                          0000E+00
                                                                       0000E+00
                                                                                     0000E+00
                                                                                                   0000E+00
                                                                                                                .0000E+00
                                                                                                                              .0000E+00
                                                                                                                                         0.0000E+0
X44
               0.0000E+00
                              0000E+00
                                            .0000E+00
                                                          0000E+00
                                                                                                                              .0000E+00
                                                                     0.0000E + 00
                                                                                     00005+00
                                                                                                 0.0000E+00
                                                                                                              Λ
                                                                                                                00005+00
                                                                                                                                           0+30000
X45
                .00002+00
                                                                     0.0000E+00
0.0000E+00
                              0000E+00
                                          0.00000+00
                                                          0000E+00
                                                                                     0000E+00
                                                                                                   0000E+00
                                                                                                                 0000E+00
                                                                                                                                         0.0000E+0
ELEV
                00008+00
                              0000E+00
                                            .0000E+00
                                                          0000E+00
                                                                                     .0000E+00
                                                                                                  .0000E+00
                                                                                                              0.00008+00
                                                                                                                            0.0000E+00
                                                                                                                                           .0000E+0
ELEVI
                 0000E+00
                            0.0000E+00
                                                                                                  .0000E+00
                                                                                                                .0000E+00
                                          0.0000E+00
                                                        0.0000E+00
                                                                     0.0000E+00
                                                                                     0000E+00
                                                                                                 ñ
                                                                                                                              0000E+00
                                                                                                                                         0.0000E+0
ELEVOD
                000000+00
                            0.000000
                                            .0000E+00
                                                          0000E+00
                                                                     0.0000E+00
                                                                                     0000E+00
                                                                                                                                         0.0000E+0
0.0000F+0
                                                                                                                            ٥
                                                                                                                              0000E+00
ATT.
                0000E+00
                              .0000E+00
                                          0.00002+00
                                                                                                  .0000E+00
                                                        0.00008+00
                                                                     0.0000E+00
                                                                                     00005+00
                                                                                                                0000E+00
AILD
                .0000E+00
                                          0.0000E+00
0.0000E+00
                            0.0000E+00
                                                          0000E+00
                                                                     0.0000E+00
                                                                                     0000E+00
                                                                                                                0000E+00
                                                                                                                              00002+00
                                                                                                                                         0.0000E+0
ATT.DD
                0000E+00
                              .0000E+00
                                                        0.0000E+00
                                                                     0.00000\pm00
                                                                                     00006+00
                                                                                                 n
                                                                                                  00005+00
                                                                                                                0000E+00
                                                                                                                              00430000
                                                                                                                                           0000E+0
               0.0000E+00
                            0.0000E+00
                                          0.00002+00
                                                         .0000E+00
                                                                       .0000E+00
                                                                                                  .0000E+00
                                                                                     0000E+00
                                                                                                              0.0000E+00
                                                                                                                            0.00008+00
                                                                                                                                         0.0000E + 0.000E
WIND2
              0.0000E+00
                              .0000E+00
                                          0.00000+00
                                                        0.0000E+00
                                                                     0.0000E+00
                                                                                  0.00008+00
                                                                                                0.00008+00
                                                                                                              0.0000E+00
                                                                                                                            0.0000E+00
                                                                                                                                         0.0000E+0
                0000E+00
                              .0000E+00
                                          0.00006+00
                                                        0.0000E+00
                                                                       .0000E+00
                                                                                     0000E+00
                                                                                                              0.0000E+00
                                                                                                                            0.0000E+00
                                                                                                                                         0.0000E+0
ANOISE
              0.0000E+00
                            0.0000E+00
                                          0.0000E+00
                                                        0.0000E+00
                                                                     0.0000E+00
                                                                                  0.0000E+00
                                                                                                 0.0000E+00
                                                                                                              0.0000E+00
                                                                                                                            0.0000E+00
                                                                                                                                         0.0000E+0
              X21
                            x22
                                          X23
                                                                     X25
                                                                                  X26
                                                                                                X27
                                                                                                              X28
                                                                                                                            X29
                                                                                                                                         x30
X1
X2
X3
X4
              0.0000E+00
                                                       0.0000E+00
0.0000E+00
                            0.0000E + 00
                                          0.0000E+00
                                                                       0000E+00
                                                                                  0.0000E+00
                                                                                                0.0000E+00
                                                                                                              0.0000E+00
                                                                                                                            0.00000+00
                                                                                                                                         0.0000E+00
              0.0000E+00
                              0000E+00
                                          0.0000E+00
                                                                     0.0000E+00
                                                                                  0.0000E+00
                                                                                                0.0000E+00
                                                                                                              0.0000E+00
                                                                                                                            0.00002+00
                                                                                                                                           0000E+00
               0.0000E+00
                              .0000E+00
                                          O
                                            0000E+00
                                                        n
                                                         .00000E+00
                                                                       .0000E+00
                                                                                    .0000E+00
                                                                                                  00002+00
                                                                                                                .0000E+00
                                                                                                                            0.0000E+C0
                                                                                                                                           .0000E+0(
              0.0000E+00
                            0.0000E+00
                                          0.0000E+00
                                                        0.0000E+00
                                                                     0.0000E+00
                                                                                  0.000000+00
                                                                                                0.0000E + 00
                                                                                                              0.0000E+00
                                                                                                                            0.0000E+00
```

```
X5
X6
X7
                  0000E+00
                                 .0000E+00
                                                0000E+00
                                                                                                       0.0000E+00
0.0000E+00
                                                            0.0000E+00
                                                                          0.0000E+00
                                                                                           .0000E+00
                                                                                                                        .0000E+00
                                                                                                                                    0.0000E+00
0.0000E+00
                                                                                                                                                   0.0000E+00
                  0000E+00
                                                            0.0000E+00
0.0000E+00
                                 0000E+00
                                                0000E+00
                                                                             0000E+00
                                                                                           0000E+00
                                                                                                                                                     00005+00
                  0000E+00
                                 0000E+00
                                                0000E+00
                                                                            .0000E+00
                                                                                           .0000E+00
                                                                                                       0.0000E+00
                                                                                                                      ñ
                                                                                                                        0000E+00
                                                                                                                                      .0000E+00
                                                                                                                                                     00+30000
                0.0000E+00
                               0.0000E + 00
                                                0000E+00
                                                            0.00005+00
                                                                            00005+00
                                                                                           0000E+00
                                                                                                                        0000E+00
                                                                                                          0000E+00
                                                                                                                                      .0000E+00
                                                                                                                                                   ٥
                                                                                                                                                     0000E+00
X9
                                 0000E+00
                0.00008+00
                                                0000E+00
                                                              0000E+00
                                                                            0000E+00
                                                                                           0000E+00
                                                                                                       n
                                                                                                         .0000E+00
                                                                                                                      ٥
                                                                                                                        0000E+00
                                                                                                                                     0.0000E+00
                                                                                                                                                     0000E+00
X10
X11
                                                                                          .0000E+00
                                                                                                         .0000E+00
                                                0000E+00
                                                              0000E+00
                                                                            000000+00
                                                                                                                        0000E+00
                                                                                                                                     0.0000E+00
                                                                                                                                                     00002+00
                                                            0.0000E+00
0.0000E+00
                0.0000E+00
                                 D000E+00
                                                0000E+00
                                                                            0000E+00
                                                                                                                        .0000E+00
                                                                                                                                    0.00005+00
                                                                                                                                                     0000E+00
X12
                0.0000E+00
                                 0000E+00
                                                0000E+00
                                                                                                                        .0000E+00
                                                                            .0000E+00
                                                                                         û
                                                                                          .0000E+00
                                                                                                       0.0000E+00
                                                                                                                      ñ
                                                                                                                                      .0000E+00
                                                                                                                                                     0000E+00
X13
X14
                0.0000E+00
                                                                            0000E+00
                                 .0000E+00
                                                00005+00
                                                            0.0000E+00
                                                                                           0000E+00
                                                                                                         .0000E+00
                                                                                                                                    0.0000E+00
                                                                                                                                                   0.00000 \pm 00
                0.0000E+00
0.0000E+00
                                 0000E+00
                                                0000E+00
                                                              00430000
                                                                                                                                      .0000E+00
                                                                                           00002+00
                                                                                                         .0000E+00
                                                                                                                      O
                                                                                                                        0000E+00
                                                                            00430000
00430000
                                                00000E+00
                                                              0000E+00
                                                                                           0000E+00
                                                                                                         0000E+00
                                                                                                                        0000E+00
                                                                                                                                                   0.0000E+00
X16
                                .0000E+00
                0.0000E+00
                                                0000E+00
                                                              0000E+00
                                                                                          .00000E+00
                                                                                                         .0000E+00
                                                                                                                      0.00000 \pm 0.000
                                                                                                                                      .0000E+00
                                                                                                                                                     0000E+00
X17
X18
                                                0000E+00
                                                              .0000E+00
                                                                            0000E+00
                                                                                           0000E+00
                                                                                                         0000E+00
                                                                                                                        0000E+00
                                                                                                                                      .0000E+00
                                                                                                                                                    .0000E+00
                                                              .0000E+00
                0.0000E+00
                              0.0000F+00
                                                0000E+00
                                                                            0000E+00
                                                                                           0000E+00
                                                                                                         .0000E+00
                                                                                                                                                  0.0000E+00
0.0000E+00
                                                                                                                        .0000E+00
                                                                                                                                    Ð
                                                                                                                                      .0000E+00
X19
                  .0000E+00
                                 0000E+00
                                                0000E+00
                                                                                                         .0000E+00
                                                                                                                      0.0000E+00
0.0000E+00
                                                                            0000E+00
                                                                                           00002+00
                                                                                                                                      0000E+00
X20
                0.0000E+00
                              0.0000E+00
                                               .0000E+00
                                                            0.0000E+00
0.0000E+00
                                                                            0000E+00
                                                                                           00002+00
                                                                                                                                    0.0000E+00
                                                                                                                                                  0.000000+00
X21
                -3.41R
                                                0000E+00
                                                                            0000E+00
                                                                                                                                      0000E+00
00430000
                                                                                           00000E+00
                                                                                                         00000F+00
                                                                                                                      0.0000E+00
                                                                                                                                                     0000E+00
X22
X23
X24
                88.67
0.0000E+00
                               -3.418
                                                                            0000E+00
                                             0.0000E+00
                                                            0.0000E+00
                                                                                           0000E+00
                                                                                                         0000E+00
                                                                                                                       .00000+00
                                                                                                                                                  0.0000E+00
                              0.0000E+00
0.0000E+00
                                                            -69.45
-4.441
                                                                                         0.0000E+00
                                                                                                       0
                                                                                                         .0000E+00
                                                                                                                      0.0000E+00
                                                                                                                                      00005+00
                                                                                                                                                  0.0000E+00
0.0000E+00
                  0000E+00
                                               69.45
                                                                                                         00002+00
0000E+00
                                                                            0000E+00
                                                                                         0.0000E+00
                                                                                                                      0.0000E+00
                                                                                                                                      0000E+00
X25
X26
X27
X28
X29
X30
X31
                0.0000E+00
                                .0000E+00
                                             0.0000E+00
0.0000E+00
                                                            0.0000E+00
0.0000E+00
                                                                                         53.39
                                                                                                                      0.0000E+00
                                                                                                                                      0000E+00
                                                                                                                                                    .0000E+00
                0.0000E+00
                                0000E+00
                                                                           53.39
                                                                                         5.108
                                                                                                       a
                                                                                                         0000E+00
                                                                                                                      0.0000E+00
                                                                                                                                      0000E+00
                                                                                                                                                     0000E+00
                                .0000E+00
                                                           0.0000E+00
0.0000E+00
                                                                            .0000E+00
                                             0.0000E+00
                                                                                          0000E+00
                                                                                                         5.199
                                                                                                                       50.64
                                                                                                                                      0000E+00
                                                                                                                                                    000000+00
                                .0000E+00
                0.0000E+00
                                                0000E+00
                                                                                        0.0000E+00
                                                                                                        50.64
                                                                                                                       -5.199
                                                                                                                                    0.0000E+00
                                                                                                                                                    0000E+00
                  0000E+00
                                               0000E+00
                                                                                        0.0000E+00
0.0000E+00
                                                                                                         0000E+00
                                                                                                                     0.0000E+00
0.0000E+00
                                                            0.0000E+00
                                                                            000000+00
                                                                                                                                      5.301
                                                                                                                                                  0.0000E+00
                0.0000E+00
                                .0000E+00
                                               .0000E+00
                                                           0.0000E+00
0.0000E+00
                                                                            0000E+00
                                                                                                                                    0.00000+00
                                                                                                                                                   5.670
                0.0000E+00
                                .0000E+00
                                                                                          .0000E+00
                                                                                                                     0.0000E+00
0.0000E+00
                                                                            0000E+00
                                                                                                         0000E+00
                                                                                                                                      .0000E+00
                                                                                                                                                    92.96
X32
                                .0000E+00
                                             ò
                                               0000E+00
                                                              0000E+00
                                                                            0000E+00
                                                                                                         0000E+00
                                                                                                                                    0.0000E+00
                                                                                                                                                  0.0000E+00
X33
X34
X35
                  0000E+00
                                0000E+00
                                               0000E+00
                                                            0.00002+00
                                                                            .0000E+00
                                                                                        0.0000E+00
                                                                                                         0000E+00
                                                                                                                       .0000E+00
                                                                                                                                      .0000E+00
                                                                                                                                                    .0000E+00
                 .0000E+00
                                0000E+00
                                             n
                                               0000E+00
                                                             .0000E+00
                                                                            0000E+00
                                                                                          .0000E+00
                                                                                                                      0.0000E+00
                                                                                                                                    0.00002+00
                                                                                                                                                    00006+00
               0.0000E+00
0.0000E+00
                                0000E+00
                                               0000E+00
                                                            0.0000E+00
                                                                                                                                    0.0000E+00
0.0000E+00
                                                                          0
                                                                            .0000E+00
                                                                                          .0000E+00
                                                                                                         0000E+00
                                                                                                                      0.00002+00
                                                                                                                                                    0000E+00
                                                           0.0000E+00
0.0000E+00
                                                                           .0000E+00
                                .00002+00
                                             ۵
                                               00005+00
                                                                                          0000E+00
                                                                                                         00002+00
                                                                                                                      0.0000E+00
                                                                                                                                                    0000E+00
X37
                0.0000E+00
                                 0000E+00
                                               0000E+00
                                                                                          0000E+00
                                                                                                                     0.0000E+00
0.0000E+00
                                                                                                         0000E+00
                                                                                                                                      .0000E+00
                                                                                                                                                    0000E+00
                0.0000E+00
                                .0000E+00
                                             ò
                                               0000E+00
                                                            0.0000E+00
                                                                            0000E+00
                                                                                          0000E+00
                                                                                                         0000E+00
                                                                                                                                      .0000E+00
                                                                                                                                                  O
                                                                                                                                                    .0000E+00
               0.0000E+00
0.0000E+00
X39
                                 0000E+00
                                               0000E+00
                                                            0.00002+00
                                                                            0000E+00
                                                                                                                       .0000E+00
                                                                                                                                      .0000E+00
                                                                                          .0000E+00
                                                                                                         0000E+00
                                                                                                                                                    0000E+00
                                                           0.0000E+00
0.0000E+00
                                0000E+00
                                             o
                                               00006+00
                                                                            0000E+00
                                                                                          0000E+00
                                                                                                         .0000E+00
                                                                                                                                                    00008+00
X41
               0.0000E+00
                                 0000E+00
                                               0000E+00
                                                                          0
                                                                            0000E+00
                                                                                          .0000E+00
                                                                                                         .0000E+00
                                                                                                                       .0000E+00
                                                                                                                                      00+30000.
00+30000.
                                                                                                                                                    0000E+00
X42
                0.0000E+00
                                                           0.0000E+00
0.0000E+00
                                                                           .0000E+00
                                0000E+00
                                               00005+00
                                                                                          00002+00
                                                                                                         .0000E+00
                                                                                                                                                    0000E+00
X43
               0.0000E+00
                                0000E+00
                                               0000E+00
                                                                          Û
                                                                                        0
                                                                                          .0000E+00
                                                                                                       0.0000E+00
                                                                                                                     o.
                                                                                                                       .0000E+00
                                                                                                                                      0000E+00
                                                                                                                                                    0000E+00
X44
X45
                0.0000E+00
                                00002+00
                                             0.00008+00
                                                           0.0000E+00
                                                                          Ď
                                                                            .0000E+00
                                                                                          0000E+00
                                                                                                         .0000E+00
                                                                                                                       0000E+00
                                                                                                                                      00002+00
                                                                                                                                                  0.0000E+00
                                             0.0000E+00
               0.00002+00
                                0000E+00
                                                              0000E+00
                                                                            0000E+00
                                                                                          .0000E+00
                                                                                                                                                    0000E+00
                                                                                        a
                                                                                                         .00002+00
                                                                                                                       0000E+00
                                                                                                                                      OCCUPANO.
ELEV
                0.0000E+00
                                00430000
                                                           0.0000E+00
                                                                          0.0000E+00
                                                                                        0.0000E+00
                                                                                                       0.0000E+00
                                                                                                                     0.0000E+00
                                                                                                                                      0000E+00
                                                                                                                                                  0.0000E+00
```

0.0000E+00 0.000E+00 0.000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.000E+00 0.000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00
VAT					0.00005+00	0 00005400	0.00008+00	0.0000E+00	0.0000E+00
0.000000+00								0.0000E+00	0.0000E+00
							0.000000+00	0.0000E+00	J.0000E+00
					0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
				0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.00002+00
			0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00		0.0000E+00
			0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00			0.0000E+00
		0.0000E+00	0.0000E+00	0.0000E+00					0.00002+00
	0.0000E+00	0.0000E+00							0.0000E+00 0.0000E+00
	0.0000E+00	0.0000E+00	0.0000E+00						0.0000E+00
0.0000E+00	0.0000E+00								0.0000E+00
0.0000E+00	0.0000E+00								0.0000E+00
0.0000E+00									0.0000E+00
0.0000E+00								0.0000E+00	0.0000E+00
								0.000000+00	0.00002+00
							0.0000E+00	0.0000E+00	0.0000E+00
							0.0000E+00	0.0000E+00	0.00002+00
					0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
				0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00		0.0000E+00
				0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00		0.0000E+00
			0.0000E+00	0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00		0.00002+00
			0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00		0.0000E+00
			0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00			0.0000E+00
			0.0000E+00	0.0000E+00	0.0000E+00				0.0000E+00
		0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00				0.00002+00
	0.0000E+00	0.0000E+00	0.000000+00	0.0000E+00	0.0000E+00				0.000002+00
	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00					0.0000E+00 0.0000E+00
	0.0000E+00	0.0000E+00	0.0000E+00	0.COOOE+00					0.0000E+00
-92.96	0.0000E+00	0.0000E+00	0.000000+00	0.0000E+00	0.00002+00	0.0000E+00	0.0000E+00	0.00002+00	0.00006.400
	0.0000E+00	0.0000E+00	0.00008+00	0.0000E+00	0.0000E+00   0.0	0.0000E+00	0.0000E+00	0.0000E+00	0.000E+00

X31 X32 X33 X34 X35 X36 X37 X38 X39 X40 X41 X42 X43 X44 X45 ELEV ELEVDD ALLL AILD MIND1 HIND2 ENOISE ANOISE	-5.670 0.000E+00	0.0000E+00 -6.197 40.00 0.0000E+00	0.0000E+00 -40.00 -6.197 0.0000E+00	0.0000E+00 0.0000E+00 -8.177 16.61 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 -16.61 -8.177 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 -139-1. -8.221 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.000E+00 0.000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00
	X41	X42	X43	X44	X45	ELEV	ELEVD	ELEVDD	AIL	AILD
X1 X2 X3 X4 X5 X6 X7 X8 X9 X10 X11 X12 X13	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00	-2.1697E+04	6.796 7.196 1.7334E-03 4.148E-03 -0.2690 0.4627 -1.835 0.1595 4.615 -3.752 0.5550 -3.138 61.46 -53.56	-0.1334 -0.1568 -4.3119E-05 -8.0848E-05 4.9694E-03 3.6978E-02 -2.0525E-03 -8.4286E-02 -1.1871E-02 -1.2727E-02 6.5016E-02 -1.286 1.121	-14292222. 119.0 -105.9 -146.8 196.0 175.1 9.616 -34.14 -222.7 -2014. 20143652. 2881.	18.03 -2.684 4.8611E-04 1.0274E-03 -0.7097 1.345 -1.082 0.6370 6.425 1.899 -5.0439E-02 -1.060 5.074 -26.77

X15 X16 X17 X18 X19 X20 X21 X22 X23 X24 X25 X26 X27 X28 X30 X31 X32 X33 X34 X35 X36 X37 X38 X39 X40 X41 X42 X43 X44 X45 ELEVD ELEVDD AILD AILD WIND1 WIND1 WIND2 ENOISE ANOISE	0.0000E+00 0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.000E+00 0.000E+00 0.000E+00 0.0000E+00	6583.  -2212.  6321,  1.3964E+04  2382.  -303.7  542.8  -527.1  2658.  2.5341E+04  6538.  4.2048E+04  210.6  0.0000E+00  994.2  769.2  4.2702E+04  -7.6982E+04  -288.8  -2237.  -1.6942E+04  1.2513E+04  5748.  -1.4657E+04  -4089.  9474.  0.0000E+00  0.0000E+00  0.0000E+00	-20.08 2.624 0.5789 -36.01 3.812 -36.45 -28.56 -59.43 -39.51 0.0000E+00 13.57 10.60 -120.7 140.6 -0.9428 8.455 94.43 68.02 -35.78 216.8 -258.1 309.0 37.30	0.0000E+00 0.0000E+00 0.0000E+00	902.6 11291258126749.11 4360. 3790. 2501470.4 0.0000E+00 828.4 810.0 -3077348.3 -1499657860.89 -29.37 -39.31 123.4 33.03 61.04 140.9 156.3 0.0000E+00	48.49 -12.93 -5.130 -15.59 -25.48 -1.623 4.399 -6.993 7.583 -4.347 -131.3 90.71 -17.39 -18.75 0.0000E+00 12.90 19.07 35.90 -38.56 0.9758 49.50 0.2221 0.4639 -0.6830 9.043 -2.040 2.311 2.627 3.098 0.0000E+00
--	--------------------------	---	---	---	--	--	--	--	--	--

	AILDD	WIND1	WIND2	ENOISE	ANOISE
X1 X2	-0.1517 -5.0292E-02	0.0000E+00		0.0000E+00	0.0000E+00
X3	-7.4279E-06			0.0000E+00	0.000000+00
X4	-1.1816E-05		5.3132E-03	0.0000E+00	0.00000+00
X5.	1.2317E-03		B.0111E-03	0.0000E+00	0.0000E+00
X6	-3.9645E-03		0.1066	0.0000E+00	0.0000E+00
X7	1.1391E-02		-0.4078	0.0000E+00	0.00000+00
X8	-2.8823E-03		0.1001	0.0000E+00	0.0000E+00
X9	-4.9071E-02		-0.1571	0.0000E+00	0.0000E+00
XIO	-1.5192E-02	0.0000E+00	-1.060	0.00002+00	0.0000E+G0
XII	1.0263E-03	0.0000E+00	0.4854	0.0000E+00	0.0000E+00
X12	1.1647E-02	0.0000E+00 0.0000E+00	-2.733	0.0000E+00	0.0000E+00
X1.3	-0.1277		2.067	0.0000E+00	0.0000E+00
X1.4	0.2540	0.0000E+00	3.001	0.0000E+00	0.0000E+00
X15	-0.3712	0.0000E+00	3.544	0.0000E+00	0.0000E+00
X16	1.0825E-02	0.0000E+00 0.0000E+00	-7.199	0.0000E+00	0.0000E+00
X1.7	2.01872-02	0.0000E+00	7.207	0.0000E+00	0.00002+00
X1.8	6.4588E-02	0.0000E+00	0.6186	0.0000E+00	0.0000E+00
X19	0.1072	0.0000E+00	1.076	0.0000E+00	0.0000E+00
X20	7.7575E-02		2.821	0.0000E+00	0.0000E+00
X21	-2.7240E-02		-0.7866	0.0000E+00	0.00008+00
X22	2.9297E-02	0.0000E+00	-0.1111	0.0000E+00	0.0000E+00
X23	-6.5626E-03		1.509	0.0000E+00	0.0000E+00
X24	-8.4969E-03	0.0000E+00	-0.3659	0.0000E+00	0.00002+00
X25	0.8394	0.00002+00	0.8635	0.0000E+00	0.0000E+00
X26	-0.3495	0.0000E+00	7.433 -15.36	0.00000+00	0.0000E+00
X27	0.1113	0.00002+00		0.0000E+00	0.00002+00
X28	0.1395		4.570 -0.2771	0.0000E+00	0.0000E+00
X29	0.0000E+00	0.00000+00	-1.251	0.00002+00	0.0000E+00
X30	-3.6967E-02		-0.5031	0.0000E+00	0.0000E+00
X31	-8.1012E-02		-0.3031 -0.4524	0.0000E+00	0.00002+00
X32	-0.2467	0.0000E+00	-0.4524 -1.592	0.00002+00	0.0000E+00
X33	0.1981	0.0000E+00		0.0000E+00	0.0000E+00
X34	-4.1943E-02	0.0000E+00	1.956 -5.981	0.0000E+00	0.0000E+00
X35	-0.4980		-10.88	0.0000E+00	0.0000E+00
X36	-1.1955E-02		-10.88	0.0000E+00	0.0000E+00
X37	-9.9611E-03			0.0000E+00	0.0000E+00
X38	7.8189E-03		0.1532 0.4254		0.0000E+00
X39	-8.7434E-02				0.0000E+00
X40	2.3536E-02				0.00002+00
			0.1033	00+30000.0	0.0000E+00

X41	-2.8729E-02	0.0000E+00	-2.007	0.0000E+00	0.0000E+00
X42	-1.8542E-02	0.0000E+00	0.1886	0.0000E+00	0.0000E+00
X43	-2.2171E-02	0.0000E+00	9.2049E-03	0.0000E+00	0.0000E+00
X44	0.0000E+00	0.0000E+00	-17.07	0.0000E+00	0.0000E+00
X45	0.0000E+00	0.0000E+00	-37.83	0.0000E+00	0.0000E+00
ELEV	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
ELEVD	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
ELEVDD	0.0000E+00	0.0000E+00	0.0000E+00	~1.6000E+07	0.0000E+00
AIL	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00
AILD	1.000	0.0000E+00	0.0000E+00	0.00002+00	0.0000E+00
AILDD	-1060.	0.0000E+00	0.0000E+00	0.0000E+00	-1.6000E+07
WIND1	0.0000E+00	0.0000E+00	-0.2668	0.0000E+00	0.0000E+00
WIND2	0.0000E+00	1.000	-1.033	0.0000E+00	0.0000E+00
ENOISE	0.0000E+00	0.0000E+00	0.0000E+00	-20.00	0.0000E+00
ANOISE	0.0000E+00	0.0000E+00	0.0000E+00	0.0000E+00	-20.00

	-	
_	ELEVC	AILC
Хl	0.0000E+00	0.0000E+00
X2	0.0000E+00	0.0000E+00
х3	0.0000E+00	0.0000E+00
X4	0.0000E+00	0.00000000
X5 X6	0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00
X7	0.0000E+00	0.0000E+00
X8	0.0000E+00	0.0000E+00
х9	0.0000E+00	0.0000E+00
X10	0.0000E+00	0.0000E+00
X11	0.0000E+00	0.0000E+00
X12	0.0000 3+00	0.0000E+00
X13 X14	0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00
X15	0.0000E+00	0.0000E+00
x16	0.0000E+00	0.0000000000000000000000000000000000000
X17	0.0000E+00	0.0000E+00
X18	0.0000E+00	0.0000E+00
X19	0.0000E+00	0.0000E+00
X20	0.0000E+00	0.00000.0
X21 X22	0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00
X22 X23	0.0000E+00	0.0000E+00
X24	0.0000E+00	0.0000E+00
X25	0.0000E+00	0.0000E+00
X26	0.0000E+00	0.0000E+00
X27	0.0000E+00	0.0000E+00
X28	0.0000E+00	0.00000+00
X29 X30	0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00
X31	0.0000E+00	0.0000E+00
X32	0.0000E+00	0.0000E+00
X33	0.00002+00	0.0000E+00
X34	0.0000E+00	0.0000E+00
X35	0.00002+00	0.0000E+00
X36	0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00
X37 X38	0.0000E+00	0.0000E+00
x39	0.0000E+00	0.0000E+00
X40	0.00002+00	0.0000E+00
X41	0.0000E+00	0.0000E+00
X42	0.0000E+00	0.0000E+00
X43	0.0000E+00	0.00000+00
X44	0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00
X45 ELEV	0.0000E+00	0.0000E+00
ELEVD	0.0000E+00	0.0000E+00
ELEVDD	8.0000E+05	0.0000E+00
AIL	0.0000E+00	0.0000E+00
AILD	0.0000E+00	0.000000+00
AILDD	0.0000E+00	8.0000E+05
WIND1	0.0000E+00 0.0000E+00	0.0000E+00
WIND2 ENOISE	0.0000E+00	0.0000E+00
ANOISE	0.0000E+00	0.0000E+00

+ +9+ +

	w <sub>1</sub>	w <sub>2</sub>	w <sub>3</sub>
X1	0.0000E+00	0.0000E+00	0.0000E+00
X2	0.0000E+00	0.0000E+00	0.0000E+00
X3	0.0000E+00	0.0000E+00	0.0000E+00
X4	0.0000E+00	0.0000E+00	0.0000E+00
X5	0.0000E+00	0.0000E+00	0.0000E+00
X6 X7	0.0000E+00	0.0000E+00	0.0000E+00
X7 X8	0.0000E+00	0.0000E+00	0.0000E+00
X9	0.0000E+00 0.0000E+00	0.0000E+00	0.0000E+00
X10	0.0000E+00	0.0000E+00 0.0000E+00	0.0000E+00
X11	0.0000E+00	0.0000E+00	0.0000E+00 0.0000E+00
X12	0.0000E+00	0.0000E+00	0.0000E+00
X13	0.0000E+00	0.0000E+00	0.0000E+00
X14	0.0000E+00	0.0000E+00	0.0000E+00
X15	0.0000E+00	0.0000E+00	0.0000E+00
X16	0.0000E+00	0.0000E+00	0.0000E+00
X17	0.0000E+00	0.0000E+00	0.0000E+00
X18	0.0000E+00	0.0000E+00	0.0000E+00
X19 X20	0.0000E+00	0.0000E+00	0.0000E+00
X21	0.0000E+00	0.0000E+00	0.0000E+00
X22	0.0000E+00	0.0000E+00	0.0000E+00
X23	0.0000E+00 0.0000E+00	0.0000E+00	0.0000E+00
X24	0.0000E+00	0.0000E+00 0.0000E+00	0.0000E+00
X25	0.0000E+00	0.0000E+00	0.0000E+00
X26	0.0000E+00	0.0000E+00	0.0000E+00 0.0000E+00
X27	0.0000E+00	0.0000E+00	0.0000E+00
X28	0.0000E+00	0.0000E+00	0.0000E+00
X29	0.0000E+00	0.0000E+00	0.0000E+00
X30	0.0000E+00	0.0000E+00	0.0000E+00
X31	0.0000E+00	0.0000E+00	0.0000E+00
X32	0.0000E+00	0.0000E+00	0.0000E+00
X33	0.0000E+00	0.0000E+00	0.0000E+00
X34	0.0000E+00	0.0000E+00	0.0000E+00
X35 X36	0.0000E+00	0.0000E+00	0.0000E+00
X37	0.0000E+00	0.0000E+00	0.0000E+00
X38	0.0000E+00 0.0000E+00	0.0000E+00	0.0000E+00
X39	0.0000E+00	0.0000E+00 0.0000E+00	0.0000E+00
X40	0.0000E+00	0.0000E+00	0.0000E+00 0.0000E+00
X41	0.0000E+00	0.0000E+00	
X42	0.0000E+00	0.0000E+00	0.0000E+00 0.0000E+00
X43	0.0000E+00	0.0000E+00	0.0000E+00
X44	0.0000E+00	0.0000E+00	0.0000E+00
X45	0.0000E+00	0.0000E+00	0.0000E+00
ELEV	0.0000E+00	0.0000E+00	0.0000E+00
ELEVD	0.0000E+00	0.0000E+00	0.0000E+00
ELEVDD	0.0000E+00	0.0000E+05	0.0000E+00
AIL	0.0000E+00	0.0000E+00	0.0000E+00
AILD	0.0000E+00	0.0000E+00	0.0000E+00
AILDD WINDl	0.00002+00	0.0000E+00	8.0000E+05
WIND1 WIND2	0.3713 1.2450	0.0000E+00	0.0000E+00
ENOISE	0.0000E+00	0.0000E+00 1.0000	0.0000E+00
ANOISE	0.0000E+00	0.0000E+00	0.0000E+00 1.0000
	J. 00002+00	U. UUUUE+UU	1.0000

	X1	X2	х3	X4	x5	х6	х7	<b>x</b> 8	х9	X10
QCG WTIPDD	4.4247E-05 35.92	4.3403E-05 -12.46	4.9713E-05 -0.5332	4.5556E-05 -0.5659	-4.1311E-06 -0.9664	7.9201E-06 12.75	7.2496E-06 -21.45	-6.7385E-05 6.822	-1.8236E-04 33.88	2.0657E-05 17.00
	X11	X12	X13	X1.4	X15	X16	X17	X18	X19	X20
QCG WTIPDD	1.3194E-04 -0.1380	-1.5849E-04 -0.8803	-6.7655E-05 5.465	-8.7358E-06 -1.614	-9.8119E-05 55.18	3.1119E-05 30.10	-5.7479E-05 -4.878	3.1600E-04 14.36	-5.7750E-04 62.54	7.1000E-04 55.18
	X21	X22	X23	X24	x25	X26	X27	X28	X29	X30
QCG WTIPDD	-9.6843E-05 -138.8	2.9934E-05 -104.4	5.4014E-04 6.831	-4.7620E-04 -11.78	-4.1630E-06 -55.04	-2.1609E-04 -30.66	-1.0541E-04 1.402	-3.1883E-05 -30.33	-1.5062E-04 4.869	-2.7714E-04 -74.28
	X31	X32	x33	X34	X35	x36	X37	X38	х39	X40
QCG WTIPDD	-2.4361E-04 74.14	2.7990E-05 16.30	-1.6592E-04 3.118	1.2748E-05 8.728	-2.0762E-05 -74.53	-1.2546E-04 1.460	-4.4360E-05 -3.334	-1.0147E-05 -7.367	1.5343E-04 -1.032	2.1956E-05 2.867
	X41	X42	X43	X44	X45	ELEV	ELEVD	ELEVDD	AIL	AILD
QCG WTIPDD	~2.9386E-05 6.583	6.5513E-05 -1.361	6.1813E-05 1.350	1.9995E-05 10.71	8.9674E-06 -25.91	0.0000E+00 48.52	0.0000E+00 -7.932		0.0000E+00 -2.5618E+04	0.0000E+00 -167.4
	AILDD	WIND1	WIND2	ENOISE	ANOISE					
QCG WTIPDD	0.0000E+00 0.2213	0.0000E+00 0.0000E+00	0.0000E+00 1.880	0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00					

- C <sub>D</sub> =	_									
	x1	X2	х3	X4	X5	Х6	х7	X8	х9	X10
SHRI BMOMI TORI SHRO BMOMO TORO ELD EL AILOD AILO	-280.4 -1.0116E+04 -3.5918E+04 -1.008 86163685. 0.0000E+00 0.0000E+00 0.0000E+00		54.94 1.9756E+04 1444. 22.26 1146. 546.4 0.0000E+00 0.0000E+00 0.0000E+00	64.24 2.1545E+04 2675. 24.73 1214. 605.9 0.0000E+00 0.0000E+00 0.0000E+00	151.2 1.3993E+04 1.6733E+04 5.633 -870.0 71.67 0.0000E+00 0.0000E+00 0.0000E+00	93.86 1.7694E+04 7989. 17.59 3613. -1539. 0.0000E+00 0.0000E+00 0.0000E+00	159.9 -2984. 3.4725E+04 6.685 -3028. 2550. 0.0000E+00 0.0000E+00 0.0000E+00	-1.131 1084. -599.8 0.0000E+00 0.0000E+00 0.0000E+00	-118.0 -1.7279E+04 3528. -17.83 8362. 2060. 0.0000E+00 0.0000E+00 0.0000E+00	-29.86 1314. 9170. -4.323 5560. 1803. 0.0000E+00 0.0000E+00 0.0000E+00
	X11	X12	X13	X14	X15	X16	X17	X18	X19	X20
SHRI BMOMI TORI SHRO BMOMO TORO ELD EL AILOD AILO	102.8 3.2923E+04 3849. 37.01 1935. 786.8 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	101.8 3.3817E+04 3825. 38.72 2152. 911.5 0.0000E+00 0.0000E+00 0.0000E+00	6.202 -1082. -3369. -4.403 830.2 -899.7 0.0000E+00 0.0000E+00 0.0000E+00	-19.80 3076. -1.0423E+04 -3.027 -882.3 -540.4 0.0000E+00 0.0000E+00 0.0000E+00	-204.1 -3.8871E+04 -4762. -27.42 1.1555E+04 -1427. 0.0000E+00 0.0000E+00 0.0000E+00		38.07 -7038. -0.8833 -13.45 660.9 -693.1 0.0000E+00 0.0000E+00 0.0000E+00	17.06 1.1182E+04 4619. 2.659 2046. 3405. 0.0000E+00 0.0000E+00 0.0000E+00	237.5 8002. 3448. -49.80 8408. 1955. 0.0000E+00 0.0000E+00 0.0000E+00	253.3 1.0350E+04 1303. -48.30 7455. 530.8 0.0000E+00 0.0000E+00 0.0000E+00
	X21	X22	X23	X24	X25	X26	X27	X28	X29	х30
SHRI BMOMI TORI SHRO BMOMO TORO ELD EL AILOD AILO	7.799 -5.7674E+04 -1.6288E+04 -37.52 -60121239. 0.0000E+00 0.0000E+00 0.0000E+00	97.62 -5.8520E+04 917.4 -36.55 -5724. -1711. 0.0000E+00 0.0000E+00 0.0000E+00	-29.15 -9678. -6520. 3.951 -3113. -5337. 0.0000E+00 0.0000E+00 0.0000E+00	5.759 -1.7572E+04 -4420. -4.938 -2967. -5925. 0.0000E+00 0.0000E+00 0.0000E+00	-33.32 -4136. 1.3953E+04 6.345 1288. 7784. 0.0000E+00 0.0000E+00 0.0000E+00	-7.012 -493.0 1.0935E+04 5.479 583.2 6242. 0.0000E+00 0.0000E+00 0.0000E+00	-103.5 152.7 -1.2971E+04 25.88 -6625. -8377. 0.0000E+00 0.0000E+00 0.0000E+00	-139.6 -2391. 2265. 34.74 -5544. -2130. 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	-159.0 -5.4007E+04 -6697. -62.23 -2987. -2052. 0.0000E+00 0.0000E+00 0.0000E+00	-326.0 1,4065E+04 -6.6463E+04 -10.69 2461. 8424. 0.0000E+00 0.0000E+00 0.0000E+00

	x31	x32	x33	X34	x35	X36	X37	х38	X39	X40
SHRI BMOMI TORI SHRO BMOMO TORO ELD EL AILOD AILO	287.0 -1.8204E+04 5.9803E+04 10.05 -3217. -8033. 0.0000E+00 0.0000E+00 0.0000E+00	159.6 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	324.2 -1013. 0.0000E+00 0.0000E+00 0.0000E+00	7562. -4374. 0.0000E+00 0.0000E+00 0.0000E+00	2.4890E+04 28.73 -1.2172E+04 9713. 0.0000E+00 0.0000E+00 0.0000E+00	-1.189 95.83 137.6 0.2784 9.422 -41.64 0.0000E+00 0.0000E+00 0.0000E+00	1.220 -530.3 -1595. -1.598 -27.31 -7.796 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	1.539 -423.9 -2912. -2.559 0.5400 20.11 0.0000E+00 0.0000E+00 0.0000E+00	0.8601 -80.47 -203.6 -0.3003 -0.7739 25.14 0.0000E+00 0.0000E+00 0.0000E+00	3.222 580.5 2433. 1.781 14.79 56.85 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00
	X41	X42	X43		X45	ELEV	ELEVD	ELEVDD	AIL	AILD
SHRI BMOMI TORI SHRO BMOMO TORO ELD EL AILOD	6.416 667.4 3134. 2.065 5.506	0.6052 -20.59 -170.6	-0.5647 28.40 202.4 0.2183 2.610 1.493 0.0000E+00 0.0000E+00 0.0000E+00	-97.82 -3.2517E+04 -1.4519E+04 -35.76 1184. -7454. 0.0000E+00 0.0000E+00 0.0000E+00	-1.384 -1345. -691.2 -1.258	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 1.000 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 1.000 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 1.000 0.0000E+00
	AILDD	WIND1	WIND2	ENOISE	ANOISE					
SHRI BMOMI TORI SHRO BMOMO TORO ELD EL AILOD AILO	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00	0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00 0.0000E+00					

F										
R 24 - F. P. & W stands	X1	X2	х3	X4	X5	х6	<b>x</b> 7	X8	х9	X10
ELEVC	1.5832E-04 3.0315E-03	-2.3582E-04 2.6654E-03	1.1387E-04 4.1081E-04	1.8312E-04 7.8271E-04	-4.1426E-05 1.4589E-04	4.8678E-05 -8.5377E-04	2.6735E-04 -1.2540E-03	1.7564E-04 4.6786E-04	-9.1525E-06 1.3813E-06	-1.9235E-0 -6.7161E-0
	Xll	X12	X13	X14	X15	X16	X17	X18	X19	x20
LEVC	2.1995E-04 9.5182E-04	-4.5889E-05 3.5894E-04	-1.7184E-06 6.2767E-05	-4.3851E-05 3.7742E-04	-8.0336E-05 -9.2428E-05	-2.5128E-05 6.5354E-04	-6.4003E-06 4.6382E-05	9.7488E-06 -2.8777E-04	-2.4859E-06 -1.6007E-04	1.1835E-0 -1.7710E-0
	X21	X22	X23	X24	X25	X26	X27	X28	X29	ж30
	-3.6349E-06 2.4929E-04	7.3601E-06	-1.4385E-05	-8.0966E-06	-2.9199E-05	7.3229E-06	2.0059E-05	1.94552-06	-5.0617E-05	-1.4932E-0
		x32						х38		
ELEVC	2.9402E-05 5.0017E-04	6.3263E-06	2.3606E-06	-7.1657E-05	1.0550E-05	-2.3694E-08	6.8456E-08	1.2641E-08	3.0596E-10	4.0774E-0
	X41	X42						ELEVDD		AILD
LEVC	-2.9662E-07 6.4990E-06	9.0481E-10	-5.4855E-10	3.9594E-06	1.6946E-09	-0.4132	-6.8441E-03		-2.1111E-02	
		WIND1		ENOISE	ANOISE					
LLEVC	-2.8063E-07 -2.0544E-05	8.0010E-05	1.0842E-04	3.541	0.1928					

	_	
	QCG	WTIPDD
X1	1785.	2.272
X2	3319.	2.6873E-02
X3	70.88	2.3472E-02
X4	554.4	2.5272E-02
X5	-689.6	-0.2266
X6	-43.74	0.1884
X7	-39.38 -108.3	-9.2332E-02 4.5919E-02
X8 X9	-105.6	0.2794
X10	777.9	0.2092
X11	1.8692E+04	4.8515E-02
X12	-9112.	-1.195
X13	2483.	-0.3082
X14	8.407	-2.693
X15	3332.	4.719
X16	6892.	0.1216
X17	189.0	0.1776
X18	-14.07	-0.3136
X19 X20	-698.0 960.5	-0.6674 -0.7365
X21	90.55	0.2265
X22	-6.130	9.7791E-02
X23	306.2	0.1553
X24	44.03	5.8746E-02
X25	-2799.	-5.226
X26	634.2	0.6398
X27	1756.	-1.150
X28	3578. 3122.	-0.9081 0.3963
X29 X30	13.31	-2.7236E-02
X31	-30.99	0.1238
X32	6683.	1.259
X33	-8069.	-0.6234
X34	-7828.	0.6847
X35	8314.	4.343
X36	86.05	1.0999E-02
X37	-20.95	9.2423E-02
X38 X39	43.47 82.23	-9.7774E-02 5.1789E-02
X40	-296.3	-0.2155
X41	60.50	1.2172E-02
X42	-20.62	-9.3657E-03
X43	18.70	4.0876E-04
X44	7830.	3.815
X45	2354.	1.587
ELEV	0.8878	-4.1163E-06
ELEVD	11.43 380.9	-1.2973E-03 1.298
ELEVDD AIL	-3.558	1.2771E-03
AILD	-98.84	-0.5599
AILDD	1.7817E+04	40.63
WIND1	-4600.	-2.597
WIND2	-1.3619E+04	-8.357
ENOISE	-3.9461E-02	3.3987E-08
ANOISE	-0.3878	-3.7938E-04

### Servo-Control

Problem #90-07 (Hydraulic Positioning System)
Problem #90-08 (Control Surface Servo Problem for an Underwater Vehicle)

Servo

## Problem #80-07 HYDRAULIC POSITIONING SYSTEM

### (A) General Description

It is desired to control the carriage position of a hydraulic positioning system under different loading conditions, for a linear plant model which is subject to large uncertainty.

### (B) Reference

- (a) Gu Qi-tai, "A Robust Regulator for a llydraulic Positioning System", Technische Hogeschool Twente Memorandum, no. 339.
- (b) Baumgartner, H., "Die Nachlaufgenauigkeit des Hydraulischen Zylinderantriebes im Maschinenbau", Diss. ETH 5963, Zürich 1977
- (c) Senning, M., "Robuste Regelung Ilydraulischer Vorschubantriebe", Vortrag Seminar Inst. f. Werkzeugmaschinenbau und Fertigungstechnik, ETH 2, Zürich, 1980.

(C) Problem Description
A model of a SISO hydraulic positioning system is given as follows:

$$\dot{x} = A(p)x + b(p)u + e(p)\omega$$

$$y = c(p)x$$

where  $x \in R^3$ ,  $u \in R^1$  is the input,  $y \in R^1$  is the output to be regulated,  $\omega \in R^1$  is a disturbance, and the plant model is parametrized by parameters  $p \in R^8$ , which lie in specified bounds  $p \in \mathcal{P}$ .

- $x_1 = \text{output position of carriage}(\text{cm})(y \text{ in Figure 1})$
- $x_2 = \text{velocity of carriage} = \dot{x}_1 \text{ (cm/sec) } (\dot{y} \text{ in Figure 1)}$ 
  - $x_3 = \text{oil pressure}(P_L \text{ in Figure 1})$
- u = servo valve flow input
- y = output position of carriage to be regulated (y in Figure 1)
- $\omega = \text{external force disturbance } (P_L \text{ in Figure I, } 0 < ||P_L|| < 800d_a N)$

It is desired to find a controller to regulate the output y to a desired set point tracking signal, subject to the following constraints: (a) The output response has zero overshoot for a step function set point change, or/and a step function disturbance change in  $\omega$ .

- (b) The output has a zero trailing error for ramp shaped reference input signal.
- (c)  $||u|| \le 866 \text{ cm}^3/\text{sec}$
- (d) The above constraints should be satisfied for all parameters  $p \in \mathcal{P}$ .




Figure 1: Schematic representation of hydraulic positioning system

The data for this problem is given as follows:

$$A = \begin{bmatrix} 0 & 1 & 0 \\ 0 & -\left(R + \frac{1}{4}R_c\right)/m & A/m \\ 0 & \frac{-4B}{4}A & \frac{-4B}{4}(\sigma + K_L) \end{bmatrix}, \quad b = \begin{bmatrix} 0 \\ 0 \\ -4B \end{bmatrix}, \quad e = \begin{bmatrix} 0 \\ -1/m \end{bmatrix}$$

$$c = \begin{bmatrix} 1 & 0 & 0 \\ 0 & -4B \end{bmatrix}$$

where the parameters  $B, m, R, R_c, K_L, \sigma, V, A$  are given as follows:

compressibility modulus (nominal value B=14000) j 9000 < B < 16000 daN/cm $^2$ Coulomb friction coefficient (nominal  $R_c = 0.01$ ) friction coefficient (nominal value R=0.150) by pass oil coefficient (nominal  $K_L = 0.002$ ) mass (nominal value m = 0.1287), Rc NL O B 2

hydraulic constant (nominal  $\sigma = 0.24$ ) piston area (nominal value A = 10.75), volume (nominal value  $V = 874 \text{ cm}^3$ ) external force

 $0 < R_c < 0.05 \text{ s daN/cm} \\ 0.000103 < K_L < 0.0035 \text{ cm}^5/\text{s daN}$  $0.001 < \sigma < 15 \text{ cm}^5/\text{s daN}$  $0.05 < R < 5 \, daN/cm$ 

0.05 < m < 0.3 t

 $10.5 < A < 11.10 \text{ cm}^2$  $0 < F_L < 800 \text{ daN}$ 

(D) Name of Person Submitting Problem

Dr. M.F. Senning SIG Swiss Industrial Company Postfach CH-8212 Neuhausen Rhine Falls Switzerland

Servo

# Problem #90-08 CONTROL SURFACE SERVO PROBLEM FOR AN UNDERWATER VEHICLE

### (A) General Description

We consider in this problem a control surface servo for an underwater vehicle. The system is a 2 input, 3 output system with disturbances. The main seatures of interest are:

- 1. A lightly damped resonant load mode with characteristics dependent on speed and depth.
- 2. A disturbance-rejection specification which depends on disturbance frequency
- 3. A parameter sensitivity specification.
- 4. Strict limitations on the complexity of the feedback structure, i.e. the controller is constrained to have a decentralized control structure.

#### (B) Reference

This problem has not been published previously. Permission of the Royal Canadian Navy to publish it is gratefully acknowledged.

### (C) Problem Description


System Overview The servo, which is completely hydraulic, is shown in Figure 1. The input differential pressure,  $\Delta P_i$ , is derived from an electrohydraulic valve with negligible dynamics. Two stages of amplification follow. The flapper valve acts as a force summer, having as input forces:


- 1. An input force proportional to  $\Delta P_i$ , applied through pistons;
- 2. A restoring force provided by a flexural spring;
- 3. A position feedback feedback force, applied by an adjustable feedback linkage through pistons and springs;
- 4. A load pressure feedback force, applied through small pistons.

#### System Model

State, control and output variables

The mass of the input pistons is ignored, and the input force is assumed to be applied directly to the flapper. Incrtia effects in hydraulic lines are also ignored, since the lines are very short.





HYDRAULIC ACTUATOR

SCHEMATIC

F18. 1

With these simplifications, the system can be modelled as an 8<sup>th</sup> order system. The system equations have the form

$$\dot{x} = Ax + Bu + Ew$$

$$y_m = C_m x$$

$$y = Cx$$

The state vector

 $\mathbf{x} = (x_1, \, \cdots, \, x_8)^{\prime =}$ 

where

= flapper valve position

= flapper valve velocity £2 = flapper output pressure £3

 $x_4$  = spool valve position  $x_5$  = spool valve velocity

load pressure 

load position 11 12

 $x_6 = load \ velocity$ 

The control vector, which represents the two feedback connections, is

 $u = (u_1, u_2)'$ 

where

u, = load pressure feedback input

u<sub>2</sub> = position feedback input

The disturbance vector incorporates both the input signal and the load disturbance hydrodynamic force referred to the ram;

 $\mathbf{w} = (w_1, w_2)'$ 

where

w<sub>2</sub> = load force (external disturbance)  $w_1 = input signal$ 

The measurable output variables are:

 $y_m = (x_6, x_7)'$ 

and the output to be regulated is:

 $y = x_7$ 

The state variables are normalized, with 1 representing the saturation limit of each variable. The output variables are therefore also normalized, with 1 representing the limits of the linear range of the model. The w vector is normalized so that 1 represents 5 volts (electrical input) for w1, and 50,000 lb for w2.

The gain  $(k_2)$  of the feedback linkage is adjustable from a ratio  $R_I$  of 0.04 to  $R_I=0.30$ . The load pressure feedback gain  $(k_1)$  is adjustable from 0 to 360. The feedback configuration is thus constrained, to have the structure:

£,  $u = \begin{pmatrix} k_1 & 0 \\ 0 & k_2 \end{pmatrix}$ 

where k<sub>1</sub>, k<sub>2</sub> are constant gains to be determined.

The load is a control surface whose effective mass (referred to the ram), effective damping force, and hydrodynamic/structural spring constant vary with vehicle speed and immersion depth.

A single set of feedback gains is sought which will satisfy the system specifications over the

Matrix elements

operating range.

0	0	0	0	0	-9.0e+02	1.1e+02	-2.2e+01										
0	0	0	0	0	0	0	-1.1e+00										
0	0	0	0	0	-1.0e+00	0	1.2e + 01		0	0	0	0	0	0	0	9.9e+0.1	Table 3: E matrix
0	0	-7.0e+02	1.4e + 03	-1.1e+02	0	0	0	A matrix	0	9.9e + 0.3	0	0	0	0	0	0	Table 3:
0	0	0	0	-4.5e+02	8.1e+01	0	0	Table 1: A	0	9.9e+04	0	0	0	0	0	0	matrix
0	-4.1e+03	-3.3e+01	0	1.6e + 03	0	0	0			4.6e+00 9	0	0	0	0	0	0	Table 2: B
8.5e+02	-1.2e+02	0	0	0	0	0	0			•							
0	-8.5e+02	3.3e + 01	0	0	0	0	0										

$$C_m = \begin{pmatrix} 0 & 0 & 0 & 0 & 1 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 & 1 & 0 \end{pmatrix}$$
$$C = \begin{pmatrix} 0 & 0 & 0 & 0 & 0 & 0 & 1 & 0 \end{pmatrix}$$

Table 4: Cm and C matrices

This dependence can be expressed in terms of a single parameter p. Over the operating range, p varies from 0.5 to 1. The values given for the A matrix in Table 1 are for p = 1. For other values Load characteristics The hydrodynamic load on the control surface is speed and depth dependent. of p, the values of the matrix elements which vary are given by:

$$A(8,6) = \frac{A(8,6)_{p=1}}{2.48 - 1.48p}$$

$$A(8,7) = F(p)A(8,7)_{p=1}$$

$$A(8,8) = F(p)A(8,8)_{p=1}$$

 $\frac{E(8,2)_{p=1}}{2.48-1.48p}$ 

E(8,2) =

where

 $F(p) = \frac{0.8065p^2(1.5 - p)}{}$ 1 - 0.5968p

### Performance Specifications

be less than 0.1 s and the peak overshoot for y shall be less than 20 percent. No state variable shall reach saturation for this input level. These requirements are to be satisfied for all operating (a) Response to command inputs: For a step input of 0.25 unit at w1, the settling time for y shall conditions, i.e.  $\forall p \in [0.5, 1]$ .

shall have the property that its steady state gain  $\|g(0)\|$  shall not exceed 1 unit, its maximum gain (b) Stiffness requirement: The steady-state sinusoidal frequency response  $g(j\omega) riangleq y(j\omega)/w_2(j\omega)$  $g_{\max} \triangleq \max_{\omega \in [0,\infty)} \|g(j\omega)\|$  should not exceed 3 times its steady-state gain  $\|g(0)\|$ , and  $\|g(j\omega)\|$ g<sub>max</sub>, V frequencies  $\geq 8$  Hz. (This specification is required to preclude hydrodynamically induced structural divergence, and is <u>mandatory.</u>) These requirements are to be satisfied for all operating conditions, i.e.  $\forall p \in [0.5, 1]$ . (c) Sensitivity specifications: All zero entries in the system matrices, and the elements A(1,2) and A(7,8), are fixed. The remaining elements may vary by ±20 per cent. Stiffness requirements (b) are to be met for all such variations, and stability is to be retained. Minor variations in input-output response (specifications a) can be tolerated in this case.

(D) Name of Person Submitting Problem

Professor II. W. Smith,

Department of Electrical Engineering, University of Toronto, Toronto, Canada M5S 1A4 Telephone: (416) 978-6341

FAX: (416) 978-7423

#### Mechanical Systems

Problem #90-09 (Cascade of Inverted Pendula)

Problem #90-10 (Regulation of a Ship's Heading)

Problem #90-11 (Automatic track Control of City Bus)

Problem #90-12 (Robotic System)

Mechanical

a1


Problem #90-09 CASCADE OF INVERTED PENDULA

(A) General Description
This problem describes a linearized model of a cascade of inverted pendula, and has the feature of being 'highly' unstable and difficult to control. The difficulties of control become more pronounced as the number of links increase.

(B) Reference The source of this problem is given in: Kwakernaak, H., Westdyk, H., "Regulability of a multiple inverted pendulum system", Control-Theory and Advanced Technology, vol. 1, no. 1, April 1985, pp. 1-9.

(C) Problem Description

Consider the following system of a cascade of inverted pendula:



where all point masses  $m_i = 1$  (kg), all links have length  $l_i = 1$  (m), g = 9.8 (m/sec<sup>2</sup>), and where  $u_1, u_2, u_3, \dots$  denote torques about the respective pivots. Let the outputs of the system be

 $y_i = \theta_i$ , i = 1, 2, 3, ... and the inputs to the system be  $u_i$ , i = 1, 2, 3, ... It is desired to design a controller to stabilize the system so that the outputs are regulated to zero, in the presence of unmeasurable constant disturbances which may be applied to the system.

The following linearized model:

 $\dot{x} = a_i x + b_i u$  $y = c_i x$ 

describes the system with i links, i = 1, 2, 3, 4, 5, 6, 10:

1.0000e+00 0 0 0 1,0000e+00 0 0 1.0000e+00 0000 1,0000e+00 0 -9.8000e+00 0 2.9400e+01 1.0000e+00 0 0 1,0000e+00 00 0.8000e+00 0 9.8000e+00 -9.8000e+00 0 00 00 0 c2 4 И 83 **B**2 **P**2 cı P.

1.0000e+00 -3.5000e+00 4.0000e+00 -2.6667e+00 4.8333e+00 -2.6667e+00 0 0 0 1.6667e+00 -2.3333e+00 6.6667e-01

-3.6285e-16 -9.8000e+00 1.9600e+01

-1.9600e+01 3.9200e+01 -1.9600e+01

2.9400e+01 -2.9400e+01

1)

p3

٥				0 0 0 0 0 0 0 0 2.0127e-32	-3.6285e-16 -9.8000e+00 1.9600e+01 0
1.9600e+01		-2.2755e-16 3.0015e-16 1.0000e+00 4.0000e+00	00000	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	-1.9600e+01 3.9200e+01 -1.9600e+01 0
+01	00000000		0000	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
-1.9600e+01	1.0000e+00	0 0 0 0 3.1160e-16 1.0000e+00 4.8333e+00	0000	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	5.8800e+01 -2.9400e+01 -1.0885e-15 0 0 0 1.0000e+00
0	000000.	0 0 0 0 1.0000e+0 3.7500e+00 5.1667e+00 3.0833e+00	0000	0 0 0 0 0 2.9028e-15 3.9200e+01 7.8400e+01	
	-		00001	***	T T
0 9	1 00	0 0 0 0 0 0 5.3500e+00 5.3500e+00 -3.3000e+00 7.5000e-01	000000	000	6323e-14 6323e-15 .gh 12 00000e+00 0
9	through 0 0 1.0		0 0 0 0 0		
-	0+	0 0 0 0 0 1.8000e+00 -2.6000e+00 8.0000e-01 5.1282e-16 5.3006e-17	0 1 0 0 0	+ + 0 + + 0	111 6 4
Political		7.2.0 0.0.0 0.0.0	c5 = 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	ν.υ. ∞ ∞	-2.0310 1.1968 2.1755 Columns 1.0000
	1,0000e+00 0 0 0 0 0 0				1.0000e+00 0 0 0 0 0 0 0 0 0
	1.0000e+00				0 0 0 0 0 0 0 0 0 0 -3.6285e-16
	0 0 0 0 0 0 -3.6285e-16 -9.8000e+00		6.4185e-17 1.0000e+00 -3.5000e+00	0000	0 0 0 0 1.0878e-15 0 -1.9600e+01 3.9200e+01
00	0 0 0 0 0 -1.8600e+01 3.9200e+01		1.0000e+00 -3.6667e+00 4.8333e+00	0000	0 0 0 0 0 -4.5686e-15 -2.9400e+01 -2.9400e+01
00				0000	
00	ough 6 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0 0 0	0 0 0 0 0 5.7500e+00 5.1667e+00 -3.0833e+00	1000 1000	0 0 0 0 0 0 7.8400e+01 7.8400e+01 -3.9200e+01 -1.3056e-14
0-1	Ă Á	1.0		0 1 0 0 through	8 F 8 H
00	Columns 1 th 0 0 0 3.9200e+01 -3.9200e+01 -4.3521e-15 0 0	1.0000e+00 0 0 0 0 0	0 0 0 0 0 0 7.5000e+00 7.5000e+00 3.5586e-17	1 0 0 1 0 0 0 0 =	4.9000e+01 -4.9000e+01 -3.6630e-14
	4	4	, 42	<b>8</b>	, ,

1.0000e+000 0 00000e+000	000000000	1.0000e+00	0000000
1.0000e+00 0 0 0 0 0 0 0 0 0 0 0		1.0000e+00	
00000000	-1.0042e-32 8.944e-48 2.0172e-32 4.0225e-32 8.0569e-32 8.0569e-32 8.0569e-12 1.9600e+00	1.0000e+00	0000000
00000000	5.4388e-16 -4.8318e-31 -1.0883e-15 1.6323e-15 4.3521e-15 -4.3861e-15 -1.9600e+01 -1.9600e+01	1.0000e+00	0000000
00000000	-1.6316e-15 1.4495e-15 -1.3649e-15 -1.3056e-14 -2.9400e+01 -2.9400e+01 -2.9400e+01 -2.9400e+01 -2.9400e+01	1.0000e+00 0 0 0 0 0 0 0 0 0 0	through 20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
-	4	1.00006+00	Columns 19 th
1.0000e+00 0 0 0 0 0 0 0	-1.0963e-16 4.2643e-16 1.0000e+00 4.0000e+00 4.0000e+00	00000	5.4388e-15 0 0 0 0 0 0 0 0 0 1.0880e-14 -4.9000e+01 9.8000e+01 -4.9000e+01 -4.9000e+01 -2.9013e-14
1.0000e+00	0 0 0 0 0 1.2911e-16 6.7758e-17 1.0000e+00 4.8333e+00	00000	-6.5249e-15 6.5281e-15 6.5281e-15 1.1760e+02 1.1760e+01 3.1009e-14 -1.8859e-14 8.1601e-15
0000000	-3.0442e-16 1.0000e+00 -3.7500e+00 -3.0833e+00 6.6667e-01	00000	-3.7188e-18 -5.8500e+01 1.3720e+01 1.3720e+01 -6.8600e+01 -7.6177e-15 -5.4454e-16 -1.4506e-15
0000000	1.0000e+00 -3.8000e+00 5.3500e+00 7.5000e-17	10000	-1.7383e-15 -7.8400e+01 1.5680e+02 -2.5751e-14 1.3056e-14 -8.1601e-15 3.9892e-15
0000000	0 0 0 0 0 0 0 5.48333e+0 5.4867e+0 3.000e-01 -9.2492e-16	000100	through 6  0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
= 9q	1.8333e+00 -2.6667e+00 8.333e-01 -5.5618e-16 4.3692e-16	C 6 1 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	al0 =  Columns 1 thi 0 0 0 0 9.8000e+01 -1.0880e-14 -1.1062e-14 -1.1062e-15 -1

0000000		
0000000		
-000000		
0000040		
00000-00	00000000	
0000-000	00000000	
0001000	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	
000000000000000000000000000000000000000	(D) Name of Person Submitting Problem Dept. of Electrical Engineering University of Toronto Toronto, Ontario, Canada M5S 1A4 Tel: (416) 978-6342	
0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	ame of Person Submit  E.J. Davison  University of Toronto  Toronto, Ontario, Car Tel: (416) 978-6342	
1 0 0 0 0 0 0 through	E.J. Davison Dept. of Electrical I Toronto, Ontario, C Tel: (416) 978-6342	
0 0 0 0 0 0 0 0 0 0	Ž	
0 0 0 0 0 0 0 Column		
	. 8626e-16 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	00
	7 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	00
	- 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2	00
	1959e-16 000000000000000000000000000000000000	00
	2.1959e-16 1.0000e+00 -3.8750e+00 -3.5893e+00 -7.1966e-16 -7.1966e-16 -1.0739e-16 -1.0739e-18 -2.9476e-17 -2.6452e-16 -2.9476e-17 -2.6452e-16 -2.9476e-17 -2.6452e-16 -1.0739e-16 -1.0739e-16 -1.0739e-16 -1.0739e-16 -1.0739e-16 -1.0739e-16 -1.0739e-16 -1.0739e-16 -1.0739e-16 -1.0739e-16 -1.0739e-16 -1.0739e-16	00
	1	00
	1.0000e+00 1.0000e+00 2.3538e+00 2.3538e+00 2.3538e-15 -2.4097e-16 -2.213538e-15 -2.3538e-15 -2.3538e-15 -2.4097e-16 00 00 00 00 00 00 00 00 00 0	00
00000		00
9 qgh	-2.9000e+00 -3.6778e+00 -3.6778e+00 -3.778e-01 3.7186e-15 -4.0482e-15 -7.5092e-16 0 0 0 0 -2.5389e-16 -2.3237e-15 -2.3237e-15 -3.0833e+00 6.6667e-01	ough 12 0 0
0 0 0 0 0 1 through	<u>í</u>	1 through 0 0 1 0
bl0 = Columns	1.9000e+00 -2.8000e+00 -2.9000e+00 -2.9590e-15 -2.6230e-15 -2.6230e-15 -3.7739e-17 -3.7739e-16	c10 = Columns 1

#### Mechanical

# Problem #90-10 REGULATION OF A SHIP'S HEADING

### (A) General Description

This problem deals with the design of a controller associated with the regulation of a ship's heading, in which constraints are imposed on the magnitude of the control signals applied.

(B) Reference
The source of this problem is given in:
Kallstrom, C.G., K.J. Astrom, N.E. Thorell, J. Eriksson, L. Sten, "Adaptive Autopilots for

Tankers", Automatica, vol. 15, no. 3, 1979, pp. 241-254.
Astrom, K.J., Kallstrom, C.G., "Identification of Ship Steering Dynamics", Automatica, vol. 12, 1976, pp. 9-22.

Kallstrom, C.G., Astrom, K.J., "Experiences of System Identification Applied to Ship Steering", Automatica, vol. 17, no. 1, 1981, pp. 187-198.

### (C) Problem Description

The linearized model of a ship moving under constant velocity (in a straight line motion) is described as follows:

$$\dot{x} = Ax + bu$$

$$y = cx$$

y = cx

where  $x \in \mathbb{R}^3$ ,  $u \in \mathbb{R}^1$ ,  $y \in \mathbb{R}^1$  are given as follows:

 $u = \text{rudder angle (radians) } (\delta \text{ in Figure 1)}$ 

 $y = \text{heading angle of ship (radians) } (\psi \text{ in Figure 1)}$ 

 $x_1 = \text{sway velocity of ship } (v \text{ in Figure 1})$ 

 $x_2 = \text{turning yaw rate} (r = \dot{\psi} \text{ in Figure 1})$ 

 $x_3 = \text{heading angle of ship (radians) } (\psi \text{ in Figure 1})$ 




Figure 1: Notation used to describe ship's motion

It is desired to find a controller for the system to regulate the heading angle of the ship to a desired angle  $y_{ref}$ , such that the following constraints are satisfied:

(a) No overshoot occurs in the output response of y.

(b) The rudder motion is constrained:

 $||u|| \le 40^{\circ}$ 

(c) The rate of rudder motion is constrained:

$$||\dot{u}|| \le 10^{o}/\text{sec}$$

The turning rate  $\dot{\psi}$  of the vessel may be measured, and used in the controller. The data for this problem is given in normalized units as follows:

length unit = length of ship

time unit = time required for ship to travel a ship's length

where the structure of A, b, c is given by:

$$A = \begin{pmatrix} a_{11} & a_{12} & 0 \\ a_{21} & a_{22} & 0 \\ 0 & 1 & 0 \end{pmatrix}, \quad b = \begin{pmatrix} b_{1} \\ b_{2} \\ 0 \end{pmatrix}, \quad c = \begin{pmatrix} 0 & 0 & 1 \end{pmatrix}$$

where a11, a12, a22, b1, b2 is given as follows for various classes of vessels:

Tanker #3	350	15.8	-0.454	-0.433	-4.005	-0.807	0.097	-0.807
Tanker #2	322	16	-0.298	-0.279	-4.370	-0.773	0.116	-0.773
Tanker #1	305	16	-0.597	-0.372	-3.651	-0.792	0.103	-0.792
Cargo #2	161	15	-0.770	-0.335	-3.394	-1.627	0.170	-1.627
Cargo #1	160	15.2	-0.895	-0.286	-4.367	-0.918	0.108	-0.918
vessel	length	peeds	g11	a <sub>12</sub>	421	<b>4</b> 13	4	<i>b</i> 2

If one wishes to explore a nonlinear model, the first equation can be modified to give

 $\frac{dx_1}{dt} = a_{11}x_1 + a_{12}x_2 + cx_1|x_1| + b_1u$ 

where c = 0.7.

(D) Name of Person Submitting Problem

K.J. Astrom
Dept. of Automatic Control
Technical University of Lund
Institute of Technology
Box 725
22007 Lund 7, Sweden
kja@control.lth.se

42

Mechanical

# Problem #90-11 AUTOMATIC TRACK CONTROL OF CITY BUS

### (A) General Description

It is desired to control the lateral motion of a city bus such that the bus follows an electromagnetic track imbedded in the street. Uncertain parameters of the system are the bus's mass, the bus's speed and road surface conditions.

(B) References
The source of this problem is given in:
Darenberg, W., "Automatische Spurfuehrung von Krastfahrzeugen", Automobilindustrie, 1987,

Ackermann, J., "The Track-Guided Bus - Parametric Modelling of its Dynamics and Analysis of the Robust Control Problem", DLR Report 515-89-15, July 1989.

(C) Problem Description
A linearized model for the lateral motion of a city bus is given as follows:

$$\dot{x} = A(q)x + bu$$
$$y = Cx$$

where  $x \in R^5$ ,  $u \in R^1$  the input,  $y \in R^1$  the output to be regulated, and the plant model, parametrized by parameters  $g \in R^2$ , which lie in specified bounds  $g \in Q$ . The variables of the model are:

= sideslip angle at center of gravity ( $\alpha$  in Figure 1)

x2 = yaw angle rate (¢ in Figure 1)

 $x_3 = \text{deviation of center of bus from track } (d \text{ in Figure 1})$ 

 $x_4 = \text{yaw angle } (\varepsilon \text{ in Figure 1})$ 

 $x_s = \text{steering angle (radians) } (\beta \text{ in Figure 1})$ 

 $u = input to integrating hydraulic steering actuator (<math>\dot{\beta}$  in Figure 1)

y = displacement of front sensor of bus from track

reciprocal of bus velocity (1/v in Figure 1)

ratio of friction coefficient and mass of bus  $(q_2 \equiv \mu/m)$ 

A, b, C are given as follows:

$$A = \begin{bmatrix} a_{11} & a_{12} & 0 & 0 & a_{15} \\ a_{21} & a_{22} & 0 & 0 & a_{25} \\ 1/q_1 & 0 & 0 & 1/q_1 & 0 \\ 0 & 1 & 0 & 0 & 0 \\ 0 & 0 & 0 & 0 & 0 \end{bmatrix}, b = \begin{bmatrix} 0 \\ 0 \\ 0 \\ 1 \end{bmatrix}$$

 $a_{11} = -2q_1q_2(\delta_F + \delta_R) \qquad a_{12} = -1 - 2q_1^2q_2(\delta_F | F - \delta_R | R_R)$   $a_{21} = -2q_2(\delta_F | F - \delta_R | R_R)/c \quad a_{22} = -2q_1q_2(\delta_F | \frac{1}{F} + \delta_R | \frac{1}{R})/c$  $a_{25} = 2q_2 \delta_F l_F/c$ a15 = 291926F

where the constant parameters of the vehicle are given by:

ls = distance of front sensor from center of mass = 6.12 m lF = distance of front axle from center of mass = 3.67 m

 $l_R = \text{distance of rear axle from center of mass} = 1.93 \text{ m}$ 

 $\delta_F = \text{lateral force coefficient front wheels } (\mu=1) = 99 \text{ kN/rad}$ 

 $\delta_R = \text{lateral force coefficient rear wheels} (\mu = 1) = 235 \, \text{kN/rad}$  $c = \text{ratio } \theta/m$ , where  $\theta$  is the moment of inertia w.r.t.

a vertical axis through the center of mass and m is the

The uncertain operating conditions of the vehicle are given as follows: bus mass,  $c = 10.86 \text{ m}^2$ 

0.5 (wet road)  $\leq \mu \leq 1$  (dry road) 9.95 tons  $\leq m \leq 16$  tons  $1ms^{-1} \leq v \leq 20ms^{-1}$ 




Figure 1: Automatic steering of city bus

eration of the bus at the front sensor ( $\ddot{y}_{Bus}$ ) is given by  $\ddot{y}_{Bus}=v\omega$ , where  $\omega:=\dot{\varepsilon}+\dot{\alpha}+l_s\frac{c}{v}$ , and thus the second derivative of the measured displacement ( $\hat{e}$ ) is given by  $\hat{e}=\hat{y}_{Bus}-\hat{y}_{Track}$ . Thus if  $\omega_{ref}\equiv 0$  (i.e. the track guideline is a straight line), then  $\tilde{e}=\hat{y}_{Bus}=\omega\omega=v(\hat{e}+\hat{\alpha})+l_s\hat{e}$  which gives  $e=d+l_s\varepsilon=y$ . If  $\omega_{ref}\neq 0$ , then the error e in the system, to be regulated to zero, is given vures, where wres depends on the geometry of the track guideline. In a curve, the lateral accel-Let yrrack be the displacement of the track guideline from a given reference; then yrrack = by  $\ddot{e} = v(\omega - \omega_{ref})$  or by

c = y - ytrack

where  $\ddot{y}_{track} = v\omega_{ref}$ .

Typical transition trajectories are:

- Switching from manual to automatic steering. In this case, the controller is activated before switching with initial condition  $x_1(0) = 0$ ,  $x_2(0) = 0$ ,  $x_3(0) = 0.15$ ,  $x_4(0) = 0$ ,  $x_5(0) = 0$ , which corresponds to a 15 cm parallel displacement from track.
- · Transition from a straight track into a curve of constant radius 400 m.
- ullet Narrow S-shaped curve for entering a bus stop bay at low speed with  $\omega_{ref}$  given in Pigure




Figure 2: Reference angular velocity for entering a narrow bus stop bay

For passenger comfort the natural frequency  $\omega_n$  of the lateral motion must not exceed 1.2 Hz, The following constraints must be satisfied during the above transitions:

 $\omega_n \le 2\pi \cdot 1.2 = 7.5 \text{ Radians/sec}$ 

The lateral acceleration must not exceed 0.4g, i.e.

 $v(\omega-\omega_{ref}) \le 4ms^{-2}$ 

and its rate by

The steering angle is limited by

 $|\dot{\beta}| \le 23^{o}/\mathrm{sec}$ 

|β| ≤ 40°

## (D) Name of Person Submitting Problem

Dr. J. Ackermann	Dr. Ing. W. Darenherg
DLR-FF-DF	Daimler Benz AG
8031 Oberpfaffenhofen	FVF/AA
W. Germany	Postfach 800230
	7000 Stuttgart 80
	W. Germany

## Problem #90-12 ROBOTIC SYSTEM

#### 1. Introduction.

Control of robots is a topic of current interest. However, most control strategies neglect actuator dynamics. There are two main approaches suggested in the literature (see e.g. reference list in  $^{1}$ ). The first is based only on the geometric equations relating task space coordinates and configuration space coordinates. The second one applies classical (e.g. PID) or modern (e.g. MRAC, optimality concepts, sliding modes etc.) control concepts to the so-called drive equations providing thus the command signals for actuator control. Only very few authors try to handle the control problem on the basis of the dynamic equations for arm and actuators  $^{1}$ ). Therefore , in the following a typical articulated robotic arm with three degrees of freedom is described in detail. Its joints are driven by DC-motors, acting via gearings of relatively high ratios.

The highly nonlinear and strongly coupled dynamic model described in detail in the following may serve e.g. for testing

- classical and modern control algorithms based on the complete nonlinear model  $% \left( 1\right) =\left\{ 1\right\} =\left\{$
- classical and modern control algorithms based on the linearized model with or without order reduction
- decoupling algorithms
- the effects of linearization, order reduction, etc.

#### 2. The Robot.

The robot sketched in Fig.1 can be modelled as given by equs.(1) and (2). Control inputs are the control voltages  $U_{C_i}$  of the actuators. The controlled outputs are the joint angles  $\phi_i$  and the relative joint angular velocities  $\dot{\phi}_i$  (i=1,2,3)

### 2.1 Drive equations

#### Notations:

Motor i mounted in link i-1 (link 0 = foundation) is driving  $\zeta_1$  ... electromagnetic moment acting on rotor  $R_i$  of the motor  $^7$ 

Desoyer, K.; Kopacek, P.; Troch, I.: Industrieroboter und Handhabungsgeräte, R.Oldenbourg-Verlag, München, 1985.

 $M_{F_{\frac{1}{2}}}$  ... moment of friction reduced to the axis of rotor  $R_{\frac{1}{2}}$ (compare the assumption stated in 3.1)

ν<sub>j</sub> ... gear ratio

 $\sigma_{j}$  ...relative angular velocity of rotor  $R_{j}$  in link i-1

 $\sigma_{i} = \nu_{i} \dot{\phi}_{i}$  (i=1,2,3)

m<sub>1</sub>,m<sub>2</sub>,m<sub>3</sub> ... masses of the links 1,2,3 including actuators m. ...... mass of end effector and load

 $c_{1},c_{L}$  ..... center of mass = center of gravity of  $m_{i},m_{L}$ 

 $x_1, {}^6y_1, {}^6z_1$  . unit vectors fixed in joint  $0_1$  of link i

 $x_{L},y_{L},z_{L},\ldots$  coordinates of  $c_{L}$  in the linkfixed system of link 3 (fig.1)  $x_i,y_j,z_i$  ... coordinates of  $c_i$  in the linkfixed system of the link i

 $c_{i}\text{-}\cos\phi_{i} \qquad S_{i}\text{-}\sin\phi_{i} \qquad c_{ik}\text{-}\cos(\phi_{i}\text{+}\phi_{k}) \qquad S_{ik}\text{-}\sin(\phi_{i}\text{+}\phi_{k})$ 

 $\begin{bmatrix} K_{x_1} & -K_{x_1 x_1} & (i=2,3) \text{ synmetric inertial tensor of link is with therein mounted actuator i+1, referred by ixis | Kyi & K$ 

symmetric inertial tensor of endeffector origin  $0_2$  that are parallel to the link with load referred to the axes through fixed axes  $x_3$ , $y_3$ , $z_3$  (fig.1).  $\begin{bmatrix} x_{1} & -x_{1}y_{1} & -x_{1}z_{1} \\ -x_{1}z_{1} & x_{1} & -x_{1}y_{1} & -x_{1}z_{1} \end{bmatrix}$   ${
m I}_1$  ... inertial moment of link l with actuator 2 with respect to the spacefixed axis  $z_0$ 

 $\mathbf{I}_{R_1^{\dagger}}\cdots$  inertial moment of the rotor  $R_i$  of actuator i with respect to its axis e<sub>j</sub> fixed in link i-l

 $\alpha_i,\beta_i,\gamma_j$  ... angles between rotor axis  $\vec{e_i}$  and linkfixed directions  $\overset{\hat{e}}{e_{\chi_i-1}},\overset{\hat{e}}{e_{\chi_i-1}},\overset{\hat{e}}{e_{\chi_i-1}},\overset{\hat{e}}{e_{\chi_i-1}}$  (fig.2).

For simplification we assume that there is no relative motion between endeffector with load and link 3,  $(x_{L},y_{L},z_{L}^{*}$  constant).

electromagnetic moments  $\mathsf{M}_{\mathsf{A}_1}$  needed to act on the rotors of the actuators With the notations given above the following equations  $^2)$  describe the for a desired motion  $\phi_i(t)$  of the links (i=1,2,3)

$$\begin{bmatrix} v_1(^MA_1^{-M}F_1) \\ v_2(^MA_2^{-M}F_2) \\ v_3(^MA_3^{-M}F_3) \end{bmatrix} = \begin{bmatrix} m_{11} & m_{12} & m_{13} \\ m_{21} & m_{22} & m_{23} \\ m_{31} & m_{32} & m_{33} \end{bmatrix} \begin{bmatrix} \ddot{\omega}_1 \\ \ddot{\omega}_2 \\ \ddot{\omega}_3 \end{bmatrix} + \begin{bmatrix} m_2 \\ m_2 \\ \ddot{\omega}_3 \end{bmatrix} + \begin{bmatrix} m_2 \\ m_3 \\ m_3 \end{bmatrix}$$

Ξ

here the following abbreviations are used;

The elements  $\mathbf{m}_{ik}$  of the 3x3 matrix in (1) are given by

$$\begin{split} \mathbf{m}_{11} &= \mathbf{I}_1 + \mathbf{m}_2 \{ K_{\chi_2} S_2^2 + K_{\chi_2} S_2^2 C_2 + 2 \{ (\mathbf{I}_2 + \mathbf{x}_2) C_2 - \mathbf{y}_2 S_2 \mathbf{I}_1 + \mathbf{I}_1^2 \} \right. \\ &+ \mathbf{m}_3 \{ K_{\chi_3} S_2^2 + K_{y_2} C_2^2 - 2 K_{\chi_3 y_3} S_2 S_2 S_3 + e (e + 2 Z_3) + (\mathbf{I}_1 + \mathbf{I}_2 C_2)^2 \\ &+ 2 (\mathbf{I}_1 + \mathbf{I}_2 C_2) \{ (\mathbf{I}_3 + \mathbf{x}_3) S_2 S_3 S_3 + e (e + 2 Z_3) + (\mathbf{I}_1 + \mathbf{I}_2 C_2)^2 \\ &+ \mathbf{m}_1 \{ K_{\chi_1} S_2^2 + K_{\chi_2} C_2^2 - 2 K_{\chi_1 y_1} S_2 S_2 S_3 + e (e + 2 Z_1) + (\mathbf{I}_1 + \mathbf{I}_2 C_2)^2 \\ &+ 2 (\mathbf{I}_1 + \mathbf{I}_2 C_2) \{ (\mathbf{I}_3 + \mathbf{x}_1) C_{23} - y_1 S_{23} \} + \mathbf{I}_{R_1} v_1^2 \end{split}$$

$$m_{22} = m_2 K_{22} + m_3 \{ K_{23} + 1_2^2 + 2 [ (1_3 + x_3) C_3 - y_3 S_3 ] 1_2 \} + 4 m_L \{ K_{2L} + 1_2^2 + 2 [ (1_3 + x_L) C_3 - y_L S_3 ] 1_2 \} + 1_{R_2} v_2^2$$

$$\begin{split} \mathbf{m}_{12} &= \mathbf{m}_{21} = -\mathbf{m}_{2}(K_{22\times_{2}}S_{2} + K_{y_{2}z_{2}}C_{2}) \\ &- \mathbf{m}_{3} \; (\; (e + z_{3})l_{2}S_{2} + (K_{y_{3}z_{3}} + ey_{3})C_{23} + (K_{z_{3}x_{3}} + e(l_{3} + x_{3})l_{2}S_{3}) \\ &- \mathbf{m}_{1} \; (\; (e + z_{L})l_{2}S_{2} + (K_{y_{L}z_{L}} + ey_{L})C_{23} + (K_{z_{L}x_{L}} + e(l_{3} + x_{L})l_{2}S_{3}) \end{split}$$

+ 1R22 cos B2

<sup>2)</sup> See footnote 1)

$$\begin{split} \mathbf{m}_{13} &= \mathbf{m}_{31} \left\{ (K_{y_{3}z_{3}}^{3} + \mathbf{e}y_{3}) C_{23}, + [K_{z_{3}x_{3}}^{3} + \mathbf{e}(1_{3} + x_{3})] S_{23} \right\} \\ &= \mathbf{m}_{L} \left\{ (K_{y_{L}z_{L}}^{1} + \mathbf{e}y_{L}) C_{23}, + [K_{z_{L}x_{L}}^{1} + \mathbf{e}(1_{3} + x_{L})] S_{23} \right\} \end{split}$$

$${}^{+} I_{R_3} v_3 (S_2 \cos x_3 + C_2 \cos B_3)$$

$$m_{23} = m_{32} = m_3 (K_{23} + \{(1_3 + x_3)C_3 - y_3S_3]1_2\} +$$

$$^{+\,\,m_L\,(K_{Z_L}+\{(1_3+x_L)C_3-y_LS_3]1_2\}\,\,+\,\,I_{R_3},_3\cos\gamma_3}$$

The elements of the 3x1 matrix  $\underline{n}$  in (1) are

$$\begin{split} n_1 &= n_{1,22} \dot{\hat{\psi}}_{2}^2 + n_{1,33} \dot{\hat{\psi}}_{3}^2 + n_{1,12} \cdot 2 \dot{\hat{\psi}}_{1} \dot{\hat{\psi}}_{2} + n_{1,23} \cdot 2 \dot{\hat{\psi}}_{2} \dot{\hat{\psi}}_{3} + n_{1,31} \cdot 2 \dot{\hat{\psi}}_{3} \dot{\hat{\psi}}_{1} \\ n_2 &= n_{2,11} \dot{\hat{\psi}}_{1}^2 + n_{2,33} \dot{\hat{\psi}}_{3}^2 + n_{2,23} \cdot 2 \dot{\hat{\psi}}_{2} \dot{\hat{\psi}}_{3} + n_{2,31} \cdot 2 \dot{\hat{\psi}}_{3} \dot{\hat{\psi}}_{1} \end{split}$$

$$n_3 = n_{3,11} \dot{\hat{\psi}}_1^2 + n_{3,22} \dot{\hat{\psi}}_2^2 + n_{3,12} \cdot 2 \dot{\hat{\psi}}_1 \dot{\hat{\psi}}_2$$

with the abbreviations:

$$\begin{split} n_{1,22} &= m_{2} (K_{y_{2}z_{2}}^{S_{2}} - K_{z_{2}x_{2}}^{C_{2}}) + \\ &+ m_{3} ((K_{y_{3}z_{3}}^{A} + ey_{3})^{S_{23}} - (K_{z_{3}x_{3}}^{A} + e(l_{3} + x_{3})^{3} C_{23} - (e + z_{3}) l_{2}^{C_{2}}) + \\ &+ m_{L} ((K_{Y_{L}z_{L}}^{A} + ey_{L})^{S_{23}} - (K_{Z_{L}x_{L}}^{A} + e(l_{3} + x_{L})^{3} C_{23} - (e + z_{L})^{1} C_{23}) \end{split}$$

$$\begin{split} & n_{1,33} = m_{3} ( (K_{y_{3}z_{3}} + ey_{3})^{5} z_{3} - (K_{z_{3}x_{3}} + e(1_{3} + x_{3}) 1c_{23}) + \\ & + m_{L} ( (K_{y_{L}z_{L}} + ey_{L})^{5} z_{3} - (K_{z_{L}x_{L}} + e(1_{3} + x_{L}) 1c_{23}) \\ & + m_{1,12} = m_{2} ( (K_{x_{2}} - K_{y_{2}})^{5} z_{2} c_{2} + K_{x_{2}y_{2}} (s_{2}^{2} - c_{2}^{2}) - ((1_{2} + x_{2})^{5} z_{1} + yc_{2}^{2}) 1_{1}) + \\ & + m_{3} ( (K_{x_{3}} - K_{y_{3}})^{5} z_{3}^{3} c_{23} + K_{x_{3}y_{3}} (s_{2}^{2} - c_{2}^{2}) - (1_{1}^{1} + 1_{2}^{2} c_{2}) ((1_{3} + x_{3})^{5} z_{3} + y_{3}^{2} c_{23}) \\ & - ((1_{1}^{1} + 1_{2}^{2} c_{2}) + (1_{3}^{1} + x_{3})^{5} c_{23}^{2} - y_{3}^{2} z_{3}^{3})^{1} z_{2}^{5}) + \\ & + m_{L} ( (K_{x_{L}} - K_{y_{L}})^{5} z_{3}^{2} c_{23} + K_{L}y_{L} (s_{23}^{2} - c_{23}^{2}) - (1_{1}^{1} + 1_{2}^{2} c_{2}) ((1_{3} + x_{L})^{5} z_{3} + y_{L}^{2} c_{23}) \\ & + m_{L} ( (K_{x_{L}} - K_{y_{L}})^{5} z_{3}^{2} c_{23} + K_{L}y_{L} (s_{23}^{2} - c_{23}^{2}) - (1_{1}^{1} + 1_{2}^{2} c_{2}) ((1_{3} + x_{L})^{5} z_{3} + y_{L}^{2} c_{23}) \\ & + m_{L} ( (K_{x_{L}} - K_{y_{L}})^{5} z_{3}^{2} c_{23} + K_{L}y_{L} (s_{23}^{2} - c_{23}^{2}) - (1_{1}^{1} + 1_{2}^{2} c_{2}) ((1_{3} + x_{L})^{5} c_{23} + y_{L}^{2} c_{23}) \\ & + m_{L} ( (K_{x_{L}} - K_{y_{L}})^{5} z_{3}^{2} c_{23} + K_{L}y_{L} (s_{23}^{2} - c_{23}^{2}) - (1_{1}^{1} + 1_{2}^{2} c_{2}) ((1_{2} + x_{L})^{5} c_{23} + y_{L}^{2} c_{23}) \\ & + m_{L} ( (K_{x_{L}} - K_{y_{L}})^{2} c_{23}^{2} c_{23} + K_{L}y_{L} (s_{23}^{2} - c_{23}^{2}) - (1_{1}^{1} + 1_{2}^{2} c_{23}^{2}) ((1_{2} + K_{L})^{2} c_{23}^{2} + y_{L}^{2} c_{23}^{2}) \\ & + m_{L} ( (K_{x_{L}} - K_{y_{L}})^{2} c_{23}^{2} c_{23}^{2} + K_{L}y_{L} (s_{23}^{2} - c_{23}^{2}) - (1_{1}^{1} + 1_{2}^{2} c_{23}^{2}) ((1_{2}^{2} + K_{L}y_{L})^{2} c_{23}^{2} + y_{L}^{2} c_{23}^{2}) \\ & + m_{L} ( (K_{x_{L}} - K_{y_{L}})^{2} c_{23}^{2} c_{23}^{2} + K_{L}y_{L} (s_{23}^{2} - c_{23}^{2}) - (1_{1}^{2} + 1_{1}^{2} c_{23}^{2} c_{23}^{2} + K_{L}y_{L}^{2} c_{23}^{2} c_{23}^{2} + K_{L}y_{L}^{2} c_{23}^{2} c_{23}^{2} c_{23}^{2} + K_{L}y_{L}^{2} c_{23}^{2} c_{23}^{2} c_{23$$

$$\begin{split} & n_{1,23} = m_{3} ((k_{y_{3}z_{3}} + ey_{3}) S_{23}^{-1} (k_{z_{3}x_{3}} + e(l_{3} + k_{3})) C_{23})^{+} \\ & + m_{L} ((k_{y_{L}z_{L}} + ey_{L}) S_{23}^{-1} (k_{z_{L}x_{L}} + e(l_{3} + k_{L})) C_{23})^{+} \\ & + \frac{1}{2} l_{R_{3}} v_{3} (C_{2} \cos_{a_{3}} - S_{2} \cos_{B_{3}}) \\ & n_{1,31} = m_{3} ((k_{x_{3}} - k_{y_{3}}) S_{23} + k_{x_{3}y_{3}} (S_{23}^{2} - C_{23}^{2}) - (l_{1} + l_{2}C_{2}) [(l_{3} + x_{3}) S_{23} + y_{3}C_{23}]) \\ & + m_{L} ((k_{x_{L}} - k_{y_{L}}) S_{23}C_{23} + k_{x_{L}y_{L}} (S_{23}^{2} - C_{23}^{2}) - (l_{1} + l_{2}C_{2}) [(l_{3} + k_{L}) S_{23} + y_{L}C_{23}]) \end{split}$$

$$n_{2,11} = n_{1,12}$$
  $n_{2,23} = n_{2,33}$   $n_{2,31} = \frac{1}{2} I_{R_3} v_3 (C_2 \cos_3 - S_2 \cos \beta_3)$ 

$$n_{2,33} = -m_3((1_3+x_3)S_3+y_3c_3)1_2-m_1((1_3+x_L)S_3+y_Lc_3)1_2$$

$$n_{3,11}$$
 =  $n_{1,31}$   $n_{3,22}$  =  $n_{2,33}$   $n_{3,12}$  =  $n_{2,31}$ 

The moments  $M_{ extsf{gi}}$  in (1) due to the weight of the links and the load are:

-

$$\begin{aligned} \mathsf{M}_{g2} &= \mathbb{I}(1_2 + \mathsf{x}_2) \mathsf{C}_2 - \mathsf{y}_2 \mathsf{S}_2 \mathsf{Jm}_2 \mathsf{g} + \mathbb{I}(1_3 + \mathsf{x}_3) \mathsf{C}_{23} - \mathsf{y}_3 \mathsf{S}_{23} + \mathsf{1}_2 \mathsf{C}_2 \mathsf{Jm}_3 \mathsf{g} + \mathbb{I}(1_3 + \mathsf{x}_1) \mathsf{C}_{23} - \mathsf{y}_1 \mathsf{S}_{23} + \mathsf{1}_2 \mathsf{C}_2 \mathsf{Jm}_1 \mathsf{g} \\ \mathsf{M}_{g3} &= \mathbb{I}(1_3 + \mathsf{x}_3) \mathsf{C}_{23} - \mathsf{y}_3 \mathsf{S}_{23} \mathsf{Jm}_3 \mathsf{g} + \mathbb{I}(1_3 + \mathsf{x}_1) \mathsf{C}_{23} - \mathsf{y}_1 \mathsf{S}_{23} \mathsf{Jm}_1 \mathsf{g} \end{aligned}$$

## 2.2 Equations for the D.C.-motors:

With the notation

$$\begin{array}{lll} \mathsf{M}_{A\,i} & \dots & \text{electromagnetic drivemoment} & (\mathsf{N}.\mathsf{m}) \\ \mathsf{K}_i & \dots & \text{motorconstant} & (\frac{\mathsf{N}.\mathsf{m}}{A}) = (\mathsf{V}.\mathsf{s}) \\ \mathsf{I}_{A\,i} & \dots & \text{armature current} & (\mathsf{A}) \\ \mathsf{L}_{A\,i} & \dots & \text{armature inductivity} & (\frac{\mathsf{V}.\mathsf{s}}{A}) \\ \mathsf{R}_{A\,i} & \dots & \text{armature obm resistance} & (\mathsf{0bm}) \\ \mathsf{U}_{A\,i} & \dots & \text{armature voltage} & (\mathsf{V}) \\ \mathsf{U}_{C\,i} & \dots & \text{control voltage} & (\mathsf{V}) \\ \mathsf{T}_{S\,t,\,i} & \dots & \mathsf{time constant of the motor} & (\mathsf{s}) \\ \mathsf{K}_{S\,t,\,i} & \dots & \mathsf{gain} & (\mathsf{s}) \\ \end{array}$$

the equations for the D.C.-motors are:

$$M_{A_i} = K_i I_{A_i}$$

$$L_{A_i} = \frac{dI_{A_i}}{dt} + R_{A_i} I_{A_i} = U_{A_i} - K_i \sigma_i \quad \text{with } \sigma_i = v_i \dot{\phi}_i$$

$$T_{St,i} = \frac{dU_{A_i}}{dt} + U_{A_i} = K_{St,i} U_{C_i} \qquad (i=1,2,3)$$

(2)

#### 2.3 Data

### 2.3.1 Data for the arm

$y_2 = 0$ $z_2 = 0,20 \text{ m}$ $y_3 = 0$ $z_3 = 0$ $y_L = 0$ $z_L = 0$		$K_{x_1} = 0.00330  \text{m}^2$	$K_{y_L} = 0.196 \text{ m}^2$	$K_{z_L} = 0.192 \text{ m}^2$	K <sub>XL</sub> yL = K <sub>yL</sub> xL = 0	$K_{JL^2L} = K_{ZL^3L} = 0$ $K_{ZL^3L} = K_{X_1^2L} = 0$
$\begin{array}{cccccccccccccccccccccccccccccccccccc$		$K_{x_3} = 0,00130 \text{ m}^2$	$_{3} = 0.0223 \text{ m}^{2}$	$K_{23} = 0.0243 \text{ m}^2$	$K_{33/3} = K_{33x_3} = 0$	$323 = K_2 3 y_3 = 0$ $3 \times 3 = K_3 2_x = 0$
$l_1 = 0.35 \text{ m}$ $l_2 = 0.45 \text{ m}$ $m_2 = 100 \text{ kg}$ $l_3 = 0.20 \text{ m}$ $m_3 = 25 \text{ kg}$ $e = 0$ $m_L = 40 \text{ kg}$	$I_1 = 8.0 \text{ kg.m}^2$	$K_{x_2} = 0.0436  \text{m}^2  \text{K}_{X_1}$			$(x_2y_2 = K_{y_2x_2} = 0 K_{x_1})$	$^{k}$ $^{y_{2}z_{2}}$ $^{z}$ $^{k}$ $^{z_{2}y_{2}}$ $^{z}$ $^{0}$ $^{k}$ $^{y_{3}z_{3}}$ $^{3}$ $^{k}$ $^{z_{3}y_{3}}$ $^{3}$ $^{0}$ $^{4}$ $^{2}$
7. 2. 2.	1,	х х	<sup>₹</sup>	K <sub>22</sub>	, Х2	, y22

## 2.3.2 Data for the D.C.-motors:

for $i = 1,2,3$		•
$K_{i} = 0.167 \text{ V.s}$	gear ratios:	moments of friction: <sup>3</sup> )
$L_{A_1} = 8.10^{-5} \text{ V.s/A}$	$v_1 = 220$	$M_{F_1} = 0.245.sign \dot{\omega}_1 \text{ N.m.}$
$R_{A_i} = 1,50 \text{ Ohm}$	$v_2 = 150$	M <sub>F,</sub> = 0,313.sign oʻz N.m
I <sub>R;</sub> = 0,000235 кg.m <sup>2</sup>	۰ <sub>3</sub> = 130	M <sub>F3</sub> = 0,397.sign φ <sub>3</sub> N.m
T <sub>St,i</sub> = 0,012 s		
$K_{St,i} = 1$		cos a <sub>3</sub> = 1
	$\cos \theta_2 = 0$	$\cos \beta_3 = 0$
		cos r <sub>3</sub> = 0

## $^{3}$ ) Compare the assumption stated in 3.1

#### 3.1 Control task:

Open-loop or closed-loop controls have to be designed for point-to-point movements and for continuous path movements.

The following important assumption is made: whenever a joint angle  $\phi_{\rm i}$  is constant over a time-interval of positive length (i.e. before starting the movement or after reaching its final value), a mechanical brake becomes active and fixes this joint angle. Therefore, from this moment on the i-th equation in (1) and (2) respectively, have to be cancelled.

## 3.1.1. Point-to-point movements.

Initial and final positions  $\phi_i(0)$  and  $\phi_i(t_f)$  are given for i=1,2,3, initial and final joint angular velocities  $\phi_i$  have to equal zero  $(\phi_i(0)=\phi_i(t_f)=0,$  i=1,2,3). The final time  $t_f$  may be given or open (time-optimal control).

Further, bounds

$$|\hat{\phi}_{i}| \le \hat{\phi}_{i}^{*}$$
  $|I_{A_{i}}| \le I_{A_{i}}^{*}$   $|U_{A_{i}}| \le U_{A_{i}}^{*}$   $i = 1,2,3$ 

must not be exceeded for  $0^{\le}t^{\le}t_{f}$ .

In addition command angular velocities may be given as indicated in Fig.3 with  $|\hat{\psi}_i|^{\frac{4}{3}}$ 

## 3.1.2. Continuous path control


A smooth path  $\phi_i(t)$ , i=1,2,3,  $0^{\le}t^{\le}t_f$  is given. The control voltages  $U_{C_i}$  are to be designed such that the actual movement equals the desired one and such that the bounds hold on  $0^{\le}t^{\le}t_f$ .

#### 3.1.3. Data:

$$\dot{\phi}_i^* = \sigma_i$$
, max/ $\nu_i$  with  $\sigma_i$ , max = 314 rad/s
$$I_{A_i}^* = 8 A$$

$$U_{A_i}^* = 65 V$$

Curve in Fig.3:



For variation of mass and position of endeffector with load there are the relations:

$$K_{\chi_{L}} = K_{\chi_{L}} + y_{L}^{2} + z_{L}^{2}$$


$$K_{\chi_{L}} = K_{\chi_{L}} + z_{L}^{2} + (1_{3} + x_{L})^{2}$$

$$K_{\chi_{L}} = K_{\chi_{L}} + z_{L}^{2} + (1_{3} + x_{L})^{2}$$

$$K_{\chi_{L}} = K_{\chi_{L}} + z_{L}^{2} + (1_{3} + x_{L})^{2} + y_{L}^{2}$$

$$K_{\chi_{L}} = K_{\chi_{L}} + (1_{3} + x_{L})^{2} + y_{L}^{2}$$

$$K_{\chi_{L}} = K_{\chi_{L}} + (1_{3} + x_{L})^{2} + y_{L}^{2}$$



symmetric inertial tensor of respect to the axes through endeffector with load with the center of mass c<sub>L</sub> that are parallel to the axes

## 4. Name of Person Submitting Problem

t, 2

φ, i,max

Fig.3.

Prof. Dr. I. Troch, K. Desoyer Technische Universität Wien Karlsplatz 13 A-1040 Wien Austria Tel: (0222) 58801

General	Systems
---------	---------

Problem #90-13 (General Control of a 'Simple' Process)

General

# Problem #90-13 ROBUST CONTROL OF A 'SIMPLE' PROCESS

### (A) General Description

This problem describes a relatively 'simple' problem which can be used for evaluating a general purpose adaptive controller (such as those adaptive controllers which are now commercialized by ASEA (Novatune), Foxboro (Exact), Turnbull (Model 6355), etc.) or any other fixed gain robust controller.

(B) Reference
The formulation of this problem is given in:

Larminat Ph. de., "Adaptive PID Regulators: Ambitions and Limitations", 1988 IFAC Workshop on Robust Adaptive Control, Newcastle, Australia, Aug. 1988.

(C) Problem Description

The system to be controlled is a SISO system described by the following block diagram (see Figure 1):




Figure 1: Adaptive control of a simple process

where the following notation is used:

Notation

$$t = 0, 1, 2, 3, \dots$$

△ : finite difference operator

$$\Delta x(t) = x(t+1) - x(t)$$

control input #(t)

output

set point y(t) : c

load disturbances d(t), c(t) : measurement noise

: level of input saturation = 6

It is desired to find a fixed self-tuning regulator (or any other type of adaptive controller or fixed gain robust controller) to control the largest possible family of plants with the structure as given in Figure 1 such that the closed loop system is stable and "good" tracking/regulation occurs in the system. In particular, it is assumed that the parameters  $K^*, T^*, n, \alpha$  of the plant are uncertain (and possibly are subject to change), and are given as follows:

Discussion

The problem above is a discrete system representation, and can be interpreted when  $n\to\infty$ ,  $\alpha\to0$ ,  $T^*\gg1$ , as being an approximation to a plant with the following transfer function:

$$y(s) = K^* \frac{e^{-sT^*}}{s} u(s)$$

Class of Disturbances/Set Points

(a) It is assumed that b(t) is a coloured noise given by:

$$b(t) = \left(\frac{1}{1 + \Delta \tau}\right) n(t)$$
, where  $\tau \le 0.25 T^*$ 

where n(t) is a sequence of independent elements with zero mean and with variance:

$$V=\sigma_b^2(2\tau-1), \quad \text{where} \quad 0 \le \sigma_b \le 0.2$$

which implies that the variance of b(t) is given by  $\sigma_{\delta}^{2}$ .

- (b) It is assumed that  $y_r(t)$  arises from a class of square waves with amplitude varying from 0 to 10 and with period equal to 207°.
  - (c) The load disturbances c(t) or/and d(t) are assumed to be square waves with amplitude varying from 0 to 5 and with period equal to  $20T^{\circ}$ .

## (D) Name of Person Submitting Problem

Ph. de Larminat IRISA Campus Universitaire de Beaulieu 35042 Rennes Cedex France Tel: (99) 36-2000

#### Prepared and Distributed by

#### INTERNATIONAL FEDERATION OF AUTOMATIC CONTROL Schlossplatz 12, A-2361 Laxenburg, Austria

Copyright © IFAC 1990