

Confidence Score	68
Confidence Level	Medium
Recommended Action	Further Investigation Required
Asset Reference	02iKj00001PJJicIAH
Condition Summary	The asset has registered multiple claim items related to regulator performance, progressing from intermittent issues and fluctuation to complete failure and wiring shorts over a period of approximately two months.
Risk Assessment	The evidence documents a clear progression of a fault related to a component identified as a 'regulator'. The fault escalates from intermittent behavior to degradation and culminates in a complete operational failure and a wiring short. The operational risk is tied to the loss of function of this specific component.
Supporting Evidence	<ul style="list-style-type: none"> • Claim Item CI-PUNE-002-A described an 'intermittent delay' with the regulator. • Claim Item CI-PUNE-002-B described 'performance fluctuation' with the regulator. • Claim Item CI-PUNE-003-A noted 'degradation under load' of the regulator. • Claim Item CI-PUNE-004-A cited 'regulator motor response failure'. • Claim Item CI-PUNE-005-A documented a 'Complete regulator failure under operation'. • Claim Item CI-PUNE-005-B documented a 'Regulator wiring short detected'. • A Work Order (00000276) has been created with a suggested maintenance date of 2026-02-10.