

<b>Confidence Score</b>	68
<b>Confidence Level</b>	Medium
<b>Recommended Action</b>	<b>Further Investigation Required</b>
<b>Asset Reference</b>	<b>02iKj00001PJJicIAH</b>
<b>Condition Summary</b>	The asset has registered multiple claim items related to regulator performance, progressing from intermittent issues and fluctuation to complete failure and wiring shorts over a period of approximately two months.

**Risk Assessment**

The evidence documents a clear progression of a fault related to a component identified as a 'regulator'. The fault escalates from intermittent behavior to degradation and culminates in a complete operational failure and a wiring short. The operational risk is tied to the loss of function of this specific component.

## **Supporting Evidence**

- Claim Item  
CI-PUNE-002-A  
described an  
'intermittent  
delay' with the  
regulator. •  
Claim Item  
CI-PUNE-002-B  
described  
'performance  
fluctuation' with  
the regulator. •  
Claim Item  
CI-PUNE-003-A  
noted  
'degradation  
under load' of  
the regulator. •  
Claim Item  
CI-PUNE-004-A  
cited 'regulator  
motor response  
failure'. • Claim  
Item  
CI-PUNE-005-A  
documented a  
'Complete  
regulator failure  
under operation'.  
• Claim Item  
CI-PUNE-005-B  
documented a  
'Regulator wiring  
short detected'.  
• A Work Order  
(00000276) has  
been created with  
a suggested  
maintenance date  
of 2026-02-10.