

COMPLAINT ANALYSIS REPORT

Generated On: 10-Jun-2026 12:08

Report Type: Complaint Analysis

Executive Summary

This report provides an in-depth analysis of customer complaints received by our company, focusing on key categories and branches. The primary objectives are to identify trends, pinpoint areas for improvement, and assess customer satisfaction levels.

Top Complaint Categories

The following categories represent the most common issues raised by customers:

1. Tyre Wear: 938 complaints
2. Engine Overheating: 871 complaints
3. Battery Issue: 861 complaints
4. Low Mileage: 853 complaints
5. Oil Leakage: 840 complaints
6. Battery Drain: 839 complaints
7. Suspension Noise: 306 complaints
8. Fuel Leakage: 284 complaints
9. Clutch Issue: 283 complaints
10. Brake Noise: 282 complaints

The top three complaint categories ("Tyre Wear," "Engine Overheating," and "Battery Issue") together account for a significant portion of the total complaints, indicating areas that require immediate attention.

Branch Analysis

Complaints are distributed across various branches:

1. Tallakulam: 419 complaints
2. Porur: 418 complaints
3. Saibaba Colony: 399 complaints
4. Anna Nagar Madurai: 393 complaints

5. KK Nagar Trichy: 387 complaints
6. Thillai Nagar: 382 complaints
7. Suramangalam: 379 complaints
8. RS Puram: 378 complaints
9. Ammapet: 375 complaints
10. Omalur: 374 complaints
11. KK Nagar: 374 complaints
12. Tambaram: 370 complaints
13. Anna Nagar: 366 complaints
14. Thirunagar: 365 complaints
15. T Nagar: 364 complaints
16. Fairlands: 363 complaints
17. Peelamedu: 356 complaints
18. Hasthampatti: 355 complaints
19. Velachery: 345 complaints
20. Woraiyur: 333 complaints
21. Gandhipuram: 332 complaints
22. Cantonment: 323 complaints
23. Singanallur: 302 complaints
24. Srirangam: 298 complaints
25. Mattuthavani: 296 complaints

Porur and Tallakulam are the branches experiencing the highest volume of complaints, suggesting potential operational challenges or service issues in these areas.

High Priority Issues

Based on customer feedback and complaint severity, the following issues require immediate attention:

1. Engine Overheating: 871 complaints
2. Fuel Leakage: 284 complaints
3. Brake Failure: 272 complaints

These issues are critical as they directly affect vehicle safety and operational efficiency. Prompt resolution of these complaints can help restore customer trust and satisfaction.

Customer Satisfaction

The average customer rating for our service is 3.44 on a scale of 1 to 5, indicating that while there is room for improvement, overall customer satisfaction remains generally satisfactory.

Recommendations

To address the identified issues effectively:

1. Enhance Tyre Quality: Implement stricter quality checks and regular maintenance schedules to reduce tyre wear.
2. Improve Engine Cooling Systems: Invest in engine cooling system upgrades or replacements to prevent overheating issues.
3. Resolve Battery Problems Promptly: Increase staff training on battery diagnostics and repair techniques.
4. Invest in Fuel System Maintenance: Regularly inspect and maintain fuel systems to minimize leakage.
5. Fix Clutch Issues: Provide more frequent maintenance checks for clutch mechanisms, especially in high-volume branches like Porur and Tallakulam.
6. Address Brake Noise: Conduct comprehensive brake inspections and provide necessary repairs to ensure safety.
7. Monitor High-Volume Branches: Implement additional resources or training at Porur and Tallakulam to manage the higher complaint volumes.

By focusing on these areas, our company can significantly improve customer satisfaction and operational efficiency.