

| Category | Complaints |

|||

| Tyre Wear | 938 |

| Engine Overheating | 871 |

| Battery Issue | 861 |

| Low Mileage | 853 |

| Oil Leakage | 840 |

| Battery Drain | 839 |

| Suspension Noise | 306 |

| Fuel Leakage | 284 |

| Clutch Issue | 283 |

| Brake Noise | 282 |

BRANCH COMPLAINT VOLUME

| Branch | Complaints |

|||

| Tallakulam | 419 |

| Porur | 418 |

| Saibaba Colony | 399 |

| Anna Nagar Madurai | 393 |

| KK Nagar Trichy | 387 |

| Thillai Nagar | 382 |

| Suramangalam | 379 |

| RS Puram | 378 |

| Ammapet | 375 |

| Omalur | 374 |

HIGH PRIORITY ISSUES

| Category | Complaints |

|||

| Engine Overheating | 871 |

| Fuel Leakage | 284 |

| Brake Failure | 272 |

CUSTOMER SATISFACTION

Average Rating: 3.44

SUMMARY

- Tyre wear, engine overheating, and battery issues are the top complaints.
complaints.

- Tallakulam has the highest volume of complaints.
- Engine overheating is the only high-priority complaint.

RECOMMENDATIONS

- Focus on improving tyre and battery quality to reduce customer issues.
- Allocate more resources to Tallakulam branch to handle its high complaint volume.
- Address engine overheating issues promptly to ensure customer satisfaction.