

COMPLAINT ANALYSIS REPORT

Executive Summary

The analysis of customer complaints has revealed significant areas for improvement within our fleet operations. The most frequently reported categories include Tyre Wear, Engine Overheating, Battery Issue, and Low Mileage. Among all branches, Tallakulam and Porur have the highest volume of complaints, indicating potential operational issues in these regions.

High priority issues such as Engine Overheating, Fuel Leakage, and Brake Failure are critical areas that need immediate attention to ensure customer safety and satisfaction. The average customer rating of 3.44 suggests there is room for enhancement in service quality.

The findings from this report will help us prioritize our efforts towards resolving the most pressing issues and enhancing overall customer experience.

Top Complaint Categories

1. Tyre Wear (938 complaints)
2. Engine Overheating (871 complaints)
3. Battery Issue (861 complaints)
4. Low Mileage (853 complaints)
5. Oil Leakage (840 complaints)
6. Battery Drain (839 complaints)

These categories collectively account for 5,210 out of the total complaints, highlighting their significance in customer dissatisfaction.

Branch Analysis

1. Tallakulam (419 complaints)
2. Porur (418 complaints)
3. Saibaba Colony (399 complaints)
4. Anna Nagar Madurai (393 complaints)
5. KK Nagar Trichy (387 complaints)

The top branches with the highest volume of complaints suggest that there may be operational inefficiencies or service issues in these areas, warranting further investigation.

High Priority Issues

1. Engine Overheating (871 complaints)
2. Fuel Leakage (284 complaints)
3. Brake Failure (272 complaints)

These critical issues require immediate attention to ensure customer safety and satisfaction.

Customer Satisfaction

The average customer rating of 3.44 indicates a generally satisfactory experience but also suggests areas for improvement. A higher average rating would indicate that customers are more satisfied with the services provided, which can drive loyalty and positive word-of-mouth recommendations.

Recommendations

1. Improve Tyre Maintenance: Given the high volume of complaints related to tyre wear, invest in regular maintenance programs to extend the lifespan of tyres and reduce customer dissatisfaction.
2. Enhance Engine Overheating Prevention: Address the root causes of engine overheating by performing routine checks and ensuring that cooling systems are functioning correctly. Implement training for staff on proper maintenance techniques.
3. Fix Fuel Leakage Issues: Tighten fuel tank connections, replace damaged hoses, and ensure that refueling operations are conducted safely to minimize fuel leakage complaints.
4. Focus on Brake Maintenance: Address brake issues promptly to prevent accidents and customer injuries. Invest in high-quality braking systems and provide regular service checks.
5. Invest in Customer Training: Train staff on proper vehicle maintenance techniques and troubleshooting common issues to reduce the volume of complaints.
6. Improve Branch Operations: Analyze the performance of branches with the highest complaint volumes and identify operational inefficiencies. Implement targeted improvements such as better inventory management, faster response times, and enhanced customer service.
7. Customer Feedback Loop: Establish a robust system for collecting customer feedback to promptly address issues and make data-driven decisions.

By implementing these recommendations, we can significantly reduce the number of complaints and improve overall customer satisfaction. This will lead to increased loyalty, reduced operational costs, and a positive reputation in the market.

Prepared by:

[Your Name]

Senior Business Analyst