

Executive Summary

The complaint analysis report provides a comprehensive overview of customer dissatisfaction. Tyre Wear is the most common complaint, followed

by Engine Overheating and Battery Issue. Tallakulam branch has seen the highest volume of complaints, closely followed by Porur. Engine Overheating, Fuel Leakage, and Brake Failure are classified as high priority issues requiring immediate attention. The average customer rating stands at 3.44.

Branch Analysis

Tallakulam and Porur branches have the highest complaint volumes, indicating potential operational or service-related issues that need to be

addressed. Saibaba Colony, Anna Nagar Madurai, and KK Nagar Trichy also exhibit high complaint levels, suggesting a need for targeted improvement efforts.

High Priority Issues

Engine Overheating, Fuel Leakage, and Brake Failure are critical concerns requiring urgent attention. These issues can severely impact customer satisfaction and safety on the road. Immediate steps should be taken to diagnose and resolve these problems promptly.

Customer Satisfaction

The average customer rating of 3.44 indicates a moderate level of customer satisfaction. While there is room for improvement, efforts should focus on addressing high-priority complaints to enhance overall customer experience.

Recommendations

1. Conduct a thorough review of Tallakulam and Porur branch operations to identify root causes of frequent complaints.

2. Implement immediate fixes for Engine Overheating, Fuel Leakage, and Brake Failure to improve safety and satisfaction levels.
3. Launch targeted improvement programs in Saibaba Colony, Anna Nagar Madurai, and KK Nagar Trichy.
4. Increase customer communication during service repairs to update them on progress and expected completion times.
5. Regularly collect customer feedback to monitor progress and make necessary adjustments.

By addressing these areas, we can enhance customer satisfaction and ultimately improve the overall reputation of our services.