

COMPLAINT ANALYSIS REPORT

Generated On: 10-Jun-2026 11:28

Report Type: Complaint Analysis

Executive Summary

The complaints data indicates a range of issues affecting customers across multiple branches. The top complaint categories include Tyre Wear, Engine Overheating, and Battery Issue. Notably, these issues have been consistently high over the analysis period. Additionally, there is a notable drop in complaints related to Suspension Noise, indicating potential improvements in this area.

Branch-wise analysis reveals that Tallakulam and Porur branches are experiencing the highest number of complaints, closely followed by Saibaba

Colony and Anna Nagar Madurai. These locations require immediate attention to minimize customer dissatisfaction and improve service quality.

The high priority issues identified include Engine Overheating, Fuel Leakage, and Brake Failure. Addressing these will have a significant impact on overall customer satisfaction and loyalty.

Customer ratings average at 3.44 out of 5, indicating room for improvement in areas such as Engine Overheating, which has the lowest rating with an average score of 2.97.

Top Complaint Categories

The most frequent complaints are categorized as follows:

1. Tyre Wear (938 complaints)
2. Engine Overheating (871 complaints)
3. Battery Issue (861 complaints)
4. Low Mileage (853 complaints)
5. Oil Leakage (840 complaints)

These top categories highlight areas of significant concern for customers, and their resolution is critical to improving the overall service quality.

Branch Analysis

The complaint volume across various branches is as follows:

1. Tallakulam (419 complaints)
2. Porur (418 complaints)
3. Saibaba Colony (399 complaints)
4. Anna Nagar Madurai (393 complaints)
5. KK Nagar Trichy (387 complaints)

Branches like Tallakulam and Porur are experiencing the highest number of complaints, suggesting potential areas for operational review or resource allocation.

High Priority Issues

The following issues have been identified as high priority due to their volume and severity:

1. Engine Overheating (871 complaints)
2. Fuel Leakage (284 complaints)
3. Brake Failure (272 complaints)

Addressing these issues promptly will help in reducing customer dissatisfaction and improving service quality.

Customer Satisfaction

The average customer rating is 3.44 out of 5, which suggests that while there is room for improvement, customers generally find satisfaction with the services provided. However, specific areas such as Engine Overheating have lower ratings (average score of 2.97), indicating significant dissatisfaction in these aspects.

Recommendations

1. Enhance Service Quality:
 - Focus on resolving high priority issues like Engine Overheating and Brake Failure more efficiently.
 - Improve customer satisfaction by addressing fuel leakage, a critical issue affecting multiple branches.
2. Branch Specific Improvements:
 - Tallakulam and Porur require immediate attention to reduce their complaint volume. Implement targeted training or allocate additional resources in these areas.
 - Regularly monitor service levels at Saibaba Colony and Anna Nagar Madurai to maintain high standards of customer satisfaction.

3. Customer Engagement:

- Conduct regular surveys to gather more detailed feedback from customers.
- Use customer feedback to continuously improve service offerings and address emerging issues proactively.

4. Operational Optimization:

- Review maintenance schedules and procedures to ensure timely service delivery.
- Implement preventive measures to reduce the occurrence of common complaints like Tyre Wear and Battery Issues.

By implementing these recommendations, we can enhance customer satisfaction and loyalty, ultimately improving our brand reputation and market position.

Prepared By:

[Your Name]

Senior Business Analyst

[Date]