

COMPLAINT ANALYSIS REPORT

EXECUTIVE SUMMARY

The analysis of customer complaints for the past period highlights significant areas of concern that need urgent attention from our operations and engineering teams. The report is structured to provide a comprehensive overview of top complaint categories, branch-wise distribution, high-priority issues, and customer satisfaction levels.

Top Complaint Categories:

- Tyre Wear
- Engine Overheating
- Battery Issue
- Low Mileage
- Oil Leakage

These categories indicate that the primary areas where our customers are facing difficulties, which could lead to significant downtime, inconvenience, and potentially negative reviews.

High Priority Issues:

- Engine Overheating
- Fuel Leakage
- Brake Failure

The high volume of these complaints underscores their critical nature and demands immediate action to prevent further customer dissatisfaction and potential business loss.

Customer Satisfaction:

The average customer rating of 3.44 suggests a moderate level of satisfaction, indicating that there is room for improvement in various aspects of our service offerings.

TOP COMPLAINT CATEGORIES

Based on the data provided, the most frequent complaints are as follows:

1. Tyre Wear (938): This indicates a significant problem with vehicle maintenance and tire management.
2. Engine Overheating (871): The engine overheating issue affects not only customer satisfaction but also operational efficiency.

3. Battery Issue (861): Battery problems are frequent, impacting driving safety and convenience.
4. Low Mileage (853): This suggests inefficiency in fuel consumption or vehicle performance.
5. Oil Leakage (840): Leaking oil can cause serious damage to the engine and requires prompt attention.

These top categories indicate that our customers are experiencing consistent issues, which could lead to a decline in customer satisfaction if not addressed promptly.

BRANCH ANALYSIS

The complaints are distributed across various branches:

1. Tallakulam (419)
2. Porur (418)
3. Saibaba Colony (399)
4. Anna Nagar Madurai (393)
5. KK Nagar Trichy (387)

It's notable that Tallakulam and Porur are experiencing the highest number of complaints, which could indicate localized issues such as higher traffic congestion or maintenance challenges.

HIGH-PRIORITY ISSUES

The following issues are listed as high priority based on their volume:

1. Engine Overheating (871)
2. Fuel Leakage (284)
3. Brake Failure (272)

These issues demand immediate attention from our operations and engineering teams to ensure the safety and reliability of our vehicles.

CUSTOMER SATISFACTION

The average customer rating of 3.44 suggests a need for improvement. This score indicates that while customers are generally satisfied, there is room for enhancing various aspects of our service and product offerings.

RECOMMENDATIONS

1. Enhance Maintenance Procedures:

Implement stricter adherence to maintenance schedules, especially for tires and batteries, to reduce the frequency of such complaints.

2. Improve Engine Cooling Systems:

Develop and implement more effective cooling systems or regular inspections to prevent engine overheating issues.

3. Focus on Safety Features:

Address brake failure concerns by ensuring that all vehicles undergo regular safety checks and potentially updating brake systems.

4. Customer Education:

Provide comprehensive training for customers on routine vehicle maintenance and proper driving techniques to reduce the occurrence of low mileage and oil leakage issues.

5. Address Branch-Specific Issues:

Conduct site visits at Tallakulam and Porur to identify localized issues and implement corrective measures.

6. Customer Feedback Mechanism:

Establish a more robust feedback mechanism to promptly address customer concerns and ensure that high-priority issues are prioritized.

By addressing these areas, we can enhance customer satisfaction and improve the overall quality of our services and products.

Prepared by:

[Your Name]

Senior Business Analyst

[Your Contact Information]