
Allocation ratio
Speedup
Runtime speedup
Memory allocation ratio
70
60
50
40
30
20
10
0
5
4
3
2
1
0
5k
10k
30k
50k
100k
300k
500k
1M
3M
5M
Number of isochromats in the reference phantom