
Allocation ratio
Speedup
Runtime speedup
Memory allocation ratio
0
0.5
1
1.5
2
2.5
3
0.2
0.4
0.6
0.8
1
1.2
1.4
5k
10k
30k
50k
100k
300k
500k
1M
3M
5M
10M
Number of isochromats in the reference phantom