
Allocation ratio
Speedup
Runtime speedup
Memory allocation ratio
0
2
4
6
8
10
0
0.5
1
1.5
2
10k
30k
100k
300k
1M
3M
Number of isochromats in the reference phantom