
spin axis
Ω
flapwise (out of plane)
$W(\xi)$
$\xi = y/L$
r_H
hub
undeformed beam axis (in plane of rotation)
$\xi = 0$
$\xi = 1$