




PICO INTERACTIVE INSTRUCTION MANUAL

You can navigate through chapters by clicking on the tabs here.

Clicking on the PicoBrew logo will take you back to the Table of Contents.

PicoBrew

Produced by:
PicoBrew Inc.
2121 N 35th St.
Seattle, WA 98103

www.picobrew.com


© 2019 PicoBrew

All rights reserved. No part of this publication may be reproduced, stored in retrieval systems or transmitted in any form or by any means electronic or mechanical, including photocopying, record or any information storage and retrieval systems, without the written permission in writing from the copyright owners.

Printed and bound in Seattle, WA, USA

PICO INSTRUCTION MANUAL



CRAFT
BEER
YOUR
WAY.



IMPORTANT SAFETY INFORMATION

- Exercise common sense while operating the Pico.
- Always use the keg cozy to shield the hot metal of the keg.
- Close supervision is needed when used around children.
- Allow machine to fully cool before removing or replacing parts.
- Do not operate with a frayed cord or broken plug.
- Do not remove Step Filter from the Pico unless in pause mode or brew cycle is completed.
- The Step Filter and contents may be hot when removing from the machine.
- Do not immerse or soak the machine.
- Make sure all hoses are connected properly before starting a brewing, rinse, or cleaning cycle.
- To avoid risk of electrical shock hazard do not disassemble the Pico. There are no user serviceable parts inside.
- Various surfaces can get extremely hot during the brewing cycle, use caution when handling the keg, hoses and components.
- Do not remove the hose clamps, hot liquid spray may result.
- Do not remove the keg attachments while brewing.
- The product is intended for household use only.
- The appliance is not to be used, or played with, by children.
- The appliance is not to be used by persons with reduced physical, sensory or mental capabilities, or lack of experience and knowledge, unless they have been given supervision or instruction.
- If the power supply cord is damaged, it must be replaced by the manufacturer, its service agent or similarly qualified person in order to avoid a hazard.

- Per FCC 15.19(a)(3) and (a)(4) This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.
- Per FCC 15.21 Change or Modifications that are not expressly approved by the manufacturer could void the user's authority to operate the equipment.
- Per RSS-Gen, Section 8.4 This device complies with Industry Canada license-exempt RSS standard(s). Operation is subject to the following two conditions: (1) this device may not cause interference, and (2) this device must accept any interference, including interference that may cause undesired operation of the device.
- Par RSS-Gen, Section 8.4 Cet appareil est conforme à Industrie Canada exempts de licence standard(s) RSS. Le fonctionnement est soumis aux deux conditions suivantes: (1) ce dispositif ne peut pas provoquer d'interférences et (2) cet appareil doit accepter toute interférence, y compris les interférences qui peuvent causer un mauvais fonctionnement de l'appareil.






TABLE OF CONTENTS


INTRODUCTION	8
UNBOXING	10
SETUP	21
FIRST RINSE	29
LET'S BREW	39
AFTER BREWING	51
FERMENTATION	61
DRY HOPPING	77
RACK & CARBONATE	83
SERVING	119
USAGE & CARE	127
SOUS VIDE ADAPTER INSTRUCTIONS	175
GLOSSARY	191

**WELCOME
TO THE
EASIEST
COUNTERTOP
BREWING
APPLIANCE,
EVER.**

**SERIOUSLY.
IT'S REALLY
EASY TO USE.**



**THIS IS YOUR NEW
BEST FRIEND.
(IT MAKES BEER)**



PICO UNBOXING GUIDE

CONGRATULATIONS!


You are about to experience the joy of homebrewing using Pico, the most advanced homebrewing appliance in the world! We know you're eager to get started so let's make sure you have everything to brew and that each item arrived in perfect condition.

Inside your Pico system box you will find 5 smaller boxes:

- Pico Appliance
- Accessories
- 1 PicoPak
- 1 Serving Keg
- 1 Brewing Keg

Note: Some international units may have the Plug Adapter located inside the main shipper box instead of attached to the Pico unit itself.

BOX 3




(A) RACKING TUBE

For transferring your beer from Brewing to Serving Keg.




(B) KEG COZY

To keep your keg warm during brewing.



(C) BLACK KEG WANDS (2)

Attaches to the Racking Tube and Ball Lock Connector hoses for the Rinse cycle and cleaning.




(D) KEG SEAL

Used on Brewing Keg while brewing and during Standard Fermentation.



(E) KEG SEAL STOPPER

Fits in Keg Seal vent hole, used only after brewing cycle is completed



(F) CO₂ REGULATOR


To force carbonate your beer.

This is not used if you are Keg Conditioning.




(G) DIP TUBE BRUSH

To clean your Brewing Keg Dip Tubes and Keg Posts.


**(H) KEG BRUSH**

To clean your Brewing Keg and Serving Keg.

**(I) CO₂ CARTRIDGES (5)**

Used with the CO₂ regulator.

This is not used if you are Keg Conditioning. Some addresses do not allow compressed air deliveries.

**(J) AIRLOCK**


For your Brewing Keg during Standard Fermentation.

**(K) HOPS PAK CRADLE**

The cradle for your Hops Pak, used during the brewing cycle.


**(L) CLEANING TAB**

Used when Deep Cleaning to thoroughly clean your Pico after every 3 brew sessions.

**(M) SOUS VIDE ADAPTER**

Used in Step Filter for sous vide.

BOX 4



(N) GRAIN PAK

Grain and water amendments for your mash.



(O) HOPS PAK

*Hops for the boil cycle.



(P) YEAST PACKET

Dry yeast for fermentation.



(Q) PICOPAK KEG LABEL

Stick to Serving Keg to brand finished beer.



(R) CARBONATION SUGAR PACKET

To Keg Condition, Naturally Carbonate, your beer. **This is not used if you Force Carbonate.**



(S) DRY HOP SACHET

*If included, found inside Yeast Box in PicoPaks that have an additional dry hopping step. Store in your refrigerator.

BOX 5



(T) DISPENSING BUNG PLUG

Used on the Serving Keg during serving or if doing Keg Conditioning.



(U) CARBONATION ADAPTER

For your Serving Keg during Forced Carbonation. Not used if Keg Conditioning.



(V) SERVING KEG

For serving your beer.


*** THE HOPS PAK ARRIVES VACUUM-SEALED TO ENSURE FRESHNESS. IF YOU WON'T START BREWING TODAY, KEEP THE HOPS PAK AND DRY HOPS SACHET IN YOUR REFRIGERATOR FOR BEST RESULTS.**

BOX 6



(W) BREWING KEG

For brewing and fermenting your beer.



(X) METAL KEG LID

Attach to Brewing Keg.



(Y) RED FAST FERMENTATION ADAPTER

For your Brewing Keg during Fast Fermentation.



(Z) FERMENTATION TEMP DECAL

(1) Ale decal. Attach to Brewing Keg to monitor fermentation temperature. Can be re-used for 3 batches.

DOUBLE CHECK YOUR SUPPLIES AND INVENTORY.

If any boxes look damaged or parts appear to be missing, please contact us immediately anytime via email at info@picobrew.com. We're here for you and want you to have a great Pico brewing experience!

YOU WILL NEED:


- Wi-Fi connection (used in: **Setup, Let's Brew**)
- Access to an internet browser
- 3 gallons of distilled or reversed osmosis filtered water (used in: **First Rinse, Let's Brew**)
- Access to clean tap water
- Sterile water or vodka (used in: **Ferment**)
- 1.5 cups of 3% Hydrogen Peroxide (used in: **Rack & Carbonate**)
- Large bowl, bucket, or other waste container (used in: **After Brewing, Rack & Carbonate**)
- Fragrance-free powdered dishwashing detergent (used in: **Usage & Care**)

PICO SETUP

**ESTIMATED TIME:
5 MINUTES**


1

Remove the red packing tape and gray protective film from your Pico.




2

Plug the power cord into a standard grounded household outlet. Press the power button to turn on your Pico.



3

Connect to your home WiFi network by selecting it with the Control Knob, then enter your WiFi password. Once you enter your password, select the OK icon.




4

Once connected, note the registration code displayed on screen.

Go to: **www.picobrew.com/newpico** Sign in to your account or create an account if you do not already have one, and enter the registration code displayed on your Pico.

Add or update your address under account settings before registering your Pico.



**NOW IT'S
TIME TO
GIVE YOUR
PICO THE
FIRST
RINSE.**

**AFTER THAT
YOU ARE
READY TO
BREW!**

PROCEED TO NEXT SECTION: FIRST RINSE

FIRST RINSE

ESTIMATED TIME:
10 MINUTES

YOU WILL NEED:

- 0.5 gallon distilled water (or reverse osmosis)
- Keg Seal
- Brewing Keg
- Keg Wand

IAN'S PRO TIP:

**Clean equipment is critical
to crafting great beer.**


This first rinse ensures you
start brewing with a sparkling
clean Pico and accessories.

1

After connecting up your Pico to the internet, rinse the Brewing Keg, Keg Seal, Step Filter, and lid with tap water. The Step Filter is located in the front of your Pico. To remove it lift it up and slide it out. After rinsing the Step Filter and lid slide them back into the Pico until the Step Filter clicks into place.

Set the Keg Seal Stopper aside, this will not be needed until after the brew session is finished.


Note: Make sure that when you remove the metal lid from your keg that the white O-ring is not left behind on the inside lip of the keg opening.



2


Check that the Water Reservoir stopper is in place. This is located in the Water Reservoir in the center back area. Add 0.5 gallon (or 8 cups) of distilled water to the Water Reservoir. Add about 2" of clean tap water to the Brewing Keg. Place black Keg Seal over the opening of Brewing Keg and press into the center of it until it pops into place.

Note: If using tap water inside the Pico Water Reservoir, remember to descale every 20 brews. (**Usage & Care:** Pico Descal). Tap, distilled, or reverse osmosis water is fine inside the Brew Keg. Using heavily chlorinated water can cause off flavors in finished product.




3

Locate the post on the Brewing Keg marked "OUT" – locate the BLACK Ball Lock Connector on the end of the hose. Pull up on the outer plastic ring of the BLACK Ball Lock Connector, place the Connector on the OUT keg post, release outer plastic ring and press down firmly on Ball Lock Connector. Press down on the Connector until it audibly clicks into place. Repeat this procedure with the GRAY Ball Lock Connector on the keg post marked "IN".




4


Use the Control Knob to select Utilities. Press Control Knob to select **First Rinse**. After approximately 5 minutes the Pico First Rinse Cycle will complete.




5 There will be approximately 1-2 inches of water in your Brewing Keg and the same amount in the Step Filter. The Water Reservoir will still contain almost all of the water you put in originally. Disconnect the Ball Lock Connectors from Brewing Keg by pulling up on the outer plastic rings and lifting up off of Brewing Keg posts.



- 6** Connect a clean Keg Wand to the BLACK Ball Lock Connector by pulling up on the outer ring of the Connector and inserting Keg Wand, release outer ring and make sure it is securely connected to Connector. Press Control Knob to begin pumping water out of Water Reservoir and into the Step Filter. Follow on-screen instructions and press Control Knob between steps. Press Control Knob when the Water Reservoir is empty.



7 The Inline Filter is a black plastic cylinder in the middle of the Black Ball Lock Connector hose. Unscrew and remove the Inline Filter cap. Remove the blue Inline Filter wire mesh insert and rinse it thoroughly using tap water. Place the Inline Filter mesh insert back into the Inline Filter and screw the filter cap back on, finger tight. This step should be performed after every Rinse Cycle to ensure cleanliness and longevity of your Pico.





Empty your Brewing Keg and Step Filter. Rinse Brewing Keg, Step Filter, Keg Seal, and Keg Wand.

You are now ready to begin your first Pico brew session!

If you experience any problems during your First Rinse, brewing session, or any other step of the process please visit www.picobrew.com/Help or contact us immediately at info@picobrew.com.

LET'S BREW


**ESTIMATED TIME:
HANDS ON 10 MINUTES
(TOTAL TIME: 2.5 HOURS)**

YOU WILL NEED:

- PicoPak
- 2.5 gallons distilled water (or reverse osmosis)
- Hops Cradle
- Racking Tube (optional)
- Brewing Keg
- Black Keg Seal
- Keg Cozy


1

Remove the vacuum-sealed wrapping and insert the Pico Hops Pak all the way into the metal Hops Pak Cradle. The fingers of the Cradle fit in the grooves of the Hops Pak.




2A

Unwrap and set the Grain Pak in the front of the Pico Step Filter, with the beer design facing the front. Place Hops Pak and Cradle in the rear of the Step Filter, pushed all the way to the left.




2B

Cover the Step Filter with the lid, with the black Steam Deflector in the front and facing up. When putting the Step Filter lid on make sure all lid holes match up to all Hops Pak holes.




3 Open the top of the clean Brewing Keg and set the plastic Racking Tube in the keg center to use as a water level gauge. Add distilled water until it reaches the spot on the Racking Tube where the hose attaches. (Alternatively, you can measure out 1 gallon plus 6 cups or 11.6 lbs of distilled water.) Remove the Racking Tube and set it aside to dry, you will not use the Racking Tube again during the brewing session. Set the rubber Keg Seal on the keg opening and press seal into the center of the keg until it pops into place, sealing the keg.




4 Slide the Keg Cozy over the Brewing Keg. Attach the Pico hose with the Black Ball Lock Connector to the post on the Brewing Keg marked “OUT”. Pull up on the outer plastic ring of the BLACK Ball Lock Connector, place the Connector on the OUT keg post, release outer plastic ring and press down firmly on Ball Lock Connector. Continue to press down on the Connector until it audibly clicks into place. Repeat this procedure with the GRAY Ball Lock Connector and the keg post marked “IN”.

Note: Do not use the Metal Keg Lid while brewing, only use the rubber Keg Seal. Make sure the white stopper is not inserted in the Keg Seal center hole while brewing.




- 5** Remove the Water Reservoir lid from the top of the Pico. Look inside and check to make sure the black rubber Drain Plug is secured inside the reservoir drain located in the center of the back of the reservoir. Fill the reservoir with approximately one gallon of distilled water. Replace the Water Reservoir lid.

Note: If using tap water inside the Pico Water Reservoir, remember to descale every 20 brews. (**Usage & Care:** Pico Descal). Tap, distilled, or reverse osmosis water is fine inside the Brew Keg. Using heavily chlorinated water can cause off flavors in finished product.



6

Press the Power Button on the front of the Pico. The display will illuminate. Select Brew PicoPak and press the Control Knob. The Pico will automatically detect and display the PicoPak.



7

You can optionally change a beer's alcohol percentage and bitterness from the PicoPak defaults. To do so, turn Control Knob to the right when screen says "Start Brewing". This will give you the ability to adjust the alcohol and bitterness. Once finished, you can select Start Brewing by pressing the Control Knob and your brew session will begin.

Note: This option is only available for select PicoPaks at this time.

8

Pico will begin brewing and complete in approximately 2-3 hours, depending on the beer recipe and any adjustments you might have made. You do not need to monitor the Pico during the brew session.

Notes:

- You can track the progress by signing in at **www.PicoBrew.com** and clicking on **BrewHouse**.
- During brew session some foam on the Keg Seal is normal, particularly during a drain cycle. You can wipe it off with a clean damp paper towel.
- It is normal for only a small amount of liquid to show in the bottom of the Step Filter during brewing.
- Pico heats the water using steam, and occasional hissing or growling noises are normal. Don't worry, Pico is not upset, only heating!

PROCEED TO NEXT SECTION: AFTER BREWING

**CONGRATS!
YOU CAN
NOW
SIT BACK,
RELAX
AND
ENJOY
YOUR
FIRST
BREW
CYCLE.**

GOOD JOB.

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

AFTER BREWING

**ESTIMATED TIME:
HANDS ON 9 MINUTES
(TOTAL TIME: 24 HRS)**


YOU WILL NEED:

- Keg Seal Stopper
- Keg Wands
- Waste container
(needs to hold approximately one gallon of liquid)

1 After brewing finishes, disconnect both of the Ball Lock Connectors from the Brewing Keg by pulling up on the outer plastic ring of each Ball Lock Connector and then pulling the Connector off of the post.

Wipe away any foam off the Keg Seal using a damp paper towel. Insert the Keg Seal Stopper into the center hole of the Black Keg Seal so that the keg is airtight. Remove the Keg Cozy from the Brewing Keg.


Note: The Brewing Keg will be very HOT so please be careful and only touch the keg's black rubber handles.



2

Set the Brewing Keg aside to cool overnight to room temperature. It is normal for the Keg Seal to suction slightly into the Brewing Keg as it cools, don't worry it will not be pulled all the way inside. You will need to pitch the yeast within 24 hours after brew session is completed.

Now remove the Step Filter from the Pico and dump the biodegradable PicoPak into a compost bin. **Remember to keep the Metal Hops Cradle and set it aside for future brewing sessions.**



ANNIE'S PRO TIP:


Be careful!!

The Hops Cradle is hot directly after brewing. Give it chance to cool before you touch it.

PicoPaks fit perfectly into an 9"x13" baking dish. Flip the Step Filter upside down so the PicoPak goes into dish upside down, use tongs to take the metal Hops Pak Cradle out to reuse for future brewing sessions. Use the dish to carry the PicoPak to your compost bin!


3 Rinse the Step Filter and lid with clean tap water. Fill the clean Step Filter with approximately 1 inch of tap water. Insert the Step Filter and lid back into the Pico until it clicks.

For each Ball Lock Connector, pull up on the outer ring of the Connector and insert a Keg Wand. Release the ring and make sure it is properly connected to the Keg Wand.




TAP WATER

- 4** Direct the end of the GRAY Ball Lock Connector ("IN") Keg Wand into a waste container or directly into a sink nearby. Press the Control Knob to start Rinse Cycle. Pico will clear the drain line into the waste container, then prompt you to empty the reservoir.




BILL'S PRO TIP:

Make sure you use a big enough waste water container! The gallon water jug you used to fill the machine is perfect for this use.




- 5** Insert the end of the BLACK Ball Lock Connector ("OUT") into the Water Reservoir. Press the Control Knob to run the pump until the Reservoir has drained. The water will be deposited into the Step Filter. To stop the pump press the Control Knob when the Reservoir is empty. Now press the power button on the Pico to turn it off.



- 6** Unscrew and remove the Inline Filter cap. Remove the blue filter insert and rinse it thoroughly using tap water. Place it back in the Inline Filter and screw the filter cap back on, finger tight.

JACK'S PRO TIP:

Cleaning the Inline Filter after every brew session is very important and will lengthen the life of your Pico!



7 Remove the Keg Wands from the Ball Lock Connectors by pulling up on the outer plastic rings. Remove the Step Filter and lid from the Pico and rinse thoroughly with tap water, they are both dishwasher safe.

Note: Do NOT use the Heat Dry or Sanitize option on your dishwasher. Condensation or Air Dry options are fine to use.

**PROCEED TO NEXT SECTION:
FERMENTATION**

**AWESOME!
IT WOULD
APPEAR
THAT
YOUR PICO
IS CLEAN
AS A
WHISTLE.**

**A CLEAN MACHINE
MEANS BETTER
BREWING.**

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

**AFTER
BREWING**

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

FERMENT YOUR BEER

**ESTIMATED TIME:
6 MINUTES**

YOU WILL NEED:

- Your keg of brewed wort, cooled to room temperature
- Fermentation Temperature Decal
- Yeast Packet
- Clean, sanitized whisk

FOR FAST FERMENTATION:

- Metal Keg Lid
- Red Fast Fermentation Adapter


FOR STANDARD FERMENTATION:

- Black Keg Seal
- Air Lock
- Sterile water or vodka

1

After brewing, allow the Brewing Keg to cool to room temperature, this may take up to 24 hours depending on ambient temperature.

Stick the Fermentation Temperature Decal on the outside of the cooled Brewing Keg. Do not stick the Fermentation Temperature Decal on the Brewing Keg if it is still warm.



2

Remove the black Keg Seal and Stopper from the Brewing Keg.

Open the provided Yeast Packet and slowly sprinkle **half** of the yeast in the packet into the Brew Keg. You do not need to stir the yeast into the wort.

If a recipe card came with your PicoPak, make sure to check for any special instructions regarding exact amount of yeast to pitch. For additional fermentation options, see details on the yeast packet.

Note: Yeast should be pitched within 24 hours of brewing session.

3

REFER TO THE FERMENTATION TEMPERATURE DECAL:

FOR FAST FERMENTATION

(See steps 4-7) Confirm that the Red Fast Fermentation Adapter is installed in the Metal Keg Lid. The wort can properly ferment at any temperature in the Fast Fermentation range indicated on the decal, however you only speed up fermentation by keeping the keg temperature at the higher end of the range, above standard fermentation temperatures.

FOR STANDARD FERMENTATION:

(See steps 8-11) Confirm that a Keg Seal and Air Lock are installed on the Brewing Keg. The wort can properly ferment at any temperature in the Standard Fermentation range indicated on the Fermentation Temperature Decal.



IF YOU PREFER FASTER FERMENTATION FOLLOW THESE SIMPLE STEPS

**YOU NEED YOUR
BEER QUICKLY?**

WHO DOESN'T?

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

**FERMENT
YOUR BEER**

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE


SOUS VIDE

GLOSSARY

4 Locate the Metal Keg Lid and remove the **GRAY** Pressure Release Valve from the lid by unscrewing it counter clockwise.

Locate the **RED** Fast Fermentation adapter (it looks like the gray one you just removed) and screw it clockwise all the way into the pressure release hole of the Metal Keg Lid.

LOCKING CLAMP






5

Insert the Metal Keg Lid into the Brewing Keg, confirm it is seated correctly and push down on the locking clamp.

- 6** Carefully place your Brewing Keg in a temperature-controlled area where it will remain at the “Fast Fermentation” range indicated on the Temperature Decal on the Brewing Keg. It is normal for the Fast Fermentation Adapter in the lid to occasionally release CO₂ as it builds up in the keg due to fermentation. This occasional release may result in some bubbling of krausen, which is the slightly sticky fermentation foam, onto the Metal Keg Lid. If any krausen bubbles out just wipe it off with a damp paper towel.



7 Read the temperature indicated by your Fermentation Temperature Decal on the side of the Brewing Keg and consult the tables below to see how long Fast Fermentation should take to complete for your beer recipe.

BEERS:

Half Squeezed, Tweaties, Annie's London Pale, Pico Pale

KEG TEMPERATURE (F)	DAYS TO FAST FERMENT
75-84	4
70-74	4-5
65-69	5-6

BEERS:

All Others

KEG TEMPERATURE (F)	DAYS TO FAST FERMENT
75-84	5
70-74	5-6
65-69	6-7


Note: The day before you rack your beer to the Serving Keg, move your Brewing Keg into your refrigerator. This will cold crash the yeast and will also help in racking the beer.

IF STANDARD FERMENTATION IS MORE YOUR THING USE THE FOLLOWING STEPS.

THE CHILL OUT ROUTE.

8


Insert the Keg Seal into the top of the Brewing Keg.
Insert the Airlock into the Keg Seal center hole.



WILL'S PRO TIP:




Don't force the Airlock too far into the Keg Seal. Insert the Airlock up to 1/2 an inch or until it fits tightly.



9

Fill your Airlock with sterile water (or vodka) to fill line. The Airlock keeps the Brewing Keg properly sealed against any wild yeast or bacteria, while still allowing CO₂ to release as the beer ferments.



UNBOXING

SETUP

FIRST
RINSELET'S
BREWAFTER
BREWINGFERMENT
YOUR BEERDRY
HOPPINGRACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

10

Place your Brewing Keg in a temperature-controlled area where it will remain at the "Standard Fermentation Range Temperature" indicated on the Temperature Decal on the Brewing Keg. Fermentation can take anywhere from a week to several weeks depending on the beer recipe.

11

As your beer ferments, CO₂ is released through the Airlock. The bubbling will be vigorous the first couple of days of fermentation then slow down. When the bubbling slows significantly or completely stops that is when fermentation has neared completion, (on average 10 days.)

KEVIN'S PRO TIP:

The day before you rack your beer to the Serving Keg, move your Brewing Keg into your refrigerator. This will cold crash the yeast and will also help in racking the beer.

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

DRY HOPPING

**ESTIMATED TIME:
1 MINUTE**

**THIS STEP IS OPTIONAL.
CERTAIN BEERS WILL COME
WITH A DRY HOP SACHET.
YOU WILL NEED:**


- Your keg of fermenting beer
- Dry Hop Sachet

12

If your PicoPak contains a Dry Hop Sachet (packaged inside the same box with the Yeast Packet) there is an extra step in order to dry hop your beer to add maximum hop flavor and aroma. Store the Dry Hop Sachet packet in your refrigerator while your beer ferments for 3 days.

13

After 3 days of fermentation, remove the Metal Keg Lid or Black Keg Seal from the Brewing Keg. Remove the Dry Hop Sachet from your refrigerator and open the clear vacuum-sealed bag, do NOT open the paper sachet bags. Place the paper Dry Hop Sachet bags into the Brewing Keg with your beer. The paper sachets are designed to work inside your Brewing Keg while preventing clogging during the racking process.



14

Replace and clamp the Metal Keg Lid or Black Keg Seal on to the Brewing Keg and confirm it is seated correctly on Brewing Keg.

Allow your beer to continue to ferment with the Dry Hops for a minimum of 4 more days, longer if fermentation is not yet complete.

**PROCEED TO NEXT SECTION:
RACK & CARBONATE YOUR BEER**

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

RACK & CARBONATE YOUR BEER

**ESTIMATED TIME:
15 MINUTES**

YOU WILL NEED:

- Your keg of completed fermented beer at room temperature or chilled
- 1.5 cups of 3% Hydrogen Peroxide (or other food grade sanitizer) and 1.5 cups of clean water
- Large Bowl
- Waste container
- Serving Keg
- Racking Tube
- Keg Wand
- Dispensing Bung Plug

FOR FORCED CARBONATION:

- Carbonation adapter
- CO₂ Regulator and Cartridge

FOR KEG CONDITIONING:

- Carbonation Sugar Packet
- Dispensing Bung

1

Remove the white plastic shipping plug from the center of the Serving Keg Bung Hole.

Sanitize the Serving Keg by pouring 1.5 cups of clean tap water and 1.5 cups of 3% hydrogen peroxide. Close the serving keg with the shipping plug. Shake the keg and let it sit for 10 minutes, dump the keg into a large bowl and set aside, then rinse the keg thoroughly with clean water.

Note: Star San is available on www.picobrew.com/BrewGear. Follow all manufacturer's instructions when using Star San. If you do not have Star San, you can alternatively use a hydrogen peroxide solution (1.5 cups of clean tap water and 1.5 cups of 3% hydrogen peroxide). Make sure to let your Serving Keg air dry after sanitizing with hydrogen peroxide. Using sanitizer solutions other than Star San may result in off flavors.

2

Attach a Keg Wand to the Racking Tube. Soak the Racking Tube and Keg Wand for 5 minutes in the large bowl of hydrogen peroxide you set aside earlier. Rinse the Racking Tube and attached Keg Wand with clean water.

PROCEED TO NEXT SECTION: RACK THE BEER

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

RACK & CARBONATE YOUR BEER

STEP 1: RACK THE BEER

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

**RACK &
CARBONATE**

SERVING


USAGE &
CARE

SOUS VIDE

GLOSSARY

- 3** Remove Brewing Keg from your refrigerator. From the Pico main menu select **Utilities** then select **Rack Beer** on the Pico display. This will provide step-by-step instructions on screen.

Press the Control Knob between each step.




4

Connect sanitized Keg Wand to the **GRAY** Ball Lock Connector.

Direct the **GRAY** Keg Wand to a waste container.
Press the Control Knob to clear the drain hose.

When liquid stops flowing into the waste container
press the Control Knob to stop the pump, this
should take no more than 1 minute.

Remove the Keg Wand from the Ball Lock
Connector.




5

Insert Metal Keg Lid onto Brewing Keg, if not already on. Do NOT use black Keg Seal for the racking process.


Connect the GRAY Ball Lock Connector to the Brewing Keg IN post, this will allow the Pico to pressurize the Brewing Keg with air.

Connect the Racking Tube's Ball Lock Connector to the Brewing Keg OUT post.



6

Direct the Racking Tube to the waste container and press the Control Knob. The initial beer coming from the Racking Tube may contain trub (sediment). When no more trub flows into the waste container press the Control Knob to stop the drain, this should take no more than 30 seconds if needed at all, this is only to clear out any trub.



UNBOXING

SETUP

FIRST
RINSELET'S
BREWAFTER
BREWINGFERMENT
YOUR BEERDRY
HOPPINGRACK &
CARBONATE

SERVING

USAGE &
CARE


SOUS VIDE

GLOSSARY

7

Insert the Racking Tube in the Serving Keg Bung Hole and press the Control Knob, this will begin to transfer beer from the Brewing Keg to the Serving Keg. While the chilled beer in the Brewing Keg transfers into the room temperature Serving Keg you will begin to see condensation on the outside of Serving Keg. This will help you see the liquid level inside the keg.

Do not leave this unattended. You will fill to just under 1" from top of Serving Keg.




8

When air begins to enter the Racking Tube, or if the Serving Keg fills to within 1" of the top,* remove the black Ball Lock Connector from the keg and then press the Control Knob to turn off the pump and stop the process.

Once racking is complete it is safe to remove Racking Tube from Serving Keg.

***DO NOT OVER FILL**



RACK & CARBONATE YOUR BEER

STEP 2: FORCE CARBONATE THE BEER

***SKIP TO PAGE 101, STEPS 14-16
IF KEG CONDITIONING.**

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

**RACK &
CARBONATE**

SERVING


USAGE &
CARE

SOUS VIDE

GLOSSARY

9


Remove the white plastic shipping plug from the center of the Carbonation Adapter. Wipe down rim of Serving Keg opening, then press the Carbonation Adapter into the Bung Hole of the Serving Keg until it pops into place.



10

Turn the CO₂ Regulator **counter clockwise** all the way to close the Regulator.


Quickly screw a new CO₂ Cartridge into the Regulator. The Cartridge will pierce through metal and you'll hear a brief air noise, continue to turn Cartridge **clockwise** until you can no longer turn it.



11

Insert the barbed regulator connector into the Carbonation Adapter, it will be a snug fit.

Slowly dial the Regulator **clockwise** to open the Regulator until it reaches 24 PSI. This is the correct setting for most beers.



12

Place the Serving Keg with attached CO₂ Regulator into your refrigerator to chill and carbonate for approximately 36 hours.

Clean the Brewing Keg and Racking Tube, see Usage & Care section on page 114.




JIM'S PROTIP:



Cold is faster!


In case you didn't know cold liquid diffuses CO₂ quicker, so chill out.



13

After approximately 36 hours, slowly dial the regulator counter-clockwise to close it and release the pressure. Then carefully remove the CO₂ Regulator and Carbonation Adapter from the Serving Keg Bung Hole. Insert the Dispensing Bung Plug into the Serving Keg Bung Hole. Dispose of the used CO₂ cartridge properly. Keep the Carbonation Adapter Bung and Regulator for future brewing sessions.


Note: If keg was overfilled during the racking process you may see some leakage from the regulator.



14

You can also keep the regulator and cartridge attached to the Serving Keg for longer term storage. To do so, after the initial 36-hour carbonation period adjust the dial on the regulator from 24 psi to 10-12 psi and maintain at that pressure. Dial the regulator back to release excess CO2 before serving then dial it back up to 10-12 psi. This storage method may require more than one CO2 cartridge.

Note: It is normal after a few hours in the refrigerator for the pressure displayed on the gauge to drop from 24 psi to about 12 psi.



RACK & CARBONATE YOUR BEER

STEP 3: KEG CONDITION THE BEER (NATURAL CARBONATION)

***SKIP TO PAGE 93, STEPS 9-13
IF FORCE CARBONATING**

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

**RACK &
CARBONATE**

SERVING


USAGE &
CARE

SOUS VIDE

GLOSSARY


14

After Racking is complete pour all contents from the Carbonation Sugar packet into the Serving Keg with your beer.



15

Press the Dispensing Keg Bung Plug into the Serving Keg Bung Hole. Swirl the keg so the Carbonation Sugar and beer are well mixed.



16

Set the Serving Keg aside to carbonate in the same area that you fermented the beer.

Note: The amount of time it takes to carbonate should be about twice the amount of time it took for original fermentation. This is based on the carbonation being done at the same temperature as the original fermentation.

Once carbonated, chill for a minimum of 12 hours to allow the carbonation to fully diffuse into the beer.

**PROCEED TO NEXT SECTION:
SERVE YOUR BEER**

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

BOTTLE YOUR BEER

YOU WILL NEED:


- Your keg of fermented beer
- Bucket
- 1 Liter bottles (x5)
- Carbonation Drops
- Bottling Tube
- Food grade sanitizer prepared according to manufacturer's instructions (Star San is recommended)

*Bottling accessories sold separately on


www.picobrew.com/BrewGear

1

Pour $\frac{1}{4}$ cup of sanitizer solution in each bottle and close the cap. Shake the bottle and let it sit for five minutes. Empty the contents in the bottle in the bucket. Check the bottle for any debris that could contaminate your beer.



- 2** Attach the Keg Wand to the ball lock fitting on the Bottling Tube. Pour sanitizer solution into the Bottling Tube and press down on the clean bucket to allow sanitizer to flow through.




3

Place carbonation drops into each bottle. Refer to instructions on packaging to determine how many drops are needed per bottle.


Note: If using Coopers carbonation drops, 3 drops per 1 liter bottle is recommended for most beers.




- 4** Remove the Brew Keg from your refrigerator. From the Pico main menu select Utilities then select **Rack Beer**. This will provide step-by-step instructions on screen. Press the Control Knob between each step.




- 5** Follow RACK THE BEER instructions in the manual, attaching your Bottling Tube instead of the Racking Tube to the OUT post on the Brew Keg



- 6** Direct the Bottling Tube to the bottom of the sanitized bucket and press down. Press the Control Knob. The initial beer coming from the Bottling Tube may contain trub (sediment). When no more trub flows in to the waste container press the Control Knob to stop the drain, this should take no more than 30 seconds.



7 Insert the Bottling Tube into the bottle, place it all the way to the bottom and press to transfer the beer. Fill all the way to the top of the bottle, when the Bottling Tube is removed you will have the correct amount of headspace. Repeat this process until the Brew Keg is empty and air begins to enter the Bottling Tube. Then press the Control Knob to turn off the pump and stop the process, and remove the Bottling Tube from the keg.



8

Seal the bottles and rinse off any beer that may have overflowed. Store the bottles in room temperature for 10-14 days. Once carbonated, chill for a minimum of 12 hours before serving.

Note: If your beer seems under-carbonated after 10-14 days, move the remaining bottles to a warmer area and continue to carbonate for a few more days.

UNBOXING
SETUP
FIRST RINSE
LET'S BREW
AFTER BREWING
FERMENT YOUR BEER
DRY HOPPING
RACK & CARBONATE
SERVING
USAGE & CARE
SOUS VIDE
GLOSSARY

SERVE YOUR BEER

**ESTIMATED TIME:
1 MINUTE**

YOU WILL NEED:

- Your keg of cold, carbonated, delicious beer
- Keg Label
- Glassware

1


Stick your Keg Label on to the Serving Keg. Lift the red tab on the Dispensing Bung and turn it a quarter turn **counter-clockwise** to the "1" position, this will open the vent for serving and release the carbonation pressure inside

Firmly pull the spout of the Serving Keg outward.



2

Twist the Serving Keg Spout **counter clockwise** to dispense beer from the keg. Twist Serving Keg Spout **clockwise** to stop dispensing beer.



UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

3

When finished serving the beer, close the Dispensing Bung vent by turning it **clockwise** to the "0" position and push the spout back into the keg. Refrigerate the Serving Keg when not serving from it.



WELCOME TO THE HOMEBREW FAMILY

WE'RE A REALLY
FUN CROWD.

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

**LET'S
STOP
FOR A
LITTLE
REFLECTION.**

**YOUR
FIRST
OF
MANY
BEERS.**

**THE FLOOD
GATES ARE NOW
OPEN FOR MORE
DELICIOUS
HOMEBREW
GOODNESS.**



CHEERS

USAGE & CARE

**ESTIMATED TIME:
20 MINUTES**

RECOMMENDED OCCURRENCE:

Should be performed after every brewing session, completed fermentation, or when keg is empty.

- Remove Step Filter from Pico. Wipe down any condensation that has formed inside Pico where Step Filter usually sits.
- Wipe down the inside of the Water Reservoir.
- Clean out the Inline Filter.
- Inspect gaskets on Inline Filter, ball locks, Brewing Keg posts.
- Tighten Inline Filter, ball locks, keg posts.

KEG CLEANING:

KEGS SHOULD BE CLEANED EVERY TIME THEY ARE DONE BEING USED, AFTER FERMENTING OR WHEN KEG IS EMPTIED.

YOU WILL NEED:

- 17mm wrench
- Brewing Keg
- Serving Keg
- All accessories used during brewing, fermentation, or serving (Metal Keg Lid, Black Keg Seal, Fast Fermentation Adapter, Pressure Relief Valve, Airlock, etc.)
- Keg Brush and Dip Tube Brush
- Large-sized container
- Fragrance-free powdered dishwasher detergent, or other homebrewing cleaning agent
- Racking Tube
- Keg Wands

LET'S START THIS ADVENTURE WITH OUR BREWING KEG.

LINDSEY'S PRO TIP:

After a keg has kicked give the keg a quick rinse with hot water, put the lid on and give it a good shake. This will make clean up easier if you can't get to cleaning the keg right away. Never leave old beer in the keg to clean later!

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE


SERVING

USAGE &
CARE

SOUS VIDE


GLOSSARY

- 1** Fill a large container with $\frac{1}{4}$ teaspoon fragrance-free powdered dishwasher detergent and enough hot tap water to almost fill container.



2

Place all accessories used during brewing or fermentation in to the container to soak. Use Keg Brush to clean all items inside container, making sure to scrub any surface that may have had any contact with beer.



UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE


GLOSSARY

STOP! BEFORE GOING FURTHER REMOVE YOUR BREWING KEG POSTS:

We recommend removing one post at a time so that there is less confusion and chance of putting the IN on the OUT post or vice versa when reassembling. There are subtle notches on the outside edges of the IN Keg Post Ball Lock in case you want to remove both posts at one time.


3

Use a 17mm wrench to remove Keg Posts.




4


CAREFUL! There is a metal spring and valve inside both the IN and OUT post Ball Locks, this is called the Poppet Valve. It may jump out as soon as the IN or OUT posts are taken off. Make sure you are standing over a contained area, not a sink with an open disposal or drain, nor a patterned carpet.



- 5** The IN post is connected to a short tube. Remove the black O-ring attached to this tube.




- 6** The OUT post is connected to a long Dip Tube that reaches the bottom of the keg. Remove the black O-ring attached to this tube.




7

Use the Dip Tube Brush to clean the inside of Keg IN/OUT Posts thoroughly. Place all parts but the Dip Tube in to container and let soak.




8

Inside the Brewing Keg mix $\frac{1}{2}$ teaspoon powdered dishwasher detergent with enough hot tap water to almost fill the keg. Place the Dip Tube in the Brewing Keg and let soak for 10 minutes, longer if there is hardened build-up.




9

Use the Keg Brush to scrub the inside of the Brewing Keg, making sure to get in contact with all internal walls and crevices of keg, and the outside of the keg making sure to get the top opening and any spot that had contact with beer. Use Dip Tube brush to clean the Dip Tube.




10

Rinse the Brewing Keg thoroughly with clean water.




11

Reassemble all O-rings to their original part locations. When reassembling the O-rings make sure to use either water or a food-grade lubricant to ease them back into place.



12

Make sure the IN/OUT keg posts are on the correct sides and are tightened down. Remember, the tube for the IN post is shorter than the Dip Tube for the OUT post. The Dip Tube is slightly angled and the end of it should almost touch the center of the bottom inside the Brewing Keg.



UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE


SOUS VIDE

GLOSSARY

SERVING KEG CLEANING:

13

Remove the Dispensing Bung Plug from the Serving Keg. Rotate vent piece to release pressure. Insert flat-head screwdriver between vent piece and rubber stopper. Twist and pry slightly with screwdriver to pop vent piece out.



UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING


USAGE &
CARE

SOUS VIDE

GLOSSARY


14

Use the screwdriver to punch the center red plastic piece down into the Serving Keg.



15

Use the screwdriver to pry out the rubber stopper. Be careful to not damage it or the Serving Keg.




16

Turn the Serving Keg upside down and shake it until the center red plastic piece falls out of the opening. Re-assemble the Dispensing Bung Plug. The plastic pieces are molded so that they fit into each other.



17

Inside the Serving Keg mix $\frac{1}{2}$ teaspoon powdered dish washing detergent with enough hot tap water to almost fill the keg. Let it soak for 10 minutes, longer if there is hardened build-up.



UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING


USAGE &
CARE

SOUS VIDE

GLOSSARY


18

Use the Keg Brush to scrub the inside of the Serving Keg, making sure to get in contact with all internal walls and crevices of keg, and the outside of the keg making sure to get the top opening and any spot that had contact with beer. Scrub Dispensing Plug and rinse with clean water.



19

Place Serving Keg over a waste container or sink. Pull the spout of Serving Keg outward. Twist the spout counter clockwise to start dispensing the cleaning agent water from keg and through the spout. Let flow into sink or waste container for approximately 10 seconds. Turn spout clockwise to stop dispensing water.



UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

20

Dump all water inside Serving Keg, give a quick rinse with clean water. Turn spout counter-clockwise to allow clean water to flow out for about 5 seconds. Turn clockwise to stop, then push spout back into keg. Dump all of the water out of the serving keg. Let air-dry upside down until dry.

**REMEBER:
NEVER
USE
ANY
CLEANING
AGENT
INSIDE
THE
PICO
UNIT.**

**POWDERED DETERGENTS
OR DRY PACKS SHOULD
ALWAYS BE USED
IN CONTAINERS
SEPARATE FROM
THE PICO, LIKE A BUCKET
OR BREWING KEG.**

PICO DEEP CLEAN

**ESTIMATED TIME:
HANDS ON 10 MINUTES
(TOTAL TIME: 45 MINUTES)**

RECOMMENDED OCCURRENCE:

Should be performed every 3 brew sessions.

YOU WILL NEED:


- 1 gallon of clean tap water
- 0.5 gallon of distilled water (or reverse osmosis)
- Brewing Keg (if in use you can use a clean container. See Note below.)
- Keg Cozy
- Keg Wands
- 1 solid dishwashing cleaning tablet (do NOT use liquid or gel pouches or any common homebrew cleaning agents)

DEEP CLEAN CYCLE:

1

Pour 1 gallon of clean tap water into the Brewing Keg. Slide the Keg Cozy over the Brewing Keg. Drop the solid cleaning tablet into the Brewing Keg. You can leave the lid or seal off during the Deep Clean cycle.

Note: The cleaning tablet should ONLY go in the Brewing Keg. Never put it or any other cleaning agent inside the Water Reservoir.



UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING


USAGE &
CARE

SOUS VIDE

GLOSSARY


2

Connect the BLACK Ball Lock Connector to the OUT post on the Brewing Keg. Repeat procedure with the GRAY Ball Lock Connector to the IN post.



3

Insert the Step Filter with lid into Pico. Turn Pico on. Click Utilities and select DEEP CLEAN.



UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE


SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

- 4** Pour 0.5 gallon of distilled water into the Water Reservoir.



5


Once the Deep Clean cycle begins it will take roughly 35 minutes to complete.

Note: The Brewing Keg will be very HOT after cleaning so please proceed with caution and only touch the keg's black rubber handles.

RINSE CYCLE:

6

Once Deep Clean cycle finishes, carefully dump all liquid from both the Step Filter and the Brewing Keg. Liquid will be HOT so use caution! Rinse thoroughly with clean water. Fill the Step Filter with approximately 1 inch of clean tap water, then insert the Step Filter with lid back into Pico until it clicks into place.

**TAP WATER**

UNBOXING

SETUP

FIRST
RINSELET'S
BREWAFTER
BREWINGFERMENT
YOUR BEERDRY
HOPPINGRACK &
CARBONATE

SERVING


USAGE &
CARE

SOUS VIDE

GLOSSARY


7

For each Ball Lock Connector, pull up on the outer ring of the Connector and insert a Keg Wand, release the ring and make sure it is properly connected to the Keg Wand.




8

Direct the end of the GRAY Ball Lock Connector ("IN") Keg Wand into a waste water container.




BILL'S PRO TIP:

Make sure you use a big enough waste water container! The gallon water jug you used to fill the machine is perfect for this use.




9

Press Control Knob to start Rinse Cycle and run the pump to clear the drain line.




10

Remove the Water Reservoir lid. Insert the end of the BLACK Ball Lock Connector ("OUT") Keg Wand into the Water Reservoir. Run the pump until the Reservoir is drained. When the Reservoir is empty stop the pump by pressing the Control Knob.




11

Press the power button on the Pico to turn it off.



12

Unscrew and remove the Inline Filter cap. Remove the blue Inline Filter cylinder and rinse it thoroughly using tap water. Put the cleaned cylinder back into the Inline Filter and screw the Filter cap back on, finger tight.



13

Remove the Keg Wands from the Ball Lock Connectors by pulling up on the outer plastic rings. Remove the Step Filter and lid from the Pico and rinse thoroughly with tap water.

Note: If your Brewing Keg is already being used, use a clean container that can hold up to 1.5 gallons and can withstand temperatures up to 135°F. The container and liquid will be hot, so please exercise caution while handling. You will need both Keg Wands, which will need to be attached to the BLACK and GRAY Ball Lock Connector hoses and directed into the container. The Keg Wand attached to the BLACK Ball Lock Connector will suction water out of the container, so make sure the end is submerged enough to suction water. The Keg Wand attached to the GRAY Ball Lock Connector will recirculate water into the container, so make sure its end is directed inside the container.

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

STEP BY STEP:

- 1.** Pour 14 ounces of Descaling Liquid into the Water Reservoir. Fill the rest of the Water Reservoir with clean tap water (approximately 1 gallon).
- 2.** Insert the Step Filter with lid into the Pico. Turn Pico on. Click Utilities and select RUN DESCALER.
- 3.** Once the descaling cycle begins, it will take roughly 30 minutes to complete. When the Water Reservoir is empty press the Control Knob to end the cycle.
- 4.** Once the descaling cycle finishes, carefully empty all liquid from the Step Filter. Fill the Water Reservoir with 1 gallon of clean tap water. Insert the Step Filter with lid back into the Pico until it clicks into place. Press the Control Knob to continue. When the Water Reservoir is empty (after approximately 30 minutes) press the Control Knob to end the cycle.
- 5.** Run a Deep Clean on your Pico by following the Deep Clean instructions in the manual.

PICO DESCALE

ESTIMATED TIME:
HANDS ON: 10 MINUTES
(TOTAL TIME: 1 HOUR)

RECOMMENDED OCCURRENCE:


Should be performed after every 20 brews if you are not using distilled or reverse osmosis water in the Water Reservoir.

YOU WILL NEED:

- 14 oz. Descaling Liquid (Available on www.picobrew.com/BrewGear)
- 2 gallons of clean tap water

SAMPLE RECIPES:

			RARE	MED	WELL
	SIZE	TIME	TEMP	TEMP	TEMP
STEAK	1" Thick	1:00	129	136	154
	1.5" Thick	1:30	129	136	154
	2" Thick	2:00	129	136	154
PORK CHOP	1" Thick	1:30	136	143	158
BONELESS CHICKEN BREAST	0.5 lb	1:30	140	150	165
SALMON	1" Thick	0:40	105	123	131
	1-2" Thick	1:00	105	123	131
		TIME	SOFT	MED	HARD
EGGS	(4)	0:20	167		
		0:25		168	
		0:40			168

RECOMMENDED: 

All temperatures are listed in degrees Fahrenheit.

SOUS VIDE ADAPTER INSTRUCTIONS.


YOU WILL NEED:

- Pico, with Step Filter and its lid
- Brewing Keg
- Keg Cozy
- Sous Vide Adapter
- 1 gallon of Distilled Water
- Tap water
- 1 gallon heavy duty Ziploc® bag or a food vacuum sealer system
- Food to cook
- 5 quarts of tap water

1


Fill the Brewing Keg with 5 quarts of warm tap water.

Note: 5 Quarts = 1.25 Gallons = One Gallon + 4 Cups =
20 Cups = 10.5lbs Water = 4.75 Liters



2

Place the black Keg Seal on the top of the Brew Keg opening, push in the center until it pops into place. Make sure the hole in the center of the Keg Seal is open. Pull the Keg Cozy over the Brewing Keg. Attach the BLACK Ball Lock Connector hose connector to the Brewing Keg post marked "OUT". Repeat the procedure with the GRAY Ball Lock Connector hose (capitalize) on the brew keg post marked "IN".



UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING


USAGE &
CARE

SOUS VIDE

GLOSSARY

3


Turn the Pico on. Using the Control Knob scroll to **Sous Vide** and press Control Knob to select.



4


Consult the Sous Vide Recipe Table on page 156 for the food you are cooking.

Set the desired water temperature for cooking by turning the Control Knob to scroll to the correct temperature and pressing the Control Knob to select and continue to the next step.




5

Enter the cooking time of your recipe in **Hours:Minutes** format by turning the Control Knob to scroll to the correct hour or minute and pressing the Control Knob to select and continue to the next step.



6


Insert the empty Step Filter and lid into the Pico, press Control Knob to continue to the next step.



7

Make sure your keg is properly connected and filled with 5 quarts of water, press the Control Knob to continue to the next step.

Open the Water Reservoir lid on top of the Pico and fill the reservoir with 1 gallon of distilled (or RO) water. Press the Control Knob to begin heating up the water to the designated cooking temperature. For sous vide recipes or cooking sessions that go over 3.5 hours you might need to add more distilled water to the reservoir during the cooking process, check on it as needed.



8

Begin preparing your food:

Trim and prepare food for cooking. Thicker cuts of meat or vegetables may require longer cooking time. Add any spices or aromatic to the food before sealing the bag(s).

Vacuum seal the food or insert into a 1 gallon heavy duty freezer Ziploc® bag with the air squeezed out and fully sealed.

LINDSEY'S PRO TIP:

To get most of the air out of a Ziploc bag seal the bag but leave about 1" of bag unsealed. Submerge Ziploc® bag of food in water and as the bag submerges the water pressure will squeeze the air out for you. Right before the bag is fully submerged seal up that last 1" of the bag and pull out of water. The bag should be mostly air-tight and ready to sous vide.

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING


USAGE &
CARE

SOUS VIDE

GLOSSARY

9

When the water has reached cooking temperature the Pico will beep. Press the Control Knob to silence the alarm. Remove the Step Filter and its lid from Pico. Place the Sous Vide Adapter in the back section of the Step Filter so the hole on the backside of the Adapter covers up the drain hole in the back of the Step Filter. The tapered front of the Adapter should be facing the front of the Step Filter. Press down so the Adapter is firmly in place. See below diagram.




10

Place food bag(s) in Step Filter. If using a Ziploc® bag, place bag(s) against the side of the Step Filter with the top hanging out over the edge of Step Filter. Once you place the Step Filter lid on it will clamp the bag(s) into place. Vacuum sealed bags should sink to bottom. If necessary, place a food-safe object on top of bag(s) to make sure they will stay fully submerged in the water during the entire cooking process.

Place lid on Step Filter, clamping any Ziploc® bags in place. Make sure the lid holes are in the correct places (see diagram) and that the black steam deflector is towards the front and facing upward.

Insert Step Filter with lid into Pico.



11

Select "Start Cooking" on-screen by pressing the Control Knob. This will begin the sous vide cooking process using the time and temperature you selected. You will be able to view the temperature and remaining cooking time on the Pico screen. If at any time you need to pause the cooking process turn the Control Knob to reveal the "Pause System" option and press Control Knob to select and pause cooking. When ready to resume cooking make sure the Step Filter is inserted correctly then select "Continue Cooking" on-screen using the Control Knob.

When Pico is finished cooking the screen will say "Finished" and an alarm will sound for 60 seconds. You can turn the alarm off by pressing the Control Knob.

If you plan on searing any food after cooking make sure to prepare the pan or grill a few minutes before the Pico is finished cooking your food. A simple way to sear meat is to use a heavy pan on your stovetop. Heat the pan on high until hot, add butter/oil and then sear the meat 1-2 minutes per side until the desired sear is achieved.

When the sous vide process is finished:

- You can select "Drain" option on-screen and this will drain water from Step Filter to Brewing Keg, this step makes it easier to get the Step Filter out without spilling water. Use tongs to take food out of Step Filter.
- Or, select "Exit" on-screen and carefully remove Step Filter from Pico, be cautious as the water inside will be warm. Use tongs to take food out of Step Filter.
- Cut open vacuum-sealed bag(s) or open Ziploc® bag(s). Dispose of bag(s).
- Season food to preference. Sear on hot pan or grill (optional).

Note: If you do not exit after the cooking is finished Pico will automatically hold the cooking temperature. Any food still in the Pico will continue to cook.


12

Disconnect both Ball Lock Connector hoses from Brewing Keg. Dispose of water in both Step Filter and Brewing Keg.

If you plan on doing another sous vide session right away you can reuse the distilled water in the Water Reservoir, check to see if you need to add more. If you are not going to do another sous vide session insert an empty Step Filter back into the Pico. Detach the BLACK Ball Lock Connector hose from the Brewing Keg. Attach a clean Keg Wand to the BLACK Ball Lock Connector and direct the wand into the Water Reservoir. Select "Start Vacuum" to begin suctioning out the remaining water and press the Control Knob to stop the vacuum when there is no more water in the reservoir. Press the power button to turn Pico off.

Unscrew and remove the Inline Filter cap attached to the BLACK Ball Lock Connector hose. Remove the blue filter insert and rinse it thoroughly using tap water. Place it back in the Inline Filter and screw the filter cap back on, finger tight.

Thoroughly clean and rinse the Step Filter, lid, Brewing Keg, and black Keg Seal.



Consuming raw or undercooked meats, poultry, seafood, shellfish or eggs may increase your risk of foodborne illness.

MANUAL GLOSSARY

**EVERYTHING
YOU NEED TO
IMPRESS
YOUR FRIENDS
AND BREW
CORRECTLY.**

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

ADJUNCT A fermentable addition to the mash that includes sugars, syrups, and unmalted cereal grains such as corn, rice, oats that provide extra sugars in the wort.

AERATE Introducing oxygen into the wort to make sure yeast can reproduce abundantly.

ALE A generic term used for beers that are created using a top-fermenting yeast strain at a higher temperature than lager yeast strains.

BACTERIA Single-celled organisms that reproduce quickly in specific environments. Integral to specific beer styles, particularly sours, and considered an off-flavor and flaw in the majority of all other beer styles.

BUNG A plug inserted into the Bung Hole at the top of a cask or keg.

CARBONATION Carbon dioxide (CO₂) is a naturally occurring by-product of fermentation. Keg Conditioning is natural carbonation created during fermentation when yeast metabolize sugars. Forced carbonation is the addition of CO₂ to the final beer.

DOUGH IN Part of the mash process where grains soak to activate and distribute temperature-specific enzymes.

DRY HOP The addition of hops after initial fermentation to increase hop aroma without increasing hop bitterness.

ESTERS Aromatic flavor compound created by yeast during fermentation. Esters contribute fruity aromas to beers.

FERMENTATION The process where yeast break down sugars into carbon dioxide (CO₂) and alcohol.

HOPS Hops are the flower cones of a the hop plant, used to contribute bitterness, aroma, and anti-microbial qualities to beer. Commercially available in pellet, plugs, whole cone, or extracted forms.

KRAUSEN Thick, moussy foam on the top of fermenting wort that occurs during the beginning of fermentation.

LAGER A generic term used for beers that are created using a bottom-fermenting yeast strain at a lower temperature than ale yeast strains. Also a term for cold-storing a beer for an extended amount of time.

MALT Barley, or other grains, used during the mash and brewing process. Contributes a wide range of flavors from uncooked bread to roasted coffee, depending on its kiln or roasted level.

UNBOXING

SETUP

FIRST
RINSE

LET'S
BREW

AFTER
BREWING

FERMENT
YOUR BEER

DRY
HOPPING

RACK &
CARBONATE

SERVING

USAGE &
CARE

SOUS VIDE

GLOSSARY

MASH	The process of steeping milled grains in hot water in order to activate enzymes and extract sugars from the malt.
PHENOLS	Chemical compounds derived from yeast activity during fermentation. Vary from spicy, peppery, smoky, medicinal, and many more.
PITCH	The process of adding yeast to cooled wort to start fermentation.
PRIMING	The act of adding a small amount of sugar to fermented beer in order to restart fermentation and create carbonation inside bottle or keg.
PSI	Pounds per square inch.
TRUB	A solid material composed of yeast, proteins, and hop particles that fall out of solution during brewing and fermentation
WILD YEAST	Yeast that is naturally airborne and ubiquitous. Typically used in sours or wild ales, considered an off-flavor in a majority of other beer styles.

WORT Unfermented liquid containing sugars extracted from the malt grain during the mash process. Adding yeast to wort starts the fermentation process which transforms the wort into beer.

YEAST Single-celled fungus that breaks down sugars in the wort during fermentation into carbon dioxide, alcohol, and creates various phenols or esters.

IMPERIAL AND METRIC CONVERSION TABLE

IMPERIAL	METRIC
0.5 gallon	1.9 liters
1 gallon	3.8 liters
2.5 gallons	9.5 liters
3 gallons	11.4 liters
75-84 F	23.9-28.9 C
70-74 F	21.2-23.3 C
65-69 F	18.3-20.6 C

**WE
HIGHLY
SUGGEST
USING THE
FOLLOWING
PAGES TO
DOCUMENT
YOUR
BREWING
JOURNEY.**

**SCRIBBLE,
DOODLE,
RECORD.
IT'S UP
TO YOU.**

This image shows a single page from a spiral-bound notebook. The page is white and features horizontal ruling lines spaced evenly down its length. On the left side, there is a grey spiral binding. At the top of the page, the words "BREWING NOTES" are printed in a bold, black, sans-serif font. The rest of the page is blank, with no handwriting or other markings.

BREWING NOTES

[illegible]

This image shows a single page from a spiral-bound notebook. The page is white and features horizontal ruling lines spaced evenly down its length. On the left side, there is a grey spiral binding. At the top of the page, the words "BREWING NOTES" are printed in a bold, black, sans-serif font. The rest of the page is blank, with no handwriting or other markings.

BREWING NOTES


[illegible]

This image shows a single page from a spiral-bound notebook. The page is white with horizontal ruling lines. On the left side, the spiral binding is visible, consisting of a series of dark grey or black rings. The title "BREWING NOTES" is printed in a bold, sans-serif font in the upper left corner of the page. The rest of the page is blank, with the ruling lines extending across its width. The lighting is even, and the page appears to be part of a larger bound volume.

17-0126

© PicoBrew Inc, 2016

www.PicoBrew.com



PICO INSTRUCTION MANUAL

