```
% HW05
% Q. 3
% ------ clear all ------
close all;
clear all;
clc;
% ----- (a) -----
B = [1];
             % numerator
A = [1. -0.9]; % denominator
f=figure(1);
zplane(B,A)
grid on
saveas(f, 'hw06_3a.eps', 'epsc');
% ----- (b) -----
N= 1000; % num points to calculate
points = freqz(B,A,N);
mag = abs(points);
phase = angle(points);
f = figure(2);
subplot(2,1,1)
plot(mag, 'linewidth',2)
grid on
title("(a)", 'Units', 'normalized', 'Position', [0.5, -0.35, 0])
xlim([1,N])
ylim([0, max(mag)]+0.5)
xlabel("Points")
ylabel("Mag. Resp.")
subplot(2,1,2)
plot(phase, 'linewidth',2)
grid on
title("(b)", 'Units', 'normalized', 'Position', [0.5, -0.35, 0])
xlim([1,N])
ylim([-pi, pi])
xlabel("Points")
ylabel("Phase Resp.")
saveas(f, 'hw06_3b.eps', 'epsc');
```



