LOR Seq. Line of Route Description			ELR	Route	Last Updated
GW710 002 Llanwern Works East to Llanwern Works West Via Steelworks Service Lines				Western 05/08/06	
Location Mileage M Ch Running lines & speed restrictions			Signalling & Remarks		
		DS 15 Coal Yard Sidings  15 UP SERVICE LINE ① (PF)		TCB Newpo	ort SB (N)
Not	for	To To Coal Discharge Bunker		alt	JSE
				① Corus lines under the d EWS Chargeman	control of
Llanwern West GF					
Llanwern Works West Connection	156 03	To/From Severn Tunnel Jn GW900 seq 003  To/From Newport GW900 seq 003			