LOR Seq. Line of Route Description LN101 018 Kings Cross to Shaftholme Jn			ELR ECM1		oute	Last Updated 12/08/08
Location	Milana		ECIVIT	Signalling & Remarks		
Tallington LC (CCTV)	84 64	US UF DF DS 125 80 40 40		TCB RA9	Peterborough S AC:York	B (P) 023
Tallington Crossovers	84 _{to} 70 85 ^{to} 02	40				
Greatford LC (CCTV)	87 08					
Not	for	operation	on	al	U	se
	91 42 *	80 *				
	92 12 *	1 75 *				
Bytham F.S. OHNS	92 29	80 125 🔻				