LOR Seq. Line of Route Description			ELR	Route	Last Updated
EA1390 001 Barking Tilbur	Barking Tilbury Line Jn East to Pitsea Jn (via Tilbury)			Anglia	27/11/06
Location  Mileage M Ch  To Barking EA1380 seq 5  U D  15		Running lines & speed restrictions		Signalling & Remarks	
		EA1380 seq 5 U D		TCB Upminster II RA8 AC:	ECC (UR) Romford 020 06
Barking Tilbury Line Jn East	7 60	50 MU 60 EA1380 seq 5			CSF 03
OHNS	7 79	单 单	_		
Not	8 40	LP GOOD 20 DOWN	ion	AWS not provided on Up G UR804 signal	oods line at
	9 16 *	DOWN TILBURY  Ripple		AWS not Provided on Down UR807 signal	n Goods line after
Renwick Road Jn	9 31	J <sub>20</sub> // Eli Stora S	Sidings		
Freightliner Depot West End GF	9 50			Dn Goods - PF	
Stora Sidings GSP	9 54 *	- 설립설립 전 U. T		Exchange Sidings 1, 2 and Goods running lines	3 are
Ripple Lane East Jn (Up Tibury/Goods	*)				
		20 20 20 50 MU 20 60 W		BF-Barking Freightliner Ter	minal